

## Quality Monitoring Report



<b>QMR Id</b> QMR [REDACTED]	<b>Created By</b> tken	<b>Report Date</b> 07/21/2017	<b>Last Updated</b> 07/21/2017	<b>Reg-Zn-Dst</b> [REDACTED]	<b>Dealer</b> 090185
<b>Section</b> Electrical	<b>Sub Section</b> Air Bag				
<b>VIN</b> JF2SJAFC2GH [REDACTED]	<b>Engine #</b> --	<b>Trans #</b> --	<b>Mileage</b> 14993		
<b>Failure Code</b> [REDACTED]	<b>Failure Date</b> 06/23/2017	<b>Failed Part #</b> 64139SG002LL	<b>Technician Duplicated Condition?</b> N		
<b>R/O Number</b> [REDACTED]	<b>Rollover</b> N	<b>Fire</b> N	<b>Accident</b> N	<b>Injury</b> N	<b>Death</b> N
<b>Property Damage</b> N					
<b>DTC Code(s)</b> B1650					
<b>Reporter Name</b> [REDACTED]	<b>Reporter Email</b> --	<b>Reporter Phone Number</b> --			

**Customer's Description of Complaint**

CLIENT STATES THAT THE PASSENGER SEAT IS NOT REGISTERING PEOPLE SITTING IN THE SEAT PROPERLY.

**Technician's Findings and Repair**

TECHNICIAN FOUND THE PASSENGER SEAT BOTTOM TO BE THROWING AIRBAG CODES FOR P1650 OCCUPANT DETECTION MALFUNCTION. TECHNICIAN THEN FOLLOWED THE SUBARU PROCEDURES AND FOUND THE PASSENGER SEAT BOTTOM TO BE MALFUNCTIONING AT THIS TIME. TECHNICIAN THEN REPLACED THE PASSENGER SEAT BOTTOM. Part is being returned to pcc for additional inspection.

**Attachments**

No Attachments Found

<b>VIN Remainder</b> JF2SJAFC2GH [REDACTED]	<b>Warranty Start Date</b> 02/27/2016	<b>Production Date</b> 12/16/2015	<b>Car Line</b> Forester
<b>Original Engine #</b> [REDACTED]	<b>Trans. Type Desc</b> Continuously Variable Transmission	<b>Model Year</b> 2016	<b>Model Code</b> GFF
<b>Color</b> QBP	<b>Options</b> 14	<b>Emission Spec</b> C	<b>Turbo</b> N

**Engine Size**

**Original Trans #**

2.5

