

Quality Monitoring Report



QMR Id QMR [REDACTED]	Created By amat4366	Report Date 08/15/2017	Last Updated 08/15/2017	Reg-Zn-Dst [REDACTED]	Dealer 090798
---------------------------------	-------------------------------	----------------------------------	-----------------------------------	---------------------------------	-------------------------

Section Electrical	Sub Section Air Bag
------------------------------	-------------------------------

VIN JF2SJAGC7HH [REDACTED]	Engine # --	Trans # --	Mileage 6399
--------------------------------------	-----------------------	----------------------	------------------------

Failure Code [REDACTED]	Failure Date 08/04/2017	Failed Part # 64139SG060LL	Technician Duplicated Condition? Y
-----------------------------------	-----------------------------------	--------------------------------------	--

R/O Number [REDACTED]	Rollover N	Fire N	Accident N	Injury N	Death N	Property Damage N
---------------------------------	----------------------	------------------	----------------------	--------------------	-------------------	-----------------------------

DTC Code(s)
B1650

Reporter Name [REDACTED]	Reporter Email [REDACTED]	Reporter Phone Number --
------------------------------------	-------------------------------------	------------------------------------

Customer's Description of Complaint

Customer states air bag light is on

Technician's Findings and Repair

B1650 passenger side ODS module failure. Replaced passenger side seat bottom cushion. We have seen 5 of these in the past few weeks.

Attachments

No Attachments Found

VIN Remainder JF2SJAGC7HH [REDACTED]	Warranty Start Date 02/11/2017	Production Date 12/14/2016	Car Line Forester
Original Engine # [REDACTED]	Trans. Type Desc Continuously Variable Transmission	Model Year 2017	Model Code HFF
Color QBP	Options 15	Emission Spec C	Turbo N
Engine Size 2.5	Original Trans # [REDACTED]		