

Quality Monitoring Report



| | | | | | |
|--------------------------------------|-----------------------------------|----------------------------------|----------------------------------------------|---------------------------------|-----------------------------|
| QMR Id QMR [REDACTED] | Created By dzwa | Report Date 08/28/2017 | Last Updated 08/28/2017 | Reg-Zn-Dst [REDACTED] | Dealer 070128 |
| Section Electrical | Sub Section Air Bag | | | | |
| VIN JF2SJALC6HH [REDACTED] | Engine # -- | Trans # -- | Mileage 11665 | | |
| Failure Code [REDACTED] | Failure Date 07/20/2017 | Failed Part # -- | Technician Duplicated Condition? Y | | |
| R/O Number [REDACTED] | Rollover N | Fire N | Accident Injury N | Death N | Property Damage N |
| DTC Code(s) B1826, B1650 | | | | | |

| | | |
|------------------------------------|-------------------------------------|------------------------------------|
| Reporter Name [REDACTED] | Reporter Email [REDACTED] | Reporter Phone Number -- |
|------------------------------------|-------------------------------------|------------------------------------|

Customer's Description of Complaint

C/S airbag light is on.

Technician's Findings and Repair

Tech followed TT for DTC B1826. Tech found connector AB19 disconnected under driver seat. Tech reconnected the connector, cleared DTCs. All OK.

Attachments

No Attachments Found

| | | | |
|------------------------------------------------|---------------------------------------------------------------|--------------------------------------|-----------------------------|
| VIN Remainder JF2SJALC6HH [REDACTED] | Warranty Start Date 02/21/2017 | Production Date 12/28/2016 | Car Line Forester |
| Original Engine # [REDACTED] | Trans. Type Desc Continuously Variable Transmission | Model Year 2017 | Model Code HFI |
| Color CBS | Options 22 | Emission Spec C | Turbo N |
| Engine Size 2.5 | Original Trans # [REDACTED] | | |

