

Vehicle Information

VIN: [REDACTED] Model: 1EK69-2015 SS
 Service Contract: No Branded Title: No Warranty Block: No PDI Status: Yes
 Order Type: 70 - RETAIL - STOCK
 Field Actions: [0 Open](#) [REQUEST ANOTHER VIN](#)

Required Field Actions

Open Field Action Details are highlighted

Type	Number	Original Nbr	Description	Release Date	Status
Product Safety Recall	N192285350	N192285350	Loss of Steering Assist	09/23/2020	Closed
Product Safety Recall	2016007	16007	Frontal Airbag and Pretensioner Non Deploy	09/08/2016	Closed
Product Safety Recall	2031340	31340	Seat Belt Tensioner Cable	07/07/2016	Closed
Customer Satisfaction Program	2015803	15803	REAR AXLE WIRING HARNESS DAMAGED BY REAR DRIVESHAFT	04/28/2016	Closed

Job Card Date: 10/21/2016 Job Card Number: [REDACTED] [Transaction Detail](#)

Repair Service Agent: [REDACTED] Odometer Reading: 11,291 MI
 BURLINGTON CHEVROLET Authorization Code: PE
 105 EAST ROUTE 130 SOUTH
 BURLINGTON NJ 08016-2731

Process Date: 10/31/2016
 Transaction Type: ZREG---Regular Vehicle Transaction
 Transaction Expense Category: Warranty
 Customer Complaint Code: 0890-Interior - Other issues
 Job Card Line #: 6 Transaction Adjustment: Cause Code: 6011-Module/Component - Alignment/Adjustment

Labour Op 6440020-Front Seat Belt Buckle Replacement
 Causal Part Number 00000000019303299-BELT KIT,D/SEAT (BKL SI) *JET BLACK
 --See other Parts and/or Net Items Line Total: USD 403.20

Parts Return Status

Project ID: [REDACTED] Request Nbr: [REDACTED]

Complaint/Cause/Correction
 Complaint: 0890 - Interior - Other issues

customer sates left front seat and rights side belt is rubbing/getting chewed up-r/f seat l/s belt also

Cause: 6011 - Module/Component - Alignment/Adjustment

both bucklets on both side protective cover rubbed through/ripped

Correction:

replaced both sides belts and rechecked operation