

SS 3495 Cascadia Cab Leak Source Identification

Use the attached documents as a guide for determining where to look for the leak(s); also to test for leak sources.

Symptoms: Corrosion on connector terminals of SAM module(s), Water inside SAM module(s), Frontwall insulation saturated with moisture, Trails of white or brown residue indicating location of water entry, Water dripping onto dash and Audible "sloshing" coming from cab header, above windshield.

If this inspection and leak testing is performed in conjunction with the FL545 Recall, up to 0.5 hours of T-time may be included on the claim, using SRT code 996-0000T.

Solution ID: 3495