

SS 3498 Cascadia Roof Leaks

If a roof leak is detected, use the attached document as a guide for determining the proper repair procedure.

Refer to Service Solution 3495 for information about identifying potential leak locations.

If any of these repairs are completed in conjunction with the FL545 Recall, the required parts, and up to the below listed amount of T-time may be included on the claim, using SRT code 996-0000T.

1. Seal entire perimeter of roof cap seam: 1.2 hours
2. Remove and reinstall marker light to inspect gasket: 0.1 hours per light, with a maximum of 0.4 hours.
Note: marker light leaks are not a known issue on Cascadia and are a highly unlikely source of a roof leak. Only check the integrity of the marker light gaskets if the soapy water test (see Service Solution #3495) results in bubbles from one or more marker lights.

If leak repairs are performed and included on your FL545 claim, be prepared to provide a detailed description of the repairs, if requested.

Solution ID: 3498