

# SS 3499 Cascadia Frontwall Leaks

---

If a frontwall leak is detected, use the attached document as a guide for determining the proper repair procedure.

Refer to Service Solution 3495 for information about identifying potential leak locations.

If any of these repairs are completed in conjunction with the FL545 Recall, the required parts and materials, and up to the below listed amount of T-time may be included on the claim, using SRT code 996-0000T.

1. Seal lower A-pillar area: 0.5 hours per side. Note: a leak on both sides is very unlikely. Use the leak test described in Service Solution #3495 to determine if a lower A-pillar leak is present.
2. Cover electrical pass-through holes with appropriate waterproof tape: 0.2 hours.

If leak repairs are performed and included on your FL545 claim, be prepared to provide a detailed description of the repairs, if requested.

Solution ID: 3499