



Engine Support



CA503 : VEHICLE SERVICES | Wednesday, May 25, 2022

DANIEL LEE | Logout

[Help](#) | [Contacts](#) | [Dealer List](#) | [Site Map](#)

1-866-4-DEALER (1-866-433-2537)

[SALES](#)[SERVICE](#)[PARTS](#)[TRAINING](#)[RESOURCES](#)[HMA Dealer Portal](#) ▶ [Message View](#)[Back](#)**Service Campaign Launch 953 and T3G - Updated Dealer Best Practices and TSBs****Posted Date:** 10/03/2019 | **Dept:** All Departments**Service Campaign 953 Update: Engine Monitoring Logic (TSB #19-01-002H-3)**

Hyundai has launched a Product Improvement Campaign to perform a knock sensor software update on applicable vehicles.

Update: Supersedes TSB #19-01-002H-2 to update the Engine ECM software on 11-14MY Sonata and 13-14MY Santa Fe Sport

**Service Campaign T3G Update: Theta GDI Engine DTC P1326 (TSB #19-01-006H-3)**

Hyundai has launched a Service Campaign for applicable vehicles with 2.0L Turbo and 2.4L GDI engines that may experience the Check Engine warning lamp illuminated with DTC P132600.

Update: Supersedes TSB# 19-01-006H-2 and modifies the Service Procedure to update the Engine ECM.

Please see the updated TSBs on Hyundai Tech Info (HTI) and the related Dealer Best Practices (attached and available on Campaign Central).

[Campaign 953 ECM Software Update Dealer Best Practice\\_v12 10032019\\_Final.pdf](#) [Campaign T3G - Engine DTC P1326 from 953\\_v5 10032019.pdf](#) [Ways to Obtain 953 Customer Information - 092419 v2.pdf](#)