

 <b>HYUNDAI</b> <b>Technical Service Bulletin</b>	GROUP <b>ENGINE</b>	NUMBER <b>22-EM-001H</b>
	DATE <b>JANUARY 2022</b>	MODEL(S) <b>APPLICABLE VEHICLES BELOW</b>
<b>SUBJECT: ENGINE WARRANTY EXTENSION (TXXI)</b>		

**Description:** The warranty coverage for engine long block repair or replacement regarding engine damage or malfunction from connecting rod bearing wear has been extended to a Limited Lifetime Warranty and is valid for original and subsequent owners.

## NOTICE

The warranty extension is limited to vehicles owned by individual consumers that have:

- Completed the Knock Sensor Detection System software update (Campaign 953) AND
- A check engine warning lamp illumination with DTC P1326 (Campaign T3G) OR
- An engine concern related to connecting rod bearing wear or damage.

Additional limitations apply. Please refer to: [www.hmaenginesettlement.com](http://www.hmaenginesettlement.com)

Please refer to Service Campaign T3G TSB # 21-01-066H (or latest version) for the engine inspection/replacement procedure.

Please refer to TSB # 21-01-067H (or latest version) for applicable part numbers and labor ops.

### Applicable Vehicles:

Certain 2011-2014 MY Sonata (YF) vehicles with 2.0L Turbo and 2.4L engines  
 Certain 2015-2019 MY Sonata (LF) vehicles with 2.0L Turbo and 2.4L engines  
 Certain 2013-2018 MY Santa Fe Sport (AN) vehicles with 2.0L Turbo and 2.4L engines  
 Certain 2019 MY Santa Fe (TM) vehicles with 2.0L Turbo and 2.4L engines  
 Certain 2014-2015 MY Tucson (LM) vehicles with 2.4L engines  
 Certain 2018-2019 MY Tucson (TL) vehicles with 2.4L engines