




1





LH Side
Tailgate Latch


Overspray of bedliner treatment
directly on latch components




RH Side
Tailgate Latch



Overspray of bedliner treatment
directly on latch components






20147 05:05

SCRAP IF DROPPED



10 Nm MAX










03/19/20



LH Side
Tailgate Latch


Overspray of bedliner treatment
directly on latch components



RH Side
Tailgate Latch



Overspray of bedliner treatment
directly on latch components



Subject: Follow-up Discussion: Super Duty Vehicle Reviews Tailgate Next Steps

Location: webex

Start: 1/6/2021 7:00 PM

End: 1/6/2021 7:30 PM

Show Time As: Tentative

Recurrence: (none)

Meeting Status: Not yet responded

Organizer:

Required Attend

Resources: webex

This meeting is to follow-up on the two vehicles below. Let me know if you have a conflict with this time.

2020

Super Duty

vehicle at dealership, and able to duplicate daily.
(Customer works at dealership)

Complete -unable to duplicate concern. FSE found:

-C4004 The female side of the connector had excessive water build up on the top of the terminal cavities. There was no visible water in the connector but the pins had a white

hue like aluminum oxidation. Water was also observed under the seal retainer on the Male side of the connector.

- PDB: Water was visible near and on fuse 69 under the cover.

Next Step: Install a data logger (B. Shick).

Was the PDB cover installed properly when you reviewed vehicle.

2018

Super Duty



dealership contacted Ford, vehicle exhibiting unintended tailgate opening



Need to schedule a review

-- Do not delete or change any of the following text. --

Join Meeting

Meeting number (access code): 179 933 9189 Meeting password: AVvBnNRE265

Tap to join from a mobile device (attendees only)

+1-313-248-3668,,1799339189## FordNet 248-3668 / Toll

+1-888-628-3668,,1799339189## US Toll Free Number

Join by phone

+1-313-248-3668 FordNet 248-3668 / Toll

+1-888-628-3668 US Toll Free Number

Global call-in numbers | Toll-free calling restrictions

Join from a video system or application

Dial 1799339189@ford.webex.com

You can also dial 173.243.2.68 and enter your meeting number.

If you are a host, [click here](#) to view host information.

NOTICE: *This meeting may include the option for video. The recording of meetings is prohibited. For company policies on using video:* [click here](#)

For additional help with WebEx, Ford users can click on the Digital Worker link: [WebEx Support](#)

Can't join the meeting? [Contact support](#).

T32MC04

Subject: Follow-up Discussion: Vehicle Reviews Next Steps

Location: WebEx

Start: 1/6/2021 7:00 PM

End: 1/6/2021 7:30 PM

Show Time As: Tentative

Recurrence: (none)

Meeting Status: Not yet responded

Organizer:

Required Attend

Resources: WebEx

This meeting is to follow-up on the two vehicles below. Let me know if you have a conflict with this time.

2020

Super Duty

vehicle at dealership, and able to duplicate daily.
(Customer works at dealership)

Complete -unable to duplicate concern. FSE found:

-C4004 The female side of the connector had excessive water build up on the top of the terminal cavities. There was no visible water in the connector but the pins had a white hue like aluminum oxidation. Water was also observed under the seal retainer on the

Male side of the connector.

- PDB: Water was visible near and on fuse 69 under the cover.

Next Step: Install a data logger (B. Shick).

Was the PDB cover installed properly when you reviewed vehicle.

2018

Super Duty

dealership contacted Ford, vehicle exhibiting unintended tailgate opening

Need to schedule a review

-- Do not delete or change any of the following text. --

Join Meeting

Meeting number (access code): 179 117 9749 Meeting password: aqT3wQ2yDa4

Tap to join from a mobile device (attendees only)

+1-313-248-3668,,1791179749## FordNet 248-3668 / Toll

+1-888-628-3668,,1791179749## US Toll Free Number

Join by phone

+1-313-248-3668 FordNet 248-3668 / Toll

+1-888-628-3668 US Toll Free Number

Global call-in numbers | Toll-free calling restrictions

Join from a video system or application

Dial 1791179749@ford.webex.com

You can also dial 173.243.2.68 and enter your meeting number.


If you are a host, [click here](#) to view host information.


NOTICE: *This meeting may include the option for video. The recording of meetings is prohibited. For company policies on using video:* [click here](#)


For additional help with WebEx, Ford users can click on the Digital Worker link: [WebEx Support](#)


Can't join the meeting? [Contact support.](#)


T32MC04




























From:
Sent:
To:
Subject:













Thx, Ken








From:
Sent:
To:
Subject:















From:
Sent:
To:
Subject:













From:
Sent:
To:
Subject:
















From:
Sent:
To:
Subject:



































Sent from my iPhone

The content of this email is confidential and is meant solely for use of the intended recipient. You may not share any part of this message with any third party without the written consent of the sender. If you received this message by mistake, please reply to (and then delete) this message. Please note that we have taken every precaution to insure that this message is error and virus free. However, we make no representation of the same and do not accept any liability for any damage caused by the content of this email or any attachments thereto. All recipients (intended or otherwise) should check this email and attachments for threats. Please do not print this email unless necessary; every unprinted email helps the environment.

Date: Mon, Aug 24, 2020 at 9:38 AM

Subject: Fwd: Tail gate malfunction

Sent from my iPhone

Begin forwarded message:

From: [REDACTED]


Date: August 17, 2020 at 5:42:41 PM PDT

To: mikeb@bickford.net

Subject: Tail gate malfunction

That's my 2017 40foot raptor that got damaged from the tail gate dropping.

[REDACTED]
2019 Ford F-450 platinum purchased in April























Sent from my iPhone


The content of this email is confidential and is meant solely for use of the intended recipient. You may not share any part of this message with any third party without the written consent of the sender. If you received this message by mistake, please reply to (and then delete) this message. Please note that we have taken every precaution to insure that this message is error and virus free. However, we make no representation of the same and do not accept any liability for any damage caused by the content of this email or any attachments thereto. All recipients (intended or otherwise) should check this email and attachments for threats. Please do not print this email unless necessary; every unprinted email helps the environment.







From:
Sent:
To:
Subject:
Attachments:



Get [Outlook for iOS](#)



