

RD-17-NBR+PVC<1304 RD-17-NBR+PVC<1304 RD-17-NBR+PVC<1304

This file represents a consolidation of multiple files sent by the manufacturer. Please use the bookmarks to navigate to each file. (Each bookmark label is the name of the original file.)

Honda Motor Co. Light Vehicles	NHTSA Report for TREAD Act	NHTSA Reporting Period:
--	-----------------------------------	--------------------------------

Report Information :

Report ID : [REDACTED]	# of Attachments : 4	Zone / District : 03 / 03G
Report Method : V s t	Create Date : 06/20/2022 12:16:48	
Brief Description : Rear d fferent a eak		

Customer Information :

Customer Name :	City / State : Un on / NJ
Delivery Date : 05/11/2022	

Vehicle Information:

Make : Honda	Model Series : CR-V	Engine Number : L15BE6529417
NHTSA Model : CR-V	Model ID : RW2H9NKNW	Style :
Model Year : 2022	Mileage : 5750	Transmission : CVT
VIN : [REDACTED]	Unit Status : So d to Customer	Body : AWDTRG
	Date of Occurrence : 06/20/2022	Engine Type:

Dealer Information :

Dealer Number / Contact : [REDACTED]
Phone Number : [REDACTED] Extension :

Claim Information :

NHTSA Component Code : 10 - POWER TRAIN		
Claim Number :	Fire? : NO	Rollover? : NO
Complaint code : 2400 / AWD/4WD PROBLEM		
Labor Operation Cd / Desc :		
Labor Op Full Code / Desc :		

Failed Part(s) :

Complaint / Symptom:

Customer states they heard a very oud noise whi e driving and then there was a message for AWD System Prob em

Probable Cause :

Inspected vehic e and found the rear differentia sea eaked out a the fluid causing damage to the rear differentia carrier. Checked and did not see any signs of impact at a .

Corrective Action :

Dea er ordered rear diff.



Y40622







This file represents a consolidation of multiple files sent by the manufacturer. Please use the bookmarks to navigate to each file. (Each bookmark label is the name of the original file.)

Honda Motor Co. Light Vehicles	NHTSA Report for TREAD Act	NHTSA Reporting Period:
--	-----------------------------------	--------------------------------

Report Information :

Report ID : [REDACTED]	# of Attachments : 4	Zone / District : 06 / 06L
Report Method : V s t		Create Date : 07/22/2022 16:39:05
Brief Description : D fferent a F uid Leak		

Customer Information :

Customer Name :	City / State : Lou sv e / KY
Delivery Date : 07/08/2022	

Vehicle Information:

Make : Honda	Model Series : CR-V	Engine Number : [REDACTED]
NHTSA Model : CR-V	Model ID : RW2H5NJW	Style :
Model Year : 2022	Mileage : 1508	Transmission : CVT
VIN : [REDACTED]	Unit Status : So d to Customer	Body : AWDEX
	Date of Occurrence :	Engine Type:

Dealer Information :

Dealer Number / Contact : [REDACTED]
Phone Number : [REDACTED] Extension :

Claim Information :

NHTSA Component Code : 10 - POWER TRAIN		
Claim Number :	Fire? : NO	Rollover? : NO
Complaint code : 2300 / 2WD DIFFERENTIAL PROB		
Labor Operation Cd / Desc :		
Labor Op Full Code / Desc :		

Failed Part(s) :

Complaint / Symptom:

The right rear shaft came apart, ooks ike diff fluid leak,and left side shaft seems damaged.

Probable Cause :

Fai ed Part Numbers are: 42310-TLA-A21 Drive shaft Assembly quantity of two 41200-5TG-010 Carrier Assembly

Corrective Action :

Rep aced Differentia axle







This file represents a consolidation of multiple files sent by the manufacturer. Please use the bookmarks to navigate to each file. (Each bookmark label is the name of the original file.)

Honda Motor Co. Light Vehicles	NHTSA Report for TREAD Act	NHTSA Reporting Period:
--	-----------------------------------	--------------------------------

Report Information :

Report ID : [REDACTED]	# of Attachments : 2	Zone / District : 06 / 06A
Report Method : V s t		Create Date : 08/08/2022 16:50:51
Brief Description : Rear D fferentia eaking - Thread ng ssue		

Customer Information :

Customer Name :	City / State : Paducah / KY
Delivery Date : 08/23/2019	

Vehicle Information:

Make : Honda	Model Series : CR-V	Engine Number : [REDACTED]
NHTSA Model : CR-V	Model ID : RW2H8KJNW	Style :
Model Year : 2019	Mileage : 31514	Transmission : CVT
VIN : [REDACTED]	Unit Status : So d to Customer	Body : AWDEXL
	Date of Occurrence : 08/05/2022	Engine Type:

Dealer Information :

Dealer Number / Contact : [REDACTED]
Phone Number : [REDACTED] Extension :

Claim Information :

NHTSA Component Code : 10 - POWER TRAIN		
Claim Number :	Fire? : NO	Rollover? : NO
Complaint code : 2400 / AWD/4WD PROBLEM		
Labor Operation Cd / Desc :		
Labor Op Full Code / Desc :		

Failed Part(s) :

Complaint / Symptom :


customer states fluid is eaking from rear

Probable Cause :

Unknown- Tech found threading in the rear differentia unit fai ed causing a eak

Corrective Action :

Rep aced Rear Differentia





This file represents a consolidation of multiple files sent by the manufacturer. Please use the bookmarks to navigate to each file. (Each bookmark label is the name of the original file.)

Honda Motor Co. Light Vehicles	NHTSA Report for TREAD Act	NHTSA Reporting Period:
-----------------------------------	----------------------------	-------------------------

Report Information :

Report ID : ██████████	# of Attachments : 1	Zone / District : 06 / 06C
Report Method : Phone	Create Date : 01/03/2023 16:15:54	
Brief Description : Rear axes broken d fferent a eaking		

Customer Information :

Customer Name :	City / State : E yra / OH
Delivery Date : 09/12/2022	

Vehicle Information:

Make : Honda	Model Series : CR-V	Engine Number : ██████████
NHTSA Model : CR-V	Model ID : RW2H8NJNW	Style :
Model Year : 2022	Mileage : 1686	Transmission : CVT
VIN : ██████████	Unit Status : So d to Customer	Body : AWDEXL
Date of Occurrence : 12/29/2022		Engine Type:

Dealer Information :

Dealer Number / Contact ██████████	Extension :
Phone Number ██████████	

Claim Information :

NHTSA Component Code : 10 - POWER TRAIN		
Claim Number :	Fire? : NO	Rollover? : NO
Complaint code : 2400 / AWD/4WD PROBLEM		
Labor Operation Cd / Desc :		
Labor Op Full Code / Desc :		

Failed Part(s) :

Complaint / Symptom:

Rear driver side axe twisted and broke. Passenger side rear showing signs of twisting. Rear differentia eaking.

Probable Cause :

Excessive fluid loss.

Corrective Action :

Rep ace rear differentia and rear axes.









MFD. BY HONDA DEVELOPMENT &
MANUFACTURING OF AMERICA, LLC 08/'22
GVWR 2150KG (4739LBS) TIRE SIZE RIM SIZE
GAWR F 1100KG (2425LBS) 235/60R18 103H 18X7.5J
GAWR R 1075KG (2369LBS) 235/60R18 103H 18X7.5J
THIS VEHICLE CONFORMS TO ALL APPLICABLE
FEDERAL MOTOR VEHICLE SAFETY
AND THEFT PREVENTION STANDARDS IN EFFECT
ON THE DATE OF MANUFACTURE SHOWN ABOVE.
V.I.N.: 7FARW2H84NE [REDACTED] TYPE: MPV

[REDACTED]

TNR N AB9 -NH883PX -F -E



