

| DTC Code | DTC Desc |
|-----------------|---|
| B0013 | Passenger Knee Bolster Deployment Control |
| B0050 | Driver Seatbelt Sensor |
| B0070 | Driver Seatbelt Pretensioner "A" Deployment Control |
| B0071 | First Row Center Seatbelt Pretensioner Deployment Control |
| B0072 | Passenger Seatbelt Pretensioner "A" Deployment Control |
| B007A | Passenger Seatbelt Pretensioner "B" Deployment Control |
| B007E | Driver Seatbelt Pretensioner "C" Deployment Control |
| B007F | Passenger Seatbelt Pretensioner "C" Deployment Control |
| U0300 | Internal Control Module Software Incompatibility |
| U0401 | Invalid Data Received from ECM/PCM A |
| U3000 | Control Module |
| U3003 | Battery Voltage |
| U023A | Lost Communication With Image Processing Module A |
| P1000 | OBD Systems Readiness Test Not Complete |
| U024C | Lost Communication with Seat Control Module "H" |
| P1111 | System Pass |
| U0403 | Invalid Data Received From Transfer Case Control Module |
| U0212 | Lost Communication With Steering Column Control Module |

| Labor Operation Code |
|----------------------|
| 14056D |
| 61108AL |
| 61108AR |
| 14056D45 |
| 04536B |
| 12650DX1 |
| 12651DX1 |
| 14056D1 |
| 12651D |
| 12651D45 |
| 12650D45 |
| 24356A |
| 12651D45WR |
| 12650D |
| 12650D80 |
| 63100AT |
| 61108AT |
| 14056D45WR |
| 61168A |
| 12650D47 |
| 12652D45 |
| 61202AR |
| 12650D81 |
| 63100AR |
| 61202AT |
| 61202AL |
| 14056D44 |
| 12650D45WR |
| 12650D82 |
| 63100AL |
| 14056D3T |
| 14056D11F |
| 24356AT |
| 14056D5L |
| 14056D11FT |
| 63100A15RB |
| MT611B09 |
| MT65099 |
| MT14A005 |
| MT78611B09 |
| MTDIAG |
| MT61108AL |
| MTACCESS |
| MT78610E45 |
| MTSEAT |
| MT61108AR |
| MT14056D1 |
| MT14B321 |
| MTBOLT |
| MTIME |
| MT611B08 |
| MT04536B |
| MT78611B08 |

| |
|-------------|
| MTCONSOLE |
| MT610E45 |
| MTSEATRET |
| MT610E44 |
| MT61108 |
| MT78611 |
| MTBAG |
| MTCIRCUIT |
| MTWIRE |
| MT31000 |
| MT14056D |
| MTREPAIR |
| MTRIPILLAR |
| MT61202AR |
| MT78610 |
| MT24356A |
| MT14056D45 |
| MT13000B |
| MT61109 |
| MT14S411 |
| MT602B82 |
| MTRIBPILLAR |
| MT45A36 |
| MT12651DWR |
| MTHARNESS |
| MT12651D45 |
| MTADJUST |
| MTLABOR |
| MT611B608 |
| MT78611B095 |
| MT14056 |
| MTTRACE |
| MT14056D44 |
| MT63100ADT |
| MT24356AT |
| MT14B32 |
| MT12651D |
| MT04563B |
| MTRICONSOLE |

PRESENT)

| Problem Code (Customer Concern Code) |
|---|
| S38 |
| S40 |
| S39 |
| S25 |
| A79 |
| S10 |
| A99 |
| A78 |
| S22 |
| S26 |
| G32 |
| S56 |
| A77 |
| D42 |

| Problem Code Description |
|--|
| AIR BAG (SRS) |
| OTHER RESTRAINT |
| AIRBAG WARNING/STATUS LIGHT |
| SEAT BELT - RETRACTOR (COIL/UNCOIL) ISSUES |
| LV CONNECTOR TERMINAL ISSUES |
| SEAT - OTHER |
| ADMINISTRATIVE (PARTS RETURN/ETC.) |
| LV CONNECTOR DISCONNECTS |
| SEAT BELT - LOCKS-UP WHILE DRIVING |
| SEAT BELT/BUCKLE - LATCHING ISSUES |
| INST CLUST/MESSAGE CENTER |
| HEATED/COOLED (VENTILATED) SEATS |
| LV CONNECTOR DAMAGE / CORROSION |
| PERFORMANCE/ENGINE POWER AND ACCELERATION |