










Select a Document:

-  [#20-NA-047: Front or Rear Crankshaft Oil Leak, Malfunction Indicator Lamp \(MIL\) Illuminated - DTC P1101 Set - \(Mar 12, 2020\).](#)
-  [#17-NA-198: Difficulty Adjusting Manual Seat Height and/or Seat Stuck in Lowest/Highest Position - \(Mar 3, 2020\).](#)
-  [#17-NA-341: 120V Portable Charge Cord is Inoperative or Charges Vehicle Intermittently - \(Mar 2, 2020\).](#)
-  [#17-NA-186: HVAC Pop-up is Blank and/or Personalization Selections within Climate and Air Quality, Collision/Detection Systems, or Lighting Menus are Missing at Times - \(Jan 31, 2020\).](#)
-  [#19-NA-206: Intermittent Shift to Park Message Displayed While Vehicle in Park - \(Jan 30, 2020\).](#)
-  [#16-NA-122: Side Detection System Message Being Displayed on Driver Information Center \(DIC\) - DTC B101E-43 Set - \(Jan 23, 2020\).](#)
-  [#08-03-10-006G: Tire Slowly Goes Flat, Tire Air Loss, Low Tire Pressure Warning Light Illuminated, Aluminum Wheel Bead Seat Corrosion \(Clean and Resurface Wheel Bead Seat\) - \(Nov 12, 2019\).](#)
-  [#19-NA-103: Intermittent Click Noise at Front of Vehicle, ABS, Traction Control System \(TCS\)/Stabilitrak Lamps May Illuminate Intermittently and/or Deactivate for Ignition Cycle, DTC P0721, P215B, C0500-C0504 and/or C0506-C050A Set - \(Oct 9, 2019\).](#)
-  [#18-NA-186: Loss of Propulsion or No Start with Malfunction Indicator Lamp \(MIL\) Illuminated, DTC P0A3F or P1B03 Set - \(Sep 17, 2019\).](#)
-  [#19-NA-211: Loss of Propulsion or No Start with Malfunction Indicator Lamp \(MIL\) Illuminated and DTC P0A45 or P1B04 Set - \(Sep 13, 2019\).](#)
-  [#16-NA-042: Infotainment System Upgrade for Android Auto Feature - \(Aug 28, 2019\).](#)
-  [#16-NA-109: Grease or Sealant Visible on Electronic Power Steering Gear - Should Not Be Interpreted as Leak - \(Aug 5, 2019\).](#)
-  [#19-NA-081: Audio Muting When Listening to Some SiriusXM Channels Due to Interference in Some Geographic Locations - \(Jul 12, 2019\).](#)
-  [#13-08-116-001E: Aftermarket ALDL or DLC Interface Devices Causing Multiple Issues - \(Jun 26, 2019\).](#)
-  [#11-08-49-001Z: Transport Mode On Message Displayed in DIC and/or Battery Light is Flashing - \(Mar 11, 2019\).](#)
-  [#18-NA-016: DTC P3260 - Internal Control Module Drive Motor Control Performance Set - \(Mar 6, 2019\).](#)
-  [#18-NA-153: Wireless Charging System Check/Phone Compatibility/Retrofit Kit Available - \(Jan 10, 2019\).](#)
-  [#18-NA-330: Malfunction Indicator Lamp Illuminated and/or No Start with Battery Circuit DTCs Set - \(Nov 5, 2018\).](#)
-  [#16-NA-316: Rear Axle Creak Noise Over Irregular Surfaces - \(Nov 1, 2018\).](#)
-  [#18-NA-332: Malfunction Indicator Lamp \(MIL\) On, DTC P2097 Set - \(Nov 1, 2018\).](#)
-  [#18-NA-096: MIL ON - DTC U016B Lost Communication with Electric A/C Compressor Control Module Set and Will Not Clear - \(Oct 26, 2018\).](#)
-  [#17-NA-145: Diagnostic Tip for Low or No Cabin Heat, and/or Noisy Auxiliary Coolant Pump - \(Sep 26, 2018\).](#)
-  [#16-NA-239: Information on Enabling 4G LTE Wi-Fi Hotspot on New Vehicle - \(Sep 6, 2018\).](#)

- [!\[\]\(95b42f0077faf7439a26242a54e021ec_img.jpg\) #18-NA-261: No Start, Malfunction Indicator Lamp \(MIL\) Illuminated - DTC U2603, U2604, U2605, U2606, U2617, U2618, U2619, U2620, U2621, U2622, U2623 and/or U2624 Set - \(Aug 24, 2018\).](#)
- [!\[\]\(e097ab4c08b8186dd0908330bbc2dc28_img.jpg\) #18-NA-242: Charging Port and/or Fuel Port Door Light On, Malfunction Indicator Lamp \(MIL\) Illuminated - DTC P04B6 Set - \(Aug 1, 2018\).](#)
- [!\[\]\(1e9d865c5de095f8e3304757c49e79d7_img.jpg\) #16-NA-127: Engine Odor and/or Burning Smell Within Cabin - \(Jun 4, 2018\).](#)
- [!\[\]\(735b10d724a5f0ec5005c4eb3eb9c9d1_img.jpg\) #18-NA-174: Rattle or Pop Noise During Gas Engine Start - \(May 23, 2018\).](#)
- [!\[\]\(e6250f05bc27fa93236b816562b699f9_img.jpg\) #18-NA-173: Malfunction Indicator Lamp \(MIL\) Illuminated - DTC P0AEE, P0AF3, P0BD2, P0BD7, P0BDC and/or P0BE1 Set - \(May 22, 2018\).](#)
- [!\[\]\(d190cc638f389909d4b049d6c19e4cb2_img.jpg\) #02-08-98-002H: Hem Flange Rust Repair - \(May 15, 2018\).](#)
- [!\[\]\(4d34001966c7597a8c3e4293694bde37_img.jpg\) #16-NA-060: Difficulty Shifting Out of Park or into Park - \(Mar 6, 2018\).](#)
- [!\[\]\(70b9adae95aa76ce55f26a9fb944efce_img.jpg\) #17-NA-215: Red LED, No WiFi Operation, and/or Limited OnStar Module Functionality After OnStar Module Replacement for Another Condition - \(Feb 28, 2018\).](#)
- [!\[\]\(7b780ea9fe954e20f3a1890df3f944e2_img.jpg\) #16-NA-203: Active Shutters Inoperative, Malfunction Indicator Lamp \(MIL\) Illuminated - DTC P059F Set - \(Feb 27, 2018\).](#)
- [!\[\]\(6ed942f5426e79452fae08b09c55d70a_img.jpg\) #18-NA-047: Malfunction Indicator Lamp Illuminated, DTC P2097 Set - \(Feb 15, 2018\).](#)
- [!\[\]\(7ac021fc5aa83a899c22bb9c073b3a95_img.jpg\) #16-NA-147: Brake Pedal Squeak Noise Heard When Applying and Releasing Brake Pedal/Cruise Control Inoperative or Disengaged - \(Jan 19, 2018\).](#)
- [!\[\]\(ac644161d49341d629aea2711a2e6e9e_img.jpg\) #16-NA-075: Power Foldaway Mirror Glass Shakes, Flutters at Normal Driving Speeds - \(Dec 15, 2017\).](#)
- [!\[\]\(e0abb7c68acc16c8045492bb231c4b01_img.jpg\) #16-NA-341: Waiting for Update Media Message Displayed Under Various Conditions - \(Nov 28, 2017\).](#)
- [!\[\]\(f7ae7c0fb463c75dd672b3ca6e6deab8_img.jpg\) #07-06-04-019F: Intermittent Malfunction Indicator Lamp \(MIL\) Illuminated, DTC P2138 with Reduced Engine Power \(Repair Instrument Panel \(IP\) to Body Harness Connector\) - \(Nov 17, 2017\).](#)
- [!\[\]\(a111623bd72ed30a4b87ae6ecc564347_img.jpg\) #17-NA-146: Service Parking Brake Message Displayed on Driver Information Center \(DIC\) - DTCs C1138, C1148, C114C, C1586, C1587, C1588 Set - \(Nov 6, 2017\).](#)
- [!\[\]\(0f6f994ab4c227dedcb0120d2e4578f9_img.jpg\) #16-NA-396: Intermittent Operation of Key Fobs, Door Unlock Inoperative "No Remote Detected" Message with Possible TPM MIL - \(Oct 18, 2017\).](#)
- [!\[\]\(2038f55e2fb2bf049e5d18738c9b6749_img.jpg\) #17-NA-295: Rattle Type Noise Heard in Cargo Area and/or Missing Tire Inflator Spacer in the Inflator Kit - \(Sep 18, 2017\).](#)
- [!\[\]\(8b3bb7af4c88c70f913e0f53c69b584b_img.jpg\) #17-NA-241: Charge Port Bezel Preventing Charging when Plugging in Charging Handle - \(Jul 21, 2017\).](#)
- [!\[\]\(de99c425ce328ea1bb5f0281f304fdb8_img.jpg\) #17-NA-083: Adaptive Cruise Control Unavailable in Bare Areas - \(Jun 26, 2017\).](#)
- [!\[\]\(57f21dc2759cc317217f298e29d861b3_img.jpg\) #16-NA-225: Diagnostic Tip for Hesitation, Surging, Staling and/or Malfunction Indicator Lamp Illuminated \(MIL\) - DTC P2635 and/or P018B Set - \(Apr 26, 2017\).](#)
- [!\[\]\(498433ed7a9755cf68896c0f712aed1a_img.jpg\) #17-NA-047: EBCM Wheel Speed Sensor Diagnostic Aid for ABS Message - Click or Ratchet Noise - Service Traction Message - Service Stabilitrak Message - Service Steering Message - \(Feb 20, 2017\).](#)
- [!\[\]\(383227c1dec52b0f22f83f97aa406e1e_img.jpg\) #16-NA-400: Diagnostic Tip for No Start, No Movement, Shift to Park Light On, Malfunction Indicator Lamp \(MIL\) Illuminated with DTC P0C28, P07A7, P1E39, P3260, P1A50, P1A53, P0B01, P0B04, or P0B07 Set - \(Dec 8, 2016\).](#)
- [!\[\]\(65aedb68fa51e83ccf661bb7a3a0a21f_img.jpg\) #16-NA-193: Dead Battery, No Start and/or Multiple DTCs - \(Nov 21, 2016\).](#)
- [!\[\]\(40679573b940492a30dc418063bfdb02_img.jpg\) #16-NA-273: Rear Door Handle Will Not Open the Door, Child Safety Lock Sticking - \(Aug 29, 2016\).](#)
- [!\[\]\(4b9bfc11ce7d3ddc27e5e7a95c7e6922_img.jpg\) #16-NA-242: Diagnostic Tips for USB Receptacle Inoperative - \(Aug 2, 2016\)](#)

© 2020 General Motors. All rights reserved.

-  [#16-NA-219: GPS Inoperative, Red Line Across GPS Indicator, or the Location is Stuck in Warren Michigan - \(Jun 30, 2016\)](#)
-  [#16-NA-140: Erratic Functionality of the ICS Touch Display When Performing A Swiping Motion Across the Display - \(May 2, 2016\)](#)
-  [#16-NA-136: Fuel Smell or Odor in Passenger Cabin While Driving or Sitting Still - \(Apr 28, 2016\)](#)
-  [#16-NA-049: Clicking Noise Near Brake Pedal, Hard Brake Pedal, White Tie Strap on Brake Pedal Assembly and or Possible DTCs C058A, P2299 or P05E0 Set - \(Apr 11, 2016\)](#)
-  [#16-NA-114: Coolant Leak from Heater Water Auxiliary Pump Hose - \(Apr 11, 2016\)](#)
-  [#16-NA-090: ABS Warning Light On, Traction Control System \(TCS\)/Stabilitrak Light On, Service Brake Assist and Service Stabilitrak Messages on DIC - \(Mar 23, 2016\)](#)
-  [#16-NA-076: Poor Horn Performance, Muffled and/or Not Loud - \(Mar 14, 2016\)](#)
-  [#16-NA-062: CHARGE DOOR OPEN Message Displayed with Charge Port Door Closed - \(Feb 25, 2016\)](#)
-  [#16-NA-011: Infotainment System Will Not Return to Media After Bluetooth Call Ends - \(Jan 19, 2016\)](#)