



Close Window

View Field Action Details



This screen allows IVH users to view the detail information for the selected VIN on Filed Action.

Vehicle Information

VIN: [REDACTED] Model: 1RF68-2017 VOLT
 Service Contract: No Branded Title: No Warranty Block: No PDI Status: Yes
 Order Type: 70 - RETAIL - STOCK
 Field Actions: [0 Open](#)

Field Action Details

Type	Number	Description	Release Date
Service Update Bulletins	N162071700	P2097 (Post O2 Trim Diagnostic) False Failing	02/10/2017
Status:	Closed		
Group:			
Sub-Group:	4015		
Expires:	08/22/2019		
Original Number:	17058		
Labour Ops:	9102988 FA 17058 - Drive Motor Power Inverter Module Reprogramming with SPS		
Government Agency #:			
Field Action Description:	The post O2 trim diagnostic may falsely fail causing DTC P2097 to set, commanding a Malfunction Indicator Light (MIL) to illuminate. The vehicle runs and functions as normal with no other symptoms.		
Safety Risk Description:			
Repair Description:	Reprogram the Drive Motor Power Inverter Module.		
Note:	Expires with Bumper to Bumper Limited Warranty		