



Close Window

View Field Action Details



This screen allows IVH users to view the detail information for the selected VIN on Filed Action.

Vehicle Information

VIN: [REDACTED] Model: 1RF68-2017 VOLT
 Service Contract: No Branded Title: No Warranty Block: No PDI Status: Yes
 Order Type: 70 - RETAIL - STOCK
 Field Actions: [0 Open](#)

Field Action Details

| Type | Number | Description | Release Date |
|---------------------------|---|---|--------------|
| Service Update Bulletins | N162071700 | P2097 (Post O2 Trim Diagnostic) False Failing | 02/10/2017 |
| Status: | Closed | | |
| Group: | | | |
| Sub-Group: | 4015 | | |
| Expires: | 08/22/2019 | | |
| Original Number: | 17058 | | |
| Labour Ops: | 9102988 FA 17058 - Drive Motor Power Inverter Module Reprogramming with SPS | | |
| Government Agency #: | | | |
| Field Action Description: | The post O2 trim diagnostic may falsely fail causing DTC P2097 to set, commanding a Malfunction Indicator Light (MIL) to illuminate. The vehicle runs and functions as normal with no other symptoms. | | |
| Safety Risk Description: | | | |
| Repair Description: | Reprogram the Drive Motor Power Inverter Module. | | |
| Note: | Expires with Bumper to Bumper Limited Warranty | | |