

Request 5

State, by model and model year, a total count for all of the following categories of claims, collectively, that have been paid by Ford to date that relate to, or may relate to, the alleged defect in the subject and peer vehicles: warranty claims; extended warranty claims; claims for good will services that were provided; field, zone, or similar adjustments and reimbursements; and warranty claims or repairs made in accordance with a procedure specified in a technical service bulletin or customer satisfaction campaign.

Separately, for each such claim, state the following information:

- a. Ford's claim number;
- b. Vehicle owner or fleet name (and fleet contact person), email address and telephone number (please use distinct fields for each data type);
- c. Vehicle owner or fleet street address, city, state (postal abbreviation), and ZIP code (please use distinct fields for each data type);
- d. 17-character VIN;
- e. Repair date (MM/DD/YYYY);
- f. Vehicle mileage at time of repair (numeric data type);
- g. Repairing dealer's or facility's name, telephone number, city and state or ZIP code (please use distinct fields for each data type);
- h. Labor operation number(s);
- i. Problem code(s);
- j. Diagnostic trouble code(s);
- k. Failed part number(s) and description(s);
- l. Replacement part number(s) and description(s);
- m. Concern stated by customer;
- n. Cause as stated on the repair order;
- o. Correction as stated on the repair order; and
- p. Additional comments, if any, by dealer/technician relating to claim and/or repair.

Provide this information in Microsoft Excel 2010, or a compatible format, entitled "WARRANTY DATA."

Answer

Records identified in a search of Ford's warranty database were reviewed for relevance and sorted in accordance with the categories described in the following table.

Category	Definition
A	Secondary fuel filter housing breach which results in a fuel leak. Secondary fuel filter crack, seam leak, pinhole leak, ambiguous leak, or fuel filter port break / crack.
A1	Potential or alleged secondary fuel filter housing related report with an alleged fire starting in the engine compartment.
B	Ambiguous fuel leak (unclear if it is at the Secondary fuel filter or Primary fuel filter)