



**A14439817 and A14439742  
FDM Jet Pump Orifice Change  
ICA for SAQ2021622979 (Crank/No Start)**





**From:** [Orea, Javier Antonio](#)  
**To:** [Lara, Maria Fernanda](#); [Dreier, Paul \(P.\)](#)  
**Subject:** RE: CD6 open issues tracker  
**Date:** Wednesday, June 28, 2023 1:14:51 PM  
**Attachments:** [image001.png](#)  
[CD6-Open\\_Issues\\_Tracker.xlsx](#)  
[CD6 Tank Pressure Control Valve Supplier Relocation .msg](#)

---

Hello Paul,

Here's the updated tracker we reviewed yesterday in the meeting.



Thanks.  
Best regards,

**Javier Antonio Orea**  
Associate Product Dev Engineer

**Kautex Textron Mexico**  
Km 117 Autopista Mexico-Puebla  
Parque Industrial FINSA nave 8, PUE, 72710  
[www.kautex.com](http://www.kautex.com)

Email: [javierantonio.orea@kautex.com](mailto:javierantonio.orea@kautex.com)

DRIVING THE FUTURE



---

**From:** Lara, Maria Fernanda <[mariafernanda.lara@kautex.com](mailto:mariafernanda.lara@kautex.com)>  
**Sent:** Wednesday, June 28, 2023 9:34 AM  
**To:** Dreier, Paul (P.) <[pdreier@ford.com](mailto:pdreier@ford.com)>; Orea, Javier Antonio <[javierantonio.orea@kautex.com](mailto:javierantonio.orea@kautex.com)>  
**Subject:** RE: CD6 open issues tracker

Adding [@Orea, Javier Antonio](#)

Best regards,

**Maria Fernanda Lara**  
KDP Product engineer

**Kautex Textron Mexico**  
Km 117 Autopista Mexico-Puebla  
Parque Industrial FINSA nave 8, PUE, 72710  
[www.kautex.com](http://www.kautex.com)


Email: [mariafernanda.lara@kautex.com](mailto:mariafernanda.lara@kautex.com)


DRIVING THE FUTURE



---

**From:** Dreier, Paul (P.) <[pdreier@ford.com](mailto:pdreier@ford.com)>  
**Sent:** Friday, May 19, 2023 7:35 AM  
**To:** Paredes, Jessica Elizabeth <[jessicaelizabeth.paredes@kautex.com](mailto:jessicaelizabeth.paredes@kautex.com)>; Lara, Maria Fernanda <[mariafernanda.lara@kautex.com](mailto:mariafernanda.lara@kautex.com)>








Email: [jessicaelizabeth.paredes@kautex.com](mailto:jessicaelizabeth.paredes@kautex.com)


DRIVING THE FUTURE














ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION



PE24-019 000013 ES

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION



PE24-019 000014 ES

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION



PE24-019 000015 ES

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION



PE24-019 000016 ES

**Julio Cesar Renteria N.**

Product Engineering  
Fuel Delivery Modules

Mexico Technical Center  
(656).689.28.00 x 3592 MX Office  
(656).199.7869 Mobile

[jurenteria@borgwarner.com](mailto:jurenteria@borgwarner.com)

---

**From:** Benitez T, Miguel Angel (.) <[mbenit25@ford.com](mailto:mbenit25@ford.com)>

**Sent:** Monday, January 9, 2023 3:37 PM

**To:** Garcia, Oscar G. (Juarez-TC) <[oscgarcia@borgwarner.com](mailto:oscgarcia@borgwarner.com)>; Pollitt, Dwayne (D.) <[dpollitt@ford.com](mailto:dpollitt@ford.com)>

**Cc:** Kaparthi, Prashanth (P.) <[pkaparth@ford.com](mailto:pkaparth@ford.com)>; Dreier, Paul (P.) <[PDREIER@ford.com](mailto:PDREIER@ford.com)>; Sanchez, David (D.S.) <[dsanch21@ford.com](mailto:dsanch21@ford.com)>; Meng, Julie (Z.) <[jmeng@ford.com](mailto:jmeng@ford.com)>; Rascon, Alejandra Patricia (Juarez-TC) <[arascon@borgwarner.com](mailto:arascon@borgwarner.com)>; Valles, Benjamin (Juarez-TC) <[bvalles@borgwarner.com](mailto:bvalles@borgwarner.com)>; Terrazas, Angel (Chihuahua) <[anterrazas@borgwarner.com](mailto:anterrazas@borgwarner.com)>; Herrera, Roberto (Juarez-TC) <[rherrera@borgwarner.com](mailto:rherrera@borgwarner.com)>; Espinoza, Sonia (Juarez-TC) <[sespinoza@borgwarner.com](mailto:sespinoza@borgwarner.com)>; Mendoza, Hector Rene (Juarez-TC) <[hemendoza@borgwarner.com](mailto:hemendoza@borgwarner.com)>; Avila, Erick O (Juarez-TC) <[eriavila@borgwarner.com](mailto:eriavila@borgwarner.com)>; Chmielewski, Thad (T.A.) <[TCHMIELE@ford.com](mailto:TCHMIELE@ford.com)>; DePotter, Valerie (V. S.) <[vdepotte@ford.com](mailto:vdepotte@ford.com)>; Dokas, David (D.M.) <[ddokas@ford.com](mailto:ddokas@ford.com)>; Renteria, Julio C (Juarez-TC) <[jurenteria@borgwarner.com](mailto:jurenteria@borgwarner.com)>; Hosana, Stephen (S.) <[SHOSANA@ford.com](mailto:SHOSANA@ford.com)>; Bolton, Al (A.F.) <[abolton@ford.com](mailto:abolton@ford.com)>; Murray, Robert (R.A.) <[rmurra33@ford.com](mailto:rmurra33@ford.com)>; Dreier, Paul (P.) <[PDREIER@ford.com](mailto:PDREIER@ford.com)>

**Subject:** RE: Alerts for new Jet pump orifice size - crank no start issue



**EXTERNAL SENDER**

For reference — this is what Julio had shared on Dec 6. Please confirm if we're on track. Thanks.

Estimated Start Date: Jan18, 2023

Completion date: Feb 08, 2023

PVPR Date: Feb 10, 2023

Thank you. All the best.

Miguel Ángel Benítez Torreblanca

Global Core FDM Engineer

[Miguel.Angel.Benitez@ford.com](mailto:Miguel.Angel.Benitez@ford.com)

Cellphone: +52-55-7919-8138

---

**From:** [oscgarcia@borgwarner.com](mailto:oscgarcia@borgwarner.com) <[oscgarcia@borgwarner.com](mailto:oscgarcia@borgwarner.com)>

**Sent:** Monday, January 9, 2023 16:23

**To:** Pollitt, Dwayne (D.) <[dpollitt@ford.com](mailto:dpollitt@ford.com)>

**Cc:** Kaparthi, Prashanth (P.) <[pkaparth@ford.com](mailto:pkaparth@ford.com)>; Dreier, Paul (P.) <[PDREIER@ford.com](mailto:PDREIER@ford.com)>; Sanchez, David (D.S.) <[dsanch21@ford.com](mailto:dsanch21@ford.com)>; Meng, Julie (Z.) <[jmeng@ford.com](mailto:jmeng@ford.com)>; arascon@borgwarner.com; [bvalles@borgwarner.com](mailto:bvalles@borgwarner.com); [anterrazas@borgwarner.com](mailto:anterrazas@borgwarner.com); [sespinoza@borgwarner.com](mailto:sespinoza@borgwarner.com); [r Herrera@borgwarner.com](mailto:r Herrera@borgwarner.com); [hemendoza@borgwarner.com](mailto:hemendoza@borgwarner.com); Avila, Erick O (Juarez-TC) <[erivila@borgwarner.com](mailto:erivila@borgwarner.com)>; Benitez T, Miguel Angel (.) <[m benit25@ford.com](mailto:m benit25@ford.com)>; Chmielewski, Thad (T.A.) <[TCHMIELE@ford.com](mailto:TCHMIELE@ford.com)>; DePotter, Valerie (V. S.) <[vdepotte@ford.com](mailto:vdepotte@ford.com)>; Dokas, David (D.M.) <[ddokas@ford.com](mailto:ddokas@ford.com)>; [jurenteria@borgwarner.com](mailto:jurenteria@borgwarner.com); Hosana, Stephen (S.) <[SHOSANA@ford.com](mailto:SHOSANA@ford.com)>; Bolton, Al (A.F.) <[abolton@ford.com](mailto:abolton@ford.com)>; Ognjanovski Jr, Rob (R.G.) <[rognjano@ford.com](mailto:rognjano@ford.com)>; Murray, Robert (R.A.) <[rmurra33@ford.com](mailto:rmurra33@ford.com)>; Dreier, Paul (P.) <[PDREIER@ford.com](mailto:PDREIER@ford.com)>

**Subject:** RE: Alerts for new Jet pump orifice size - crank no start issue

Hi Duane, Good Day and Happy New Year!

I have checked with Julio and he is checking some details with the FH Test Lab – he will respond to you shortly.

Best Regards

**Oscar G. Garcia**

Product Engineering Supervisor

Mexico Technical Center – Fuel Handling Product Line



Shipping Address:

BorgWarner Mexico Technical Center

12425 Mercantile Ave.

Ramp A, Docks 1-2

El Paso, TX. USA - 79928

+1.915.727.2303 US Mobile

+1.915.612.9725 US Office

[oscgarcia@borgwarner.com](mailto:oscgarcia@borgwarner.com)

---

**From:** Pollitt, Dwayne (D.) [<mailto:dpollitt@ford.com>]

**Sent:** Monday, January 9, 2023 12:51 PM

**To:** Benitez T, Miguel Angel (.) <[m benit25@ford.com](mailto:m benit25@ford.com)>; Chmielewski, Thad (T.A.) <[TCHMIELE@ford.com](mailto:TCHMIELE@ford.com)>; DePotter, Valerie (V. S.) <[vdepotte@ford.com](mailto:vdepotte@ford.com)>; Dokas, David (D.M.) <[ddokas@ford.com](mailto:ddokas@ford.com)>; Renteria, Julio C (Juarez-TC) <[jurenteria@borgwarner.com](mailto:jurenteria@borgwarner.com)>; Garcia, Oscar G. (Juarez-TC) <[oscgarcia@borgwarner.com](mailto:oscgarcia@borgwarner.com)>; Hosana, Stephen (S.) <[SHOSANA@ford.com](mailto:SHOSANA@ford.com)>; Bolton, Al (A.F.) <[abolton@ford.com](mailto:abolton@ford.com)>; Ognjanovski Jr, Rob (R.G.) <[rognjano@ford.com](mailto:rognjano@ford.com)>; Murray, Robert (R.A.) <[rmurra33@ford.com](mailto:rmurra33@ford.com)>; Dreier, Paul (P.) <[PDREIER@ford.com](mailto:PDREIER@ford.com)>

**Cc:** Kaparthi, Prashanth (P.) <[pkaparth@ford.com](mailto:pkaparth@ford.com)>; Dreier, Paul (P.) <[PDREIER@ford.com](mailto:PDREIER@ford.com)>; Sanchez, David (D.S.) <[dsanch21@ford.com](mailto:dsanch21@ford.com)>; Meng, Julie (Z.) <[jmeng@ford.com](mailto:jmeng@ford.com)>; Rascon, Alejandra Patricia (Juarez-TC) <[arascon@borgwarner.com](mailto:arascon@borgwarner.com)>; Valles, Benjamin (Juarez-TC) <[bvalles@borgwarner.com](mailto:bvalles@borgwarner.com)>; Terrazas, Angel (Chihuahua) <[anterrazas@borgwarner.com](mailto:anterrazas@borgwarner.com)>; Herrera, Roberto (Juarez-TC) <[r Herrera@borgwarner.com](mailto:r Herrera@borgwarner.com)>; Espinoza, Sonia (Juarez-TC) <[sespinoza@borgwarner.com](mailto:sespinoza@borgwarner.com)>; Mendoza, Hector Rene (Juarez-TC) <[hemendoza@borgwarner.com](mailto:hemendoza@borgwarner.com)>; Avila, Erick O (Juarez-TC) <[erivila@borgwarner.com](mailto:erivila@borgwarner.com)>

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION



PE24-019 000019 ES

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION



PE24-019 000020 ES

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION



PE24-019 000021 ES

---

**From:** Chmielewski, Thad (T.A.) <[tchmiele@ford.com](mailto:tchmiele@ford.com)>

**Sent:** Wednesday, December 7, 2022 16:09

**To:** DePotter, Valerie (V. S.) <[vdepotte@ford.com](mailto:vdepotte@ford.com)>; Dokas, David (D.M.) <[ddokas@ford.com](mailto:ddokas@ford.com)>; [jurenteria@borgwarner.com](mailto:jurenteria@borgwarner.com); [oscgarcia@borgwarner.com](mailto:oscgarcia@borgwarner.com); Benitez T, Miguel Angel (.) <[mbenit25@ford.com](mailto:mbenit25@ford.com)>; Pollitt, Dwayne (D.) <[dpollitt@ford.com](mailto:dpollitt@ford.com)>; Hosana, Stephen (S.) <[SHOSANA@ford.com](mailto:SHOSANA@ford.com)>; Bolton, Al (A.F.) <[abolton@ford.com](mailto:abolton@ford.com)>; Ognjanovski Jr, Rob (R.G.) <[rogniano@ford.com](mailto:rogniano@ford.com)>

**Cc:** Kaparathi, Prashanth (P.) <[pkaparth@ford.com](mailto:pkaparth@ford.com)>; Dreier, Paul (P.) <[PDREIER@ford.com](mailto:PDREIER@ford.com)>; Sanchez, David (D.S.) <[dsanch21@ford.com](mailto:dsanch21@ford.com)>; Meng, Julie (Z.) <[jmeng@ford.com](mailto:jmeng@ford.com)>; Murray, Robert (R.A.) <[rmurra33@ford.com](mailto:rmurra33@ford.com)>; [arascon@borgwarner.com](mailto:arascon@borgwarner.com); [bvalles@borgwarner.com](mailto:bvalles@borgwarner.com); [anterrazas@borgwarner.com](mailto:anterrazas@borgwarner.com); [rherera@borgwarner.com](mailto:rherera@borgwarner.com); [sespinoza@borgwarner.com](mailto:sespinoza@borgwarner.com); [hemendoza@borgwarner.com](mailto:hemendoza@borgwarner.com); Avila, Erick O (Juarez-TC) <[eriavila@borgwarner.com](mailto:eriavila@borgwarner.com)>

**Subject:** RE: Alerts for new jet pump orifice size - crank no start issue

Hi Team,

For U725, Alert extended another 90 days  
Expires on April 1<sup>st</sup>

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION



PE24-019 000023 ES

---

**From:** DePotter, Valerie (V. S.) <[vdepotte@ford.com](mailto:vdepotte@ford.com)>

**Sent:** Wednesday, December 07, 2022 8:26 AM

**To:** Dokas, David (D.M.) <[ddokas@ford.com](mailto:ddokas@ford.com)>; Jurenteria <[oscgarcia@borgwarner.com](mailto:oscgarcia@borgwarner.com)>; Benitez T, Miguel Angel (.) <[mbenit25@ford.com](mailto:mbenit25@ford.com)>; Pollitt, Dwayne (D.) <[dpollitt@ford.com](mailto:dpollitt@ford.com)>; Hosana, Stephen (S.) <[SHOSANA@ford.com](mailto:SHOSANA@ford.com)>; Bolton, Al (A.F.) <[abolton@ford.com](mailto:abolton@ford.com)>; Ognjanovski Jr, Rob (R.G.) <[rogjano@ford.com](mailto:rogjano@ford.com)>; Chmielewski, Thad (T.A.) <[TCHMIELE@ford.com](mailto:TCHMIELE@ford.com)>

**Cc:** Kaparathi, Prashanth (P.) <[pkaparth@ford.com](mailto:pkaparth@ford.com)>; Dreier, Paul (P.) <[PDREIER@ford.com](mailto:PDREIER@ford.com)>; Sanchez, David (D.S.) <[dsanch21@ford.com](mailto:dsanch21@ford.com)>; Meng, Julie (Z.) <[jmeng@ford.com](mailto:jmeng@ford.com)>; Murray, Robert (R.A.) <[rmurra33@ford.com](mailto:rmurra33@ford.com)>; arascon <[arascon@borgwarner.com](mailto:arascon@borgwarner.com)>; bvalles <[bvalles@borgwarner.com](mailto:bvalles@borgwarner.com)>; anterrazas <[anterrazas@borgwarner.com](mailto:anterrazas@borgwarner.com)>; rherera <[rherera@borgwarner.com](mailto:rherera@borgwarner.com)>; hemendoza <[hemendoza@borgwarner.com](mailto:hemendoza@borgwarner.com)>; Avila, Erick O (Juarez-TC) <[eriavila@borgwarner.com](mailto:eriavila@borgwarner.com)>

**Subject:** RE: Alerts for new jet pump orifice size - crank no start issue

+ Thad Chmielewski, Rob O.

Valerie DePotter

Ford Motor Company

Fuel Systems Engineering

[vdepotte@ford.com](mailto:vdepotte@ford.com) (313) 805-5802

---

**From:** Dokas, David (D.M.) <[ddokas@ford.com](mailto:ddokas@ford.com)>

**Sent:** Wednesday, December 7, 2022 7:04 AM

**To:** [jurenteria@borgwarner.com](mailto:jurenteria@borgwarner.com); [oscgarcia@borgwarner.com](mailto:oscgarcia@borgwarner.com); Benitez T, Miguel Angel (.) <[mbenit25@ford.com](mailto:mbenit25@ford.com)>; Pollitt, Dwayne (D.) <[dpollitt@ford.com](mailto:dpollitt@ford.com)>; Hosana, Stephen (S.) <[SHOSANA@ford.com](mailto:SHOSANA@ford.com)>; Bolton, Al (A.F.) <[abolton@ford.com](mailto:abolton@ford.com)>

**Cc:** Kaparathi, Prashanth (P.) <[pkaparth@ford.com](mailto:pkaparth@ford.com)>; Dreier, Paul (P.) <[PDREIER@ford.com](mailto:PDREIER@ford.com)>; Sanchez, David (D.S.) <[dsanch21@ford.com](mailto:dsanch21@ford.com)>; Meng, Julie (Z.) <[jmeng@ford.com](mailto:jmeng@ford.com)>; Murray, Robert (R.A.) <[rmurra33@ford.com](mailto:rmurra33@ford.com)>; DePotter, Valerie (V. S.) <[vdepotte@ford.com](mailto:vdepotte@ford.com)>; arascon <[arascon@borgwarner.com](mailto:arascon@borgwarner.com)>; bvalles <[bvalles@borgwarner.com](mailto:bvalles@borgwarner.com)>; anterrazas <[anterrazas@borgwarner.com](mailto:anterrazas@borgwarner.com)>; rherera <[rherera@borgwarner.com](mailto:rherera@borgwarner.com)>; sespinoza <[sespinoza@borgwarner.com](mailto:sespinoza@borgwarner.com)>; Avila, Erick O (Juarez-TC) <[eriavila@borgwarner.com](mailto:eriavila@borgwarner.com)>

**Subject:** RE: Alerts for new jet pump orifice size - crank no start issue

+ Al Bolton

Regards,

Dave Dokas

Technical Specialist – Fuel Delivery Modules and Lines

Ford Motor Company

Office: AEC 3507

Phone: (313) 805-9842

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION



PE24-019 000025 ES

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION



PE24-019 000026 ES

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION



PE24-019 000027 ES

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION



PE24-019 000028 ES

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION



PE24-019 000029 ES

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION



PE24-019 000030 ES

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION



PE24-019 000031 ES

12425 Mercantile Ave.  
Ramp A, Docks 1-2  
El Paso, TX. 79928  
USA

---

**From:** Benitez T, Miguel Angel (.) <[mbenit25@ford.com](mailto:mbenit25@ford.com)>

**Sent:** Wednesday, November 16, 2022 4:47 PM

**To:** Espinoza, Sonia (Juaresz-TC) <[sespinoza@borgwarner.com](mailto:sespinoza@borgwarner.com)>; Pollitt, Dwayne (D.) <[dpollitt@ford.com](mailto:dpollitt@ford.com)>; Dokas, David (D.M.) <[ddokas@ford.com](mailto:ddokas@ford.com)>

**Subject:** RE: FDM crank no-start warranty issue



**EXTERNAL SENDER**

H Sonia — Monday and Wednesday meetings were cancelled, but the timing for the permanent jet pump change was going to be discussed on Monday. Can you please share the timing before the Friday meeting? Thanks in advance.

Thank you. All the best.

Miguel Ángel Benítez Torreblanca

Global Core FDM Engineer

[Miguel.Angel.Benitez@ford.com](mailto:Miguel.Angel.Benitez@ford.com)

Cellphone: +52-55-7919-8138

---

**From:** [sespinoza@borgwarner.com](mailto:sespinoza@borgwarner.com) <[sespinoza@borgwarner.com](mailto:sespinoza@borgwarner.com)>

**Sent:** Tuesday, November 15, 2022 13:57

**To:** Pollitt, Dwayne (D.) <[dpollitt@ford.com](mailto:dpollitt@ford.com)>; Benitez T, Miguel Angel (.) <[mbenit25@ford.com](mailto:mbenit25@ford.com)>; Dokas, David (D.M.) <[ddokas@ford.com](mailto:ddokas@ford.com)>; Martin, David (D.S.) <[dmart127@ford.com](mailto:dmart127@ford.com)>; Castle, Larry (H.L.) <[lcastle@ford.com](mailto:lcastle@ford.com)>; [hemendoza@borgwarner.com](mailto:hemendoza@borgwarner.com); [jporras@borgwarner.com](mailto:jporras@borgwarner.com); [oscgarcia@borgwarner.com](mailto:oscgarcia@borgwarner.com); [rherrera@borgwarner.com](mailto:rherrera@borgwarner.com); [bvalles@borgwarner.com](mailto:bvalles@borgwarner.com); [Obrecht, Gregory \(G.T.\) <gobrecht1@ford.com>](mailto:Obrecht, Gregory (G.T.)<gobrecht1@ford.com>); [Marquez Tapia, Ramon \(RMT.\) <rmarqu46@ford.com>](mailto:Marquez Tapia, Ramon (RMT.)<rmarqu46@ford.com>); [Sanchez, David \(D.S.\) <dsanch21@ford.com>](mailto:Sanchez, David (D.S.)<dsanch21@ford.com>); [letsanchez@borgwarner.com](mailto:letsanchez@borgwarner.com); [Ognjanovski Jr, Rob \(R.G.\) <rognjano@ford.com>](mailto:Ognjanovski Jr, Rob (R.G.)<rognjano@ford.com>); [Bolton, Al \(A.F.\) <abolton@ford.com>](mailto:Bolton, Al (A.F.)<abolton@ford.com>); [Patel, Anup \(A.M.\) <apatel1@ford.com>](mailto:Patel, Anup (A.M.)<apatel1@ford.com>); [Chmielewski, Thad \(T.A.\) <TCHMIELE@ford.com>](mailto:Chmielewski, Thad (T.A.)<TCHMIELE@ford.com>); [Ranspach IV, Paul \(P.M.\) <PRANSPA1@ford.com>](mailto:Ranspach IV, Paul (P.M.)<PRANSPA1@ford.com>); [Ryzyi, Sheila \(S.M.\) <stryzyi@ford.com>](mailto:Ryzyi, Sheila (S.M.)<stryzyi@ford.com>)

**Cc:** Condrion, Brian (B.G.) <[bcondrion@ford.com](mailto:bcondrion@ford.com)>; [anrobes@borgwarner.com](mailto:anrobes@borgwarner.com); [cocarrillo@borgwarner.com](mailto:cocarrillo@borgwarner.com); [Hoskins, Cody \(C.\) <CHOSKI22@ford.com>](mailto:Hoskins, Cody (C.)<CHOSKI22@ford.com>); [Schneidau, Dan \(D.\) <dscshnei6@ford.com>](mailto:Schneidau, Dan (D.)<dscshnei6@ford.com>); [Paddy, Carter \(C.D.\) <CPADDY@ford.com>](mailto:Paddy, Carter (C.D.)<CPADDY@ford.com>); [Pollock, Gee \(G.\) <GPOLLO10@ford.com>](mailto:Pollock, Gee (G.)<GPOLLO10@ford.com>); [gmuniz@borgwarner.com](mailto:gmuniz@borgwarner.com); [Ali, Shaique \(S.\) <SALI4@ford.com>](mailto:Ali, Shaique (S.)<SALI4@ford.com>)

**Subject:** RE: FDM crank no-start warranty issue

---

**WARNING:** This message originated outside of Ford Motor Company. Use caution when opening attachments, clicking links, or responding.

Good afternoon,  
Please find enclosed the 8D file, root cause and escape points updated

Best Regards

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION



PE24-019 000033 ES

Fuel Handling

BorgWarner  
Mexico Technical Center  
Tel: +1 (915) 612 9721  
Cel: +52 (656) 168 3498  
[sonia.espinoza@delphi.com](mailto:sonia.espinoza@delphi.com)  
[sespinoza@borgwarner.com](mailto:sespinoza@borgwarner.com)

Warehouse address:  
12425 Mercantile Ave.  
Ramp A, Docks 1-2  
El Paso, TX. 79928  
USA

---

**From:** Espinoza, Sonia (Juarez-TC)

**Sent:** Wednesday, November 9, 2022 2:40 PM

**To:** 'Pollitt, Dwayne (D.)' <[dpollitt@ford.com](mailto:dpollitt@ford.com)>; 'Benitez T, Miguel Angel (.)' <[mbenit25@ford.com](mailto:mbenit25@ford.com)>; 'Dokas, David (D.M.)' <[ddokas@ford.com](mailto:ddokas@ford.com)>; 'Martin, David (D.S.)' <[dmart127@ford.com](mailto:dmart127@ford.com)>; 'Castle, Larry (H.L.)' <[lcastle@ford.com](mailto:lcastle@ford.com)>; 'Mendoza, Hector Rene (Juarez-TC)' <[hemendoza@borgwarner.com](mailto:hemendoza@borgwarner.com)>; 'Porras, Luis M (Juarez-TC)' <[lporras@borgwarner.com](mailto:lporras@borgwarner.com)>; 'Garcia, Oscar G. (Juarez-TC)' <[oscgarcia@borgwarner.com](mailto:oscgarcia@borgwarner.com)>; Herrera, Roberto (Juarez-TC) <[rherrera@borgwarner.com](mailto:rherrera@borgwarner.com)>; 'Valles, Benjamin (Juarez-TC)' <[bvalles@borgwarner.com](mailto:bvalles@borgwarner.com)>; 'Obrecht, Gregory (G.T.)' <[gobrech1@ford.com](mailto:gobrech1@ford.com)>; 'Marquez Tapia, Ramon (RMT.)' <[rmarqu46@ford.com](mailto:rmarqu46@ford.com)>; 'Sanchez, David (D.S.)' <[dsanch21@ford.com](mailto:dsanch21@ford.com)>; 'Sanchez, Leticia (Juarez-TC)' <[letsanchez@borgwarner.com](mailto:letsanchez@borgwarner.com)>; 'Ognjanovski Jr, Rob (R.G.)' <[rogniano@ford.com](mailto:rogniano@ford.com)>; 'Bolton, Al (A.F.)' <[abolton@ford.com](mailto:abolton@ford.com)>; 'Patel, Anup (A.M.)' <[apatel1@ford.com](mailto:apatel1@ford.com)>; 'Chmielewski, Thad (T.A.)' <[TCHMIELE@ford.com](mailto:TCHMIELE@ford.com)>

**Cc:** 'Condron, Brian (B.G.)' <[bcondron@ford.com](mailto:bcondron@ford.com)>; 'Robles, Angel (Chihuahua)' <[anrobles@borgwarner.com](mailto:anrobles@borgwarner.com)>; 'Carrillo, Conrado (Juarez-TC)' <[cocarrillo@borgwarner.com](mailto:cocarrillo@borgwarner.com)>; 'Hoskins, Cody (C.)' <[CHOSKI22@ford.com](mailto:CHOSKI22@ford.com)>; 'Schneidau, Dan (D.)' <[dschne16@ford.com](mailto:dschne16@ford.com)>; 'Pollock, Gee (G.)' <[GPOLLO10@ford.com](mailto:GPOLLO10@ford.com)>; 'Muniz, Gerardo (Chihuahua)' <[gmuniz@borgwarner.com](mailto:gmuniz@borgwarner.com)>; 'Ali, Shaique (S.)' <[SALI14@ford.com](mailto:SALI14@ford.com)>

**Subject:** RE: FDM crank no-start warranty issue

Good afternoon,  
please find enclosed the Excel file with the open items we discussed today, two open items were closed as discussed in de meeting.

Best Regards

**Sonia Espinoza**  
Product Engineer  
Fuel Handling  
  
BorgWarner  
Mexico Technical Center  
Tel: +1 (915) 612 9721  
Cel: +52 (656) 168 3498  
[sonia.espinoza@delphi.com](mailto:sonia.espinoza@delphi.com)  
[sespinoza@borgwarner.com](mailto:sespinoza@borgwarner.com)

Warehouse address:  
12425 Mercantile Ave.  
Ramp A, Docks 1-2  
El Paso, TX. 79928  
USA

**From:** Espinoza, Sonia (Juarez-TC)

**Sent:** Monday, November 7, 2022 1:12 PM

**To:** Pollitt, Dwayne (D.) <[dpollitt@ford.com](mailto:dpollitt@ford.com)>; Benitez T, Miguel Angel (.) <[mbenit25@ford.com](mailto:mbenit25@ford.com)>; Dokas, David (D.M.) <[ddokas@ford.com](mailto:ddokas@ford.com)>; Martin, David (D.S.) <[dmart127@ford.com](mailto:dmart127@ford.com)>; Castle, Larry (H.L.) <[lcastle@ford.com](mailto:lcastle@ford.com)>; Mendoza, Hector Rene (Juarez-TC) <[hemendoza@borgwarner.com](mailto:hemendoza@borgwarner.com)>; Porras, Luis M (Juarez-TC) <[lporras@borgwarner.com](mailto:lporras@borgwarner.com)>; Garcia, Oscar G. (Juarez-TC) <[oscgarcia@borgwarner.com](mailto:oscgarcia@borgwarner.com)>; Herrera, Roberto (Juarez-TC) <[rherrera@borgwarner.com](mailto:rherrera@borgwarner.com)>; Valles, Benjamin (Juarez-TC) <[bvalles@borgwarner.com](mailto:bvalles@borgwarner.com)>; Obrecht, Gregory (G.T.) <[gobrech1@ford.com](mailto:gobrech1@ford.com)>; Marquez Tapia, Ramon (RMT.) <[rmarqu46@ford.com](mailto:rmarqu46@ford.com)>; Sanchez, David (D.S.) <[dsanchz1@ford.com](mailto:dsanchz1@ford.com)>; Sanchez, Leticia (Juarez-TC) <[letsanchez@borgwarner.com](mailto:letsanchez@borgwarner.com)>; Ognjanovski Jr, Rob (R.G.) <[rognjano@ford.com](mailto:rognjano@ford.com)>; Bolton, Al (A.F.) <[abolton@ford.com](mailto:abolton@ford.com)>; Patel, Anup (A.M.) <[apatel1@ford.com](mailto:apatel1@ford.com)>; Chmielewski, Thad (T.A.) <[TCHMIELE@ford.com](mailto:TCHMIELE@ford.com)>

**Cc:** Condrion, Brian (B.G.) <[bcondrion@ford.com](mailto:bcondrion@ford.com)>; Schneidau, Dan (D.) <[dschnei6@ford.com](mailto:dschnei6@ford.com)>; Robles, Angel (Chihuahua) <[anrobles@borgwarner.com](mailto:anrobles@borgwarner.com)>; Carrillo, Conrado (Juarez-TC) <[cocarrillo@borgwarner.com](mailto:cocarrillo@borgwarner.com)>; Hoskins, Cody (C.) <[CHOSK122@ford.com](mailto:CHOSK122@ford.com)>; Schneidau, Dan (D.) <[dschnei6@ford.com](mailto:dschnei6@ford.com)>; Paddy, Carter (C.D.) <[CPADDY@ford.com](mailto:CPADDY@ford.com)>; Pollock, Gee (G.) <[GPOLLO10@ford.com](mailto:GPOLLO10@ford.com)>; Muniz, Gerardo (Chihuahua) <[gmuniz@borgwarner.com](mailto:gmuniz@borgwarner.com)>; Ali, Shaique (S.) <[SALI4@ford.com](mailto:SALI4@ford.com)>

**Subject:** RE: FDM crank no-start warranty issue

Good afternoon,  
please find the latest update for the Warranties Data excel file.

Best Regards

**Sonia Espinoza**

Product Engineer  
Fuel Handling

BorgWarner  
Mexico Technical Center  
Tel: +1 (915) 612 9721  
Cel: +52 (656) 168 3498

[sonia.espinoza@delphi.com](mailto:sonia.espinoza@delphi.com)  
[sespinoza@borgwarner.com](mailto:sespinoza@borgwarner.com)

Warehouse address:  
12425 Mercantile Ave.  
Ramp A, Docks 1-2  
El Paso, TX. 79928  
USA



ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION



PE24-019 000037 ES

Chmielewski, Thad (T.A.) <[TCHMIELE@ford.com](mailto:TCHMIELE@ford.com)>

**Cc:** Woodring, Christopher (C.A.) <[cwoodrin@ford.com](mailto:cwoodrin@ford.com)>; Condron, Brian (B.G.) <[bcondron@ford.com](mailto:bcondron@ford.com)>; Robles, Angel (Chihuahua) <[anrobles@borgwarner.com](mailto:anrobles@borgwarner.com)>; Carrillo, Conrado (Juarez-TC) <[cocarrillo@borgwarner.com](mailto:cocarrillo@borgwarner.com)>; Hoskins, Cody (C.) <[CHOSK122@ford.com](mailto:CHOSK122@ford.com)>; Schneidau, Dan (D.) <[dschnei6@ford.com](mailto:dschnei6@ford.com)>; Paddy, Carter (C.D.) <[CPADDY@ford.com](mailto:CPADDY@ford.com)>; Pollock, Gee (G.) <[GPOLLO10@ford.com](mailto:GPOLLO10@ford.com)>; Muniz, Gerardo (Chihuahua) <[gmuniz@borgwarner.com](mailto:gmuniz@borgwarner.com)>; Ali, Shaique (S.) <[SALI4@ford.com](mailto:SALI4@ford.com)>

**Subject:** RE: FDM crank no-start warranty issue

Good afternoon,

please find enclosed the Excel file with the open items we discussed today and the files for the presentations.

- FLI updated file

Best Regards

**Sonia Espinoza**

Product Engineer  
Fuel Handling

BorgWarner

Mexico Technical Center  
Tel: +1 (915) 612 9721

Cel: +52 (656) 168 3498

[sonia.espinoza@delphi.com](mailto:sonia.espinoza@delphi.com)

[sespinoza@borgwarner.com](mailto:sespinoza@borgwarner.com)

Warehouse address:

12425 Mercantile Ave.

Ramp A, Docks 1-2

El Paso, TX. 79928

USA

---

**From:** Espinoza, Sonia (Juarez-TC)

**Sent:** Wednesday, October 26, 2022 5:44 PM

**To:** Pollitt, Dwayne (D.) <[dpollitt@ford.com](mailto:dpollitt@ford.com)>; Benitez T, Miguel Angel (.) <[mbenit25@ford.com](mailto:mbenit25@ford.com)>; Dokas, David (D.M.) <[ddokas@ford.com](mailto:ddokas@ford.com)>; Martin, David (D.S.) <[dmart127@ford.com](mailto:dmart127@ford.com)>; Castle, Larry (H.L.) <[lcastle@ford.com](mailto:lcastle@ford.com)>; Cooper, Scott (S.D.) <[scooper6@ford.com](mailto:scooper6@ford.com)>; Cruz, Sara (Juarez-TC) <[sacruz@borgwarner.com](mailto:sacruz@borgwarner.com)>; Mendoza, Hector Rene (Juarez-TC) <[hemendoza@borgwarner.com](mailto:hemendoza@borgwarner.com)>; Porras, Luis M (Juarez-TC) <[lporras@borgwarner.com](mailto:lporras@borgwarner.com)>; Garcia, Oscar G. (Juarez-TC) <[oscgarcia@borgwarner.com](mailto:oscgarcia@borgwarner.com)>; Herrera, Roberto (Juarez-TC) <[rherrera@borgwarner.com](mailto:rherrera@borgwarner.com)>; Valles, Benjamin (Juarez-TC) <[bvalles@borgwarner.com](mailto:bvalles@borgwarner.com)>; Obrecht, Gregory (G.T.) <[gobrech1@ford.com](mailto:gobrech1@ford.com)>; Marquez Tapia, Ramon (RMT) <[rmarqu46@ford.com](mailto:rmarqu46@ford.com)>; Sanchez, David (D.S.) <[dsanch21@ford.com](mailto:dsanch21@ford.com)>; Sanchez, Leticia (Juarez-TC) <[letsanchez@borgwarner.com](mailto:letsanchez@borgwarner.com)>; Pearce, Randy (.) <[rpearce@ford.com](mailto:rpearce@ford.com)>; Ognjanovski Jr, Rob (R.G.) <[rognjano@ford.com](mailto:rognjano@ford.com)>; Bolton, Al (A.F.) <[abolton@ford.com](mailto:abolton@ford.com)>; Patel, Anup (A.M.) <[apatel1@ford.com](mailto:apatel1@ford.com)>;

Chmielewski, Thad (T.A.) <[TCHMIELE@ford.com](mailto:TCHMIELE@ford.com)>

**Cc:** Woodring, Christopher (C.A.) <[cwoodrin@ford.com](mailto:cwoodrin@ford.com)>; Condron, Brian (B.G.) <[bcondron@ford.com](mailto:bcondron@ford.com)>; Robles, Angel (Chihuahua) <[anrobles@borgwarner.com](mailto:anrobles@borgwarner.com)>; Carrillo, Conrado (Juarez-TC) <[cocarrillo@borgwarner.com](mailto:cocarrillo@borgwarner.com)>; Hoskins, Cody (C.) <[CHOSK122@ford.com](mailto:CHOSK122@ford.com)>; Schneidau, Dan (D.) <[dschnei6@ford.com](mailto:dschnei6@ford.com)>; Paddy, Carter (C.D.) <[CPADDY@ford.com](mailto:CPADDY@ford.com)>; Pollock, Gee (G.) <[GPOLLO10@ford.com](mailto:GPOLLO10@ford.com)>; Muniz, Gerardo (Chihuahua) <[gmuniz@borgwarner.com](mailto:gmuniz@borgwarner.com)>; Ali, Shaique (S.) <[SALI4@ford.com](mailto:SALI4@ford.com)>

**Subject:** RE: FDM crank no-start warranty issue

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION



PE24-019 000039 ES

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION



PE24-019 000040 ES

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION



PE24-019 000041 ES

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION



PE24-019 000042 ES

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION



PE24-019 000043 ES

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION



PE24-019 000044 ES

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION



PE24-019 000045 ES

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION



PE24-019 000046 ES

<cocarrillo@borgwarner.com>; Hoskins, Cody (C.) <CHOSKI22@ford.com>; Schneidau, Dan (D.) <dschnei6@ford.com>; Paddy, Carter (C.D.) <CPADDY@ford.com>; Pollock, Gee (G.) <GPOLLO10@ford.com>; Muniz, Gerardo (Chihuahua) <gmuniz@borgwarner.com>; Ali, Shaique (S.) <SALI4@ford.com>  
**Subject:** RE: FDM crank no-start warranty issue

Good afternoon,  
please find enclosed the Excel file with the open items we discussed today and the files for the presentations.

Best Regards

**Sonia Espinoza**  
Product Engineer  
Fuel Handling

BorgWarner  
Mexico Technical Center  
Tel: +1 (915) 612 9721  
Cel: +52 (656) 168 3498  
[sonia.espinoza@delphi.com](mailto:sonia.espinoza@delphi.com)  
[sespinoza@borgwarner.com](mailto:sespinoza@borgwarner.com)

Warehouse address:  
12425 Mercantile Ave.  
Ramp A, Docks 1-2  
El Paso, TX. 79928  
USA

---

**From:** Espinoza, Sonia (Juarez-TC)

**Sent:** Wednesday, October 5, 2022 2:37 PM

**To:** Pollitt, Dwayne (D.) <dpollitt@ford.com>; Benitez T, Miguel Angel (.) <mbenit25@ford.com>; Dokas, David (D.M.) <ddokas@ford.com>; Martin, David (D.S.) <dmart127@ford.com>; Castle, Larry (H.L.) <lcastle@ford.com>; Cooper, Scott (S.D.) <scooper6@ford.com>; Cruz, Sara (Juarez-TC) <sacruz@borgwarner.com>; Mendoza, Hector Rene (Juarez-TC) <hemendoza@borgwarner.com>; Porras, Luis M (Juarez-TC) <lporras@borgwarner.com>; Garcia, Oscar G. (Juarez-TC) <oscgarcia@borgwarner.com>; Herrera, Roberto (Juarez-TC) <rherrera@borgwarner.com>; Valles, Benjamin (Juarez-TC) <bvalles@borgwarner.com>; Obrecht, Gregory (G.T.) <gobrech1@ford.com>; Marquez Tapia, Ramon (RMT.) <rmarqu44@ford.com>; Sanchez, David (D.S.) <dsanch21@ford.com>; Sanchez, Leticia (Juarez-TC) <letsanchez@borgwarner.com>; Pearce, Randy (.) <rpearce@ford.com>; Bolton, Al (A.F.) <abolton@ford.com>; Patel, Anup (A.M.) <apatel1@ford.com>; Chmielewski, Thad (T.A.) <TCHMIELE@ford.com>  
**Cc:** Woodring, Christopher (C.A.) <cwoodrin@ford.com>; Condron, Brian (B.G.) <bcondron@ford.com>; Robles, Angel (Chihuahua) <anrobles@borgwarner.com>; Carrillo, Conrado (Juarez-TC) <cocarrillo@borgwarner.com>; Hoskins, Cody (C.) <CHOSKI22@ford.com>; Schneidau, Dan (D.) <dschnei6@ford.com>; Paddy, Carter (C.D.) <CPADDY@ford.com>; Pollock, Gee (G.) <GPOLLO10@ford.com>; Muniz, Gerardo (Chihuahua) <gmuniz@borgwarner.com>; Ali, Shaique (S.) <SALI4@ford.com>  
**Subject:** RE: FDM crank no-start warranty issue

Good afternoon,  
please find enclosed the Excel file with the open items we discussed today and the files for the presentations.

35



Best Regards

**Sonia Espinoza**  
Product Engineer  
Fuel Handling

BorgWarner  
Mexico Technical Center  
Tel: +1 (915) 612 9721  
Cel: +52 (656) 168 3498  
[sonia.espinoza@delphi.com](mailto:sonia.espinoza@delphi.com)  
[sespinoza@borgwarner.com](mailto:sespinoza@borgwarner.com)

Warehouse address:  
12425 Mercantile Ave.  
Ramp A, Docks 1-2  
El Paso, TX. 79928  
USA

**From:** Espinoza, Sonia (Juarez-TC)

**Sent:** Monday, October 3, 2022 3:32 PM

**To:** Pollitt, Dwayne (D.) <[dpollitt@ford.com](mailto:dpollitt@ford.com)>; Benitez T, Miguel Angel (.) <[mbenit25@ford.com](mailto:mbenit25@ford.com)>; Dokas, David (D.M.) <[ddokas@ford.com](mailto:ddokas@ford.com)>; Martin, David (D.S.) <[dmart127@ford.com](mailto:dmart127@ford.com)>; Castle, Larry (H.L.) <[lcastle@ford.com](mailto:lcastle@ford.com)>; Cooper, Scott (S.D.) <[scooper6@ford.com](mailto:scooper6@ford.com)>; Cruz, Sara (Juarez-TC) <[sacruz@borgwarner.com](mailto:sacruz@borgwarner.com)>; Mendoza, Hector Rene (Juarez-TC) <[hemendoza@borgwarner.com](mailto:hemendoza@borgwarner.com)>; Porras, Luis M (Juarez-TC) <[lporras@borgwarner.com](mailto:lporras@borgwarner.com)>; Garcia, Oscar G. (Juarez-TC) <[oscgarcia@borgwarner.com](mailto:oscgarcia@borgwarner.com)>; Herrera, Roberto (Juarez-TC) <[rherrera@borgwarner.com](mailto:rherrera@borgwarner.com)>; Valles, Benjamin (Juarez-TC) <[bvalles@borgwarner.com](mailto:bvalles@borgwarner.com)>; Obrecht, Gregory (G.T.) <[gobrech1@ford.com](mailto:gobrech1@ford.com)>; Marquez Tapia, Ramon (RMT.) <[rmarqu46@ford.com](mailto:rmarqu46@ford.com)>; Sanchez, David (D.S.) <[dsanch21@ford.com](mailto:dsanch21@ford.com)>; Sanchez, Leticia (Juarez-TC) <[letsanchez@borgwarner.com](mailto:letsanchez@borgwarner.com)>; Pearce, Randy (.) <[rpearce@ford.com](mailto:rpearce@ford.com)>; Bolton, Al (A.F.) <[abolton@ford.com](mailto:abolton@ford.com)>; Patel, Anup (A.M.) <[apatel1@ford.com](mailto:apatel1@ford.com)>; Chmielewski, Thad (T.A.) <[TCHMIELE@ford.com](mailto:TCHMIELE@ford.com)>  
**Cc:** Woodring, Christopher (C.A.) <[cwoodrin@ford.com](mailto:cwoodrin@ford.com)>; Condron, Brian (B.G.) <[bcondron@ford.com](mailto:bcondron@ford.com)>; Robles, Angel (Chihuahua) <[anrobles@borgwarner.com](mailto:anrobles@borgwarner.com)>; Carrillo, Conrado (Juarez-TC) <[ccarrillo@borgwarner.com](mailto:ccarrillo@borgwarner.com)>; Hoskins, Cody (C.) <[CHOSKI22@ford.com](mailto:CHOSKI22@ford.com)>; Schneidau, Dan (D.) <[dschnei6@ford.com](mailto:dschnei6@ford.com)>; Paddy, Carter (C.D.) <[CPADDY@ford.com](mailto:CPADDY@ford.com)>; Pollock, Gee (G.) <[GPOLLO10@ford.com](mailto:GPOLLO10@ford.com)>; Muniz, Gerardo (Chihuahua) <[gmuniz@borgwarner.com](mailto:gmuniz@borgwarner.com)>; Ali, Shaique (S.) <[SALI14@ford.com](mailto:SALI14@ford.com)>  
**Subject:** RE: FDM crank no-start warranty issue

Good afternoon,  
please find enclosed the Excel file with the open items we discussed today the files for the presentations and 8D file updated

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION



PE24-019 000049 ES

ENTIRE PAGE CONFIDENTIAL BUSINESS INFORMATION



PE24-019 000050 ES