

PE24-024 KEYWORD CRITERIA

Model Year(s)	Vehicle Family (ies)		
2019-2023	Jeep Wrangler (JL) / Gladiator (JT)		
Column 1	Column 2	Column 3	
fire		misfire	
flame		mis-fire	
smoke		miss-fire	
odor		missfire	
arcing		clutch	
burning		trans	
melting		transmission	
	And		But Not
		burn hole	
		exhaust	
		EVAP	
		ESIM	
		Smoke test	
		95B	
		B9A	

Categorization Criteria

Responsive: Defect A - Fire alleged in the power steering pump or immediate area of the power steering pump

Defect B - Fire alleged under hood that occurred with the engine OFF

Maybe Responsive: Defect A - Fire alleged under hood, right side of vehicle

Defect B - Fire alleged under hood but does not state specifically where under hood OR Fire alleged somewhere on vehicle but location is not identified

Not Responsive: Does not allege fire or fire allegation is not under hood OR Fire allegation is under hood but narrative clearly states engine was running and fire was not in the vicinity of the power steering pump OR Fire allegation is related to Recall 24V720 or Recall 23V787