

REPLACE TIMING COVER GASKETS, TIMING COVER IS LEAKING OIL AS WELL AS CRANK SEAL, NEED TO REMOVE TIMING COVER AND RESEAL.

RESEALED TIMING COVER GASKET. VERIFIED NO LEAKS PRESENT AT THIS TIME. REPAIR COMPLETE

Claim Number: N/A
Comeback Line Flag : Y
Comeback RO Number : [REDACTED]
Technician ID : 100018
Technician Name : RYAN FOX
Tech Remark

:
N/A
Service Payment Type : W
Dealer Ops Code : 14DOZZ09101504
Dealer Ops Code Desc : TIMING COVER GSKT

REPLACED VALVE COVER GASKET, VERIFIED NO LEAK PRESENT AT THIS TIME. REPAIR COMPLETED

Claim Number: N/A
Comeback Line Flag : Y
Comeback RO Number : [REDACTED]
Technician ID : 100018
Technician Name : RYAN FOX
Tech Remark

:
N/A
Service Payment Type : W
Dealer Ops Code : 02DOZDIAG1
Dealer Ops Code Desc : GENERAL CONCERN 1

REPLACED BALANCER VEHICLE OPERATING AS DESIGNED AT THIS TIME.

Claim Number: N/A
Comeback Line Flag : Y
Comeback RO Number : [REDACTED]
Technician ID : 100018
Technician Name : RYAN FOX
Tech Remark

:
N/A
Service Payment Type : W
Dealer Ops Code : 02DOZDIAG4
Dealer Ops Code Desc : GENERAL CONCERN 4

