

**Parts Change Log**

**NHTSA Inquiry RQ24-003**

Part #1 - Jumper Line								Service Parts - Disposition						
Version	Model Year	Engineering Part Number	Date Part Incorporated into Vehicle Production	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service	Are Parts At This Level Interchangeable with the Previous Level(s)? Y/N	Disposition of Parts Upon Removal (Scrap / Consume / Rework)	Actions Planned in the Next 120 Days
1	2021, 2022	4C24-3F524-GA	Jan 10 2014	Jun 21 2021	Update power steering quick connect nut component part to F33C-3F565-BB in place of F33C-3F656-BA.	Unknown	Yes 2014, 2015, 2016, 2017, 2018, 2019, 2020, 2021, all Stripped Chassis and Cutaway.	4C2Z-3A719-A	Feb 27 2014	N/A	Jun 21 2021	N	Scrap	N/A
1	2022	4C24-3F524-GB	Jun 21 2021	Oct 26 2022	Remove 90° fitting connector and replace it with rolled end form, re-route of line for ease assemble.	Address disconnection of pressure line.	Yes 2022, 2023, 2024, all Stripped Chassis and Cutaway.	4C2Z-3A719-B	Jun 21 2021	22S08	Oct 26 2022	N	Consume	N/A
1	2024	4C24-3F524-GC	Oct 26 2022	N/A	Increase torque in quick connect of jumper lines to 110Nm to improve teflon ring sealing.	Torque increase to improve teflon ring robutsness.	Yes 2022, 2023, 2024, all Stripped Chassis and Cutaway.	4C2Z-3A719-C	Oct 26 2022	N/A	N/A	Y	N/A	N/A

Part #2 - Power Steering Line -								Service Parts - Disposition						
Version	Model Year	Engineering Part Number	Date Part Incorporated into Vehicle Production	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service	Are Parts At This Level Interchangeable with the Previous Level(s)? Y/N	Disposition of Parts Upon Removal (Scrap / Consume / Rework)	Actions Planned in the Next 120 Days
1	2021, 2022	LC24-3F523-AD	July 09 2019	Jun 21 2021	Slight re-route to power steering line to increase clearance to front end accessory drive pulley.	Increase clearance to fead pulley and allow easier installation of belt.	No	LC2Z-3A717-A	Jul 09 2019	N/A	Jun 21 2021	N	Scrap	N/A
1	2022	LC24-3F523-AE	Jun 21 2021	Oct 17 2021	Remove 90° fitting connector with rolled end form connector and re-route for ease assembly and avoid side load.	Address disconnect of pressure line from quick connect.	The part is compatible if jumper line is replaced as well (4C24-3F524-GB/GC) 2021, 2022 Cutaway.	LC2Z-3A717-C	Jun 21 2021	22S08	Oct 17 2021	N	Consume	N/A
1	2024	RC24-3F523-AA	Oct 17 2021	N/A	Add teflon supporting ring on pressure line pump interface.	Add teflon supporting ring to improve O-ring sealing robutsness.	The part is compatible if jumper line is replaced as well (4C24-3F524-GB/GC) 2021, 2022 Cutaway.	RC2Z-3A717-A	Oct 17 2021	N/A	N/A	Y	N/A	N/A

Part #3 - Power Steering Line								Service Parts - Disposition						
Version	Model Year	Engineering Part Number	Date Part Incorporated into Vehicle Production	Date Part Removed from Vehicle Production	Description of the Change	Reason for the Change	Is the Part Interchangeable with Other Models and/or Model Years? If So, Provide Details	Service Part Number	Date Part Released for Service	TSB Number Detailing Change	Date Part Removed from Service	Are Parts At This Level Interchangeable with the Previous Level(s)? Y/N	Disposition of Parts Upon Removal (Scrap / Consume / Rework)	Actions Planned in the Next 120 Days
2	2021, 2022	LC24-3F523-BC	July 09 2019	Jun 21 2021	Slight re-route to power steering line to increase clearance to front end accessory drive pulley.	Increase clearance to fead pulley and allow easier installation of belt.	No	LC2Z-3A717-B	Jul 09 2019	N/A	Jun 21 201	N	Scrap	N/A
2	2022	LC24-3F523-BD	Jun 21 2021	Oct 17 2021	Remove 90° fitting connector with rolled end form connector and re-route for ease assembly and avoid side load.	Address disconnect of pressure line from quick connect.	The part is compatible if jumper line is replaced as well (4C24-3F524-GB/GC) 2021, 2022 Cutaway.	LC2Z-3A717-D	Jun 21 2021	22S08	Oct 17 2021	N	Consume	N/A
2	2024	RC24-3F523-BA	Oct 17 2021	N/A	Add teflon supporting ring on pressure line pump interface.	Add teflon supporting ring to improve O-ring sealing robutsness.	The part is compatible if jumper line is replaced as well (4C24-3F524-GB/GC) 2021, 2022 Cutaway.	RC2Z-3A717-B	Oct 17 2021	N/A	N/A	Y	N/A	N/A