


Loss of CAN seen in durability testing

INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552 (B) (6)

Part 1 – Clip missing on Transmission Harness

INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552 (B) (6)



Missing Clip Location



Assessment Summary




Executive Summary: Missing attachment clip allowed harness to contact stud.




Part 2 - ORC Takeout Damage

INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552 (B) (6)

Damage Location




Occupant Restraint
Module (Located
under Center Console)



Wiring near ORC
was damaged.

INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552 (B) (6)

Area Overview



Part 3- Harness contact with Hardtop bolts

INFORMATION REDACTED PURSUANT TO THE FREEDOM OF INFORMATION ACT (FOIA), 5 U.S.C. 552 (B) (6)

