


Loss of CAN seen in durability testing



Part 1 – Clip missing on Transmission Harness

Missing Clip Location




Assessment Summary

Executive Summary: Missing attachment clip allowed harness to contact stud.




Part 2 - ORC Takeout Damage

Damage Location



Occupant Restraint
Module (Located
under Center Console)



Wiring near ORC
was damaged.

Area Overview

