

**From:** Aguilar Ruelas, Eduardo (EAAR.) [eaguil19@ford.com]  
**Sent:** 5/24/2024 11:47:41 PM  
**To:** Clark, Karl (K.C.) [kclark4@ford.com]; Romero Furlong, Sandra Ale (S.) [sromerof@ford.com]; Griffin, Chad (E.) [cgriff16@ford.com]; Hinman, Beth (B.) [bhinman2@ford.com]; Hughes, Evan (E.R.) [ehughe70@ford.com]; Tyda, Ryan (R.) [rtyda@ford.com]  
**CC:** Swanson, Bruce (.) [bswan3@ford.com]; Diwakar, Sujatha (S.) [sdiwakar@ford.com]; McIntyre, Peter (P.) [pmcinty1@ford.com]; Vaddadi, Vinay (V.) [vvaddadi@ford.com]; Sangameswaran, Sangeetha (S.) [ssangame@ford.com]; Mceachern, Matthew (M.) [mmceach6@ford.com]; West, Devin (D.) [dwest90@ford.com]; Polsinelli, Antonietta (A.) [abravo1@ford.com]; Pratt, David (D.S.) [dpratt20@ford.com]; West, Devin (D.) [dwest90@ford.com]; Gill, Balwinder (B.K.) [bgill51@ford.com]; Balzer, Stacy (S.L.) [sbalzer1@ford.com]; Dorony, Kenneth (K.R.) [kdorony@ford.com]  
**Subject:** RE: 24S24 Missing Certification -- Plan and Timing  
**Attachments:** P758-2022\_PCM-7E0.xlsx

Hello team, our tool, now named IVS Verification Tool, can be used in almost all modules except for the APIM, which is one of the exceptions. We use this tool to verify if all the sample VINs in the report 03.1.1 from the Givis Data Warehouse Reporting System are qualifying for a service action before sending the service action for validation. Regarding the PCM for the P758 22MY, I found that there are 2 service actions that impact this ECU program and model year, as well as some VINs that are not qualifying for any service action. You would need to check if these VINs are at the latest level and therefore not qualifying for a service action, or if they are not being covered. I am attaching the report for you to review and see if it is useful for you.

Vehicle Program: P758 / 2022. Model: UNKNOWN. Node: 7E0. Module: N/D. Total Vehicles: 80,106. Total Collections: 66

GIVIS Data up to: 05/23/2024

| Total Vehicles | Assn  | Vehicle Sample | Strategy             | Image | Hardware | Core Assembly        | Assembly               | Calibration | Config | Source | Warning | Quality | ID | F113 Derived    |
|----------------|-------|----------------|----------------------|-------|----------|----------------------|------------------------|-------------|--------|--------|---------|---------|----|-----------------|
| 8,395          | 28835 |                | F188:NZ6A-14C204-2D  | N/D   | N/D      | F111:L V4A-12B884-CA | F113:L X6A-12A650-BBB  | N/D         | N/D    | -      | -       | NO      | -  | NZ5A-12A650-ZF  |
| 3,451          | 28835 |                | F188:NZ6A-14C204-2E  | N/D   | N/D      | F111:L V4A-12B884-CA | F113:L X6A-12A650-BBB  | N/D         | N/D    | -      | -       | NO      | -  | NZ5A-12A650-ZF  |
| 1,651          | 28835 |                | F188:NZ6A-14C204-AAD | N/D   | N/D      | F111:L V4A-12B884-CA | F113:L X6A-12A650-BBB  | N/D         | N/D    | -      | -       | NO      | -  | NZ5A-12A650-AAF |
| 1,498          | 28835 |                | F188:NZ6A-14C204-FJ  | N/D   | N/D      | F111:L V4A-12B884-CA | F113:L X6A-12A650-BBB  | N/D         | N/D    | -      | -       | NO      | -  | NZ5A-12A650-ZF  |
| 627            | 28835 |                | F188:NZ6A-14C204-2C  | N/D   | N/D      | F111:L V4A-12B884-CA | F113:L X6A-12A650-BBB  | N/D         | N/D    | -      | -       | NO      | -  | NZ5A-12A650-ZF  |
| 496            | 28835 |                | F188:NZ6A-14C204-AAE | N/D   | N/D      | F111:L V4A-12B884-CA | F113:L X6A-12A650-BBB  | N/D         | N/D    | -      | -       | NO      | -  | NZ5A-12A650-AAF |
| 211            | 28835 |                | F188:NZ6A-14C204-ZB  | N/D   | N/D      | F111:L V4A-12B884-CA | F113:L X6A-12A650-BBB  | N/D         | N/D    | -      | -       | NO      | -  | NZ5A-12A650-ZF  |
| 7              | 50908 |                | F188:NZ6A-14C204-JB  | N/D   | N/D      | F111:M1PA-12B884-AA  | F113:M1PA-12A650-DA    | N/D         | N/D    | -      | -       | NO      | -  | NZ5A-12A650-JE  |
| 5              | 185   |                | F188:NZ6A-14C204-AAD | N/D   | N/D      | F111:L V4A-12B884-CA | F113:L V4Z-12A650-CBNP | N/D         | N/D    | -      | -       | NO      | -  | NZ5A-12A650-AAF |
| 4              | 185   |                | F188:NZ6A-14C204-FK  | N/D   | N/D      | F111:L V4A-12B884-CA | F113:L V4Z-12A650-CBNP | N/D         | N/D    | -      | -       | NO      | -  | NZ5A-12A650-ZF  |
| 4              | 28835 |                | F188:NZ6A-14C204-FE  | N/D   | N/D      | F111:L V4A-12B884-CA | F113:L X6A-12A650-BBB  | N/D         | N/D    | -      | -       | NO      | -  | NZ5A-12A650-ZF  |
| 1              | 1     |                | F188:NZ6A-14C204-ZE  | N/D   | N/D      | F111:L V4A-12B884-CA | F113:SVL V4A-12A650-CB | N/D         | N/D    | -      | -       | NO      | -  | NZ5A-12A650-ZF  |

Best regards | Mit freundlichen Grüßen

**Eduardo Aguilar - IVS & VADR Technical Leader**

✉ [eaguil19@ford.com](mailto:eaguil19@ford.com)



**From:** Clark, Karl (K.C.) <kclark4@ford.com>  
**Sent:** viernes, 24 de mayo de 2024 06:43 a. m.  
**To:** Aguilar Ruelas, Eduardo (EAAR.) <eaguil19@ford.com>; Romero Furlong, Sandra Ale (S.) <sromerof@ford.com>;

**Cc:** Swanson, Bruce (.) <bswanso3@ford.com>; Diwakar, Sujatha (S.) <sdiwakar@ford.com>; McIntyre, Peter (P.) <pmcinty1@ford.com>; Vaddadi, Vinay (V.) <vvaddadi@ford.com>; Sangameswaran, Sangeetha (S.) <ssangame@ford.com>; Mceachern, Matthew (M.) <mmceach6@ford.com>; West, Devin (D.) <dwest90@ford.com>; Polsinelli, Antonietta (A.) <abravo1@ford.com>; Pratt, David (D.S.) <dpratt20@ford.com>; West, Devin (D.) <dwest90@ford.com>; Gill, Balwinder (B.K.) <BGILL51@ford.com>; Balzer, Stacy (S.L.) <sbalzer1@ford.com>; Dorony, Kenneth (K.R.) <kdorony@ford.com>

**Subject:** RE: 24S24 Missing Certification -- Plan and Timing

Team – Appears not all affected vehicles were eligible to receive the FSA s/w fix. If I'm not mistaken, Beth Hinman recently provided an R&R matrix to help us verify the corrective action to fix it right the 2<sup>nd</sup> time?!

Eduardo – Can we leverage the SAP tool to determine if this would have detected the error? I'm guessing SAP has not been rolled out yet for every ECU s/w release?!

**From:** Mceachern, Matthew (M.) <mmceach6@ford.com>

**Sent:** Thursday, May 23, 2024 4:31 PM

**To:** West, Devin (D.) <[dwest90@ford.com](mailto:dwest90@ford.com)>; Polsinelli, Antonietta (A.) <[abravo1@ford.com](mailto:abravo1@ford.com)>; Landt, Michael (M.R.) <[mlandt1@ford.com](mailto:mlandt1@ford.com)>; Pratt, David (D.S.) <[dpratt20@ford.com](mailto:dpratt20@ford.com)>; Clark, Karl (K.C.) <[kclark4@ford.com](mailto:kclark4@ford.com)>; Duffy, Matthew (.) <[mduffy6@ford.com](mailto:mduffy6@ford.com)>; Fuher, Michael (M.J.) <[mfuher@ford.com](mailto:mfuher@ford.com)>; Guenther, Mark (M.T.) <[mguenthe@ford.com](mailto:mguenthe@ford.com)>; Ling, Gunther (G.) <[GLING6@ford.com](mailto:GLING6@ford.com)>; Johnston, Steven (S.J.) <[sjohnst6@ford.com](mailto:sjohnst6@ford.com)>; Willard, Jeremy (J.) <[jwillar1@ford.com](mailto:jwillar1@ford.com)>; Stendardo, David (D.) <[dstendar@ford.com](mailto:dstendar@ford.com)>; Torres, Ricardo (R.) <[RTORRE87@ford.com](mailto:RTORRE87@ford.com)>; Forgacs, Daniel (J.) <[dforgacs@ford.com](mailto:dforgacs@ford.com)>

Cc: Smolarek, David (D.T.) <[DSMOLAR3@ford.com](mailto:DSMOLAR3@ford.com)>; Brophy, Adam (A.) <[ABROPHY1@ford.com](mailto:ABROPHY1@ford.com)>; Jean, Julieta (J.) <[jjean6@ford.com](mailto:jjean6@ford.com)>; Mayorga, Hector (H.) <[hmayorga@ford.com](mailto:hmayorga@ford.com)>; Zamora, Christian (C.) <[czamor11@ford.com](mailto:czamor11@ford.com)>

**Subject:** RE: 24S24 Missing Certification -- Plan and Timing

The VIN list for affected vehicles is attached as requested.

-----Original Appointment-----

**From:** West, Devin (D.) <dwest90@ford.com>

**Sent:** Thursday, May 23, 2024 11:36 AM

**To:** West, Devin (D.); Polsinelli, Antonietta (A.); Landt, Michael (M.R.); Pratt, David (D.S.); Clark, Karl (K.C.); Duffy, Matthew (.); Fuher, Michael (M.J.); Guenther, Mark (M.T.); Ling, Gunther (G.); Johnston, Steven (S.J.); Willard, Jeremy (J.); Mceachern, Matthew (M.); Stendardo, David (D.); Torres, Ricardo (R.); Forgacs, Daniel (J.)

**Cc:** Smolarek, David (D.T.); Brophy, Adam (A.); Jean, Julieta (J.); Mayorga, Hector (H.); Zamora, Christian (C.)

**Subject:** 24S24 Missing Certification -- Plan and Timing

**When:** Thursday, May 23, 2024 3:30 PM-4:00 PM (UTC-05:00) Eastern Time (US & Canada).

**Where:**

Hi Team,

Setting up a recurring meeting. At least one of the certifications for the calibrations in 24524 was missed resulting in a population of VINs not being able to receive the update. Setting up some time to review the issue and plan to resolve it as well as the potential FSA pause.

~~~~~

— Do not delete or change any of the following text. —

## Join Meeting

Meeting number (access code): 2347 292 0490 Meeting password: [REDACTED]

**Tap to join from a mobile device (attendees only)**

+1-313-248-3668,,23472920490## FordNet 248-3668 / Toll

+1-888-628-3668,,23472920490## US Toll Free Number

### Join by phone

+1-313-248-3668 FordNet 248-3668 / Toll

+1-888-628-3668 US Toll Free Number

[Global call-in numbers](#) | [Toll-free calling restrictions](#)

### Join from a video system or application

Dial [23472920490@ford.webex.com](tel:23472920490)

You can also dial 173.243.2.68 and enter your meeting number.

If you are a host, [click here](#) and login site to view host information.

**NOTICE: Protecting and Properly Using Company Assets:** *We are careful not to disclose Ford information, even accidentally. If we share non-public information outside of Ford, we follow applicable procedures and obtain proper approvals and ensure appropriate confidentiality agreements are in place. • We follow Ford's information and records retention protocols and programs. • We do not destroy information if there is a legal requirement to maintain it, such as a suspension order or other litigation hold.*

For company policies on recording: [Click Here to Download](#)

For additional help joining Webex meetings: [WebEx Help](#)

Can't join the meeting? Ford users submit a ticket: [Contact Support](#)

T32MC04