

[2019 GMC Truck Sierra 1500 \(New Model\) 4WD](#) | [\[REDACTED\]](#) | [Sierra 1500 Service Manual 13131286](#) |  
[Bulletins By Category](#) | **Technical**

**Select a Document:**

- [#20-NA-218: Possible Crank No Start or Extended Crank with DTC P12A6 - \(Feb 5, 2021\)](#)
- [#21-NA-027: Trailing Connector Loose Within Rear Bumper - \(Feb 5, 2021\)](#)
- [#19-NA-076: Blue or Black Screen and Service Rear Vision System Message on Radio Display Shifting into Reverse - \(Feb 5, 2021\)](#)
- [#20-NA-198: Trailer Running Lights Shut Off Due to Excessive Load on the Running Lamp Circuit - \(Jan 29, 2021\)](#)
- [#21-NA-018: Pop Noise Heard Coming from Rear Roof of Cab Area - \(Jan 27, 2021\)](#)
- [#19-NA-257: Pickup Box Out of Alignment - \(Dec 22, 2020\)](#)
- [#20-NA-175: Vertical Misalignment Between Cab and Pickup Box on Driver Side of Vehicle - \(Dec 22, 2020\)](#)
- [#19-NA-218: Ticking Noise from the Engine - \(Dec 16, 2020\)](#)
- [#19-NA-153: Malfunction Indicator Lamp \(MIL\) Illuminated - DTC P0741 Set - \(Dec 3, 2020\)](#)
- [#19-NA-136: Howling, Whining/Whirring, Shudder/Vibration, and/or Grinding Noise While in 4HI, 4HI Auto and/or During Parking Lot Maneuvers in Auto Mode - \(Dec 1, 2020\)](#)
- [#20-NA-078: Malfunction Indicator Lamp \(MIL\) Illuminated - DTC P0741 Set - \(Nov 23, 2020\)](#)
- [#20-NA-097: Unwanted Radio Volume Ramp Up to Max, Radio Resets, Radio Display Blank, or Non-Responsive to Touch - \(Nov 13, 2020\)](#)
- [#20-NA-196: OnStar Over the Air Update for TTY / TDD Operation and Continuous Improvement Changes - \(Oct 27, 2020\)](#)
- [#13-08-116-001F: Aftermarket ALDL or DLC Interface Devices Causing Multiple Issues - \(Oct 23, 2020\)](#)
- [#18-NA-383: Water Found in Rear Interior of Cab, Water Leak at Rear Sliding Window - \(Oct 23, 2020\)](#)
- [#20-NA-171: Radio Software Version V808 USB Update - \(Sep 25, 2020\)](#)
- [#20-NA-073: Loss of Brake Assist, Various Messages Displayed in Driver Information Center \(DIC\), Brake Pedal Travel and Apply May Feel Different, One or More of the Following DTCs May be Set: P0606 with C0021, C05D2, C0595, C2A3B, C0024, C053D, P25A2 - \(Sep 22, 2020\)](#)
- [#20-NA-194: Hard Tri-Fold Tonneau Water Leaks at the Front Corners of the Pickup Box - \(Sep 18, 2020\)](#)
- [#20-NA-157: Transport Mode On Message Displayed in Driver Information Center \(DIC\) and/or Battery Light is Flashing - \(Sep 17, 2020\)](#)
- [#20-NA-155: Service Engine Soon Message at Start Up or Shortly after Start Up - \(Sep 10, 2020\)](#)
- [#20-NA-187: Delayed and/or Harsh Engagement of Transmission Shift After Vehicle Sitting with Engine Off - \(Sep 9, 2020\)](#)
- [#20-NA-167: Malfunction Indicator Lamp \(MIL\) Illuminated - DTC P0128 Set - \(Aug 27, 2020\)](#)
- [#19-NA-255: Wax Coating on Frame Peeling, Metal Shows Corrosion/Rusting \(U.S. and Canada Only\) - \(Aug 13, 2020\)](#)
- [#20-NA-021: Intermittent Service Steering Column Lock message displayed with U0155 Set - \(Jul 29, 2020\)](#)
- [#19-NA-277: Poor Fuel Transfer and/or Rear Fuel Tank Collapsed, DTCs P2635, P2636, P2A00 and/or P026D Set - \(Jul 21, 2020\)](#)
- [#20-NA-145: Heated Seat Switch Indicators Inoperative or 110v Power Receptacle Switch Indicator Dimly Lit - \(Jul 20, 2020\)](#)
- [#20-NA-141: Tri-Fold Tonneau Paint Finish Fading or Discolored - \(Jul 8, 2020\)](#)

© 2021 General Motors. All rights reserved.

- [#19-NA-228: Malfunction Indicator Lamp \(MIL\) Illuminated, Shift to Park Message on Drivers Information Center \(DIC\), Unable to Turn Off Ignition and/or Discharged Battery - Multiple DTCs Set - \(Jun 3, 2020\)](#)
- [#16-NA-383: Information on Rough Idle, Crank No Start, Extended Crank or Misfire Due to Excessive Carbon on Top of Valves or Sticking Valves, Malfunction Indicator Light \(MIL\) Illuminated - DTC P0300, P0301, P0302, P0303, P0304, P0305, P0306, P0307, P0308 Set - \(May 8, 2020\)](#)
- [#20-NA-048: Rattle Noise from Driver or Passenger Seat Belt - \(Apr 20, 2020\)](#)
- [#20-NA-083: Low Oil or Add Oil Message Being Displayed on the Driver Information Center \(DIC\) - \(Apr 7, 2020\)](#)
- [#19-NA-035: 8L45, 8L90 Park System Does Not Engage - \(Apr 1, 2020\)](#)
- [#19-NA-121: Shake and/or Shudder During Light Throttle Acceleration Between 25 and 80 MPH \(40 and 128 KM/H\) at Steady Speed - \(Mar 30, 2020\)](#)
- [#20-NA-040: Pickup Box Power Endgate May Not Open on Initial Press, or May Not Open at All - \(Mar 18, 2020\)](#)
- [#20-NA-019: Shifter Stuck In Park - \(Mar 17, 2020\)](#)
- [#20-NA-050: Rough Shifting, Surging, Jerk/Lurch While Accelerating from a Stop Just After Shifting Out of 4LO, Service 4WD Message Displayed on the Driver Information Center \(DIC\), Malfunction Indicator LAMP \(MIL\) Illuminated - DTCs P17D4, P215B, P279A and/or P279B Set - \(Mar 3, 2020\)](#)
- [#19-NA-129: Squeak and/or Clunking Noise from Rear of Vehicle - \(Mar 2, 2020\)](#)
- [#20-NA-044: Endgate Will Not Auto Open or Auto Close After Accessory Tonneau Cover Installation, and/or Poor Fit of Tonneau Cover to Endgate - \(Feb 28, 2020\)](#)
- [#19-NA-267: Driver Information Center Welcome Logo Flickers When Entering Vehicle or Blank Heads Up Display - \(Feb 26, 2020\)](#)
- [#19-NA-212: Diagnostic Tip for Crank/No Start - \(Jan 28, 2020\)](#)
- [#18-NA-026: Transmission Fluid Leak from Transmission Oil Cooler Line Fitting Retaining Bolt - \(Jan 22, 2020\)](#)
- [#19-NA-160: Intermittent or Continuous Horn Blowing, Horn Activation Sensitive to the Touch - \(Jan 6, 2020\)](#)
- [#19 NA 279: Radio Software Version V807 Over-the Air Update \(Jan 2, 2020\)](#)
- [#18-NA-292: Malfunction Indicator Lamp \(MIL\) Illuminated with DTC P0300 - \(Dec 2, 2019\)](#)
- [#19-NA-270: Phone Ringer Volume Turned Down or Too Quiet - \(Nov 21, 2019\)](#)
- [#08-03-10-006G: Tire Slowly Goes Flat, Tire Air Loss, Low Tire Pressure Warning Light Illuminated, Aluminum Wheel Bead Seat Corrosion \(Clean and Resurface Wheel Bead Seat\) - \(Nov 12, 2019\)](#)
- [#19-NA-087: Radio Software Version V805 Over-the-Air Update - \(Oct 23, 2019\)](#)
- [#19-NA-189: Radio Displays Climate Off Message or HVAC Popup Displays Different Settings - \(Sep 17, 2019\)](#)
- [#19-NA-005: Hoot or Whistle Noise Heard at Highway Speeds - \(Sep 17, 2019\)](#)
- [#19-NA-195: Intermittent OnStar Inoperative, DTC B101D-39, Red LED and Clock Date/Time Inaccurate - \(Sep 6, 2019\)](#)
- [#19-NA-197: Air Leak/Whistle Type Noise Heard from Engine Compartment - \(Sep 3, 2019\)](#)
- [#19-NA-155: No Start Conditions Due to Dead Battery - \(Sep 3, 2019\)](#)
- [#19-NA-154: Noisy Starter Operation or a No Start Condition During Auto-Start Function - \(Sep 3, 2019\)](#)
- [#19-NA-147: Malfunction Indicator Lamp \(MIL\) Illuminated with One or More Codes set. DTC P30CE, P30CF, P30D0, P30D1 - \(Sep 3, 2019\)](#)
- [#19-NA-148: Malfunction Indicator Lamp \(MIL\) Illuminated with DTC P1467 set - \(Sep 3, 2019\)](#)

- [#19-NA-152: Static Crackling Noise Using Bluetooth Microphone - \(Aug 13, 2019\)](#)
- [#16-NA-109: Grease or Sealant Visible on Electronic Power Steering Gear - Should Not Be Interpreted as Leak - \(Aug 5, 2019\)](#)
- [#19-NA-151: Malfunction Indicator Lamp \(MIL\) Illuminated - DTCs U0101, U102, U0129, U0140 and/or U18A2 Set - \(Jul 10, 2019\)](#)
- [#19-NA-047: Radio Software Version V803 Over-the-Air Update - \(Jun 25, 2019\)](#)
- [#19-NA-135: SiriusXM Radio Stations Missing or SXM Favorites Greyed Out - \(Jun 14, 2019\)](#)
- [#19-NA-093: Engine Air Filter Life Shows 0% After Battery Disconnect - \(May 21, 2019\)](#)
- [#18-NA-314: Radio Software Version V507 Over-the-Air Update - \(Apr 15, 2019\)](#)
- [#18-NA-301: Service 4WD Lamp Message Displayed - DTC C119B 04, P0700, and/or P2534 Set - \(Apr 1, 2019\)](#)
- [#18-NA-338: Rear Infotainment Performance Issues - \(Mar 19, 2019\)](#)
- [#18-NA-368: Park Assist Message Displayed on the Drivers Information Center \(DIC\) - \(Mar 8, 2019\)](#)
- [#19-NA-029: Wi-Fi Hotspot Inoperative - \(Feb 12, 2019\)](#)
- [#16-NA-342: Rearview Mirror Displays a Blue Screen - \(Jan 31, 2019\)](#)
- [#18-NA-376: Radio Software Version V509 Over-the-Air Update - \(Jan 29, 2019\)](#)
- [#18-NA-364: Sirius XM Channel and Song Information Displays but No Audio Plays - \(Dec 4, 2018\)](#)
- [#18-NA-350: Sunroof Air Deflector Loose Spring Arm - \(Nov 19, 2018\)](#)
- [#18-NA-289: Malfunction Indicator Lamp \(MIL\) Illuminated - DTC P3498, P3499, P349A, P039B, P349C, P349D, P349E, and/or P349F Set - \(Sep 25, 2018\)](#)
- [#18-NA-284: Service Rear Vision System Message Displayed, Missing Rear View Camera Guidance Lines - \(Sep 20, 2018\)](#)
- [#18-NA-283: Wi-Fi Hotspot Displays myCadillac for SSID Name - \(Sep 18, 2018\)](#)
- [#18-NA-269: Privacy Settings, Permissions, and Terms and Conditions Accessible While Driving - \(Aug 31, 2018\)](#)
- [#18-NA-259: Passive Entry and Passive Starting Functions Are Always Inoperative on One, or Both, of the RKE Fobs, Possible Various DIC Messages - \(Aug 22, 2018\)](#)
- [#18-NA-256: Rear View Camera \(RVC\) Missing Guidance Lines and Has Distorted Image - \(Aug 20, 2018\)](#)
- [#02-08-98-002H: Hem Flange Rust Repair - \(May 15, 2018\)](#)