




Close Window

## View Field Action Details



This screen allows IVH users to view the detail information for the selected VIN on Filed Action.

### Vehicle Information



Model: TK10543-2019 SIERRA 1500 CREW CAB 4WD

Service Contract: [Yes](#)    Branded Title: No    Warranty Block: No    PDI Status: Yes  
Order Type: 70 - RETAIL - STOCK  
Field Actions: [0 Open](#)

### Field Action Details

Type	Number	Description	Release Date
Service Update Bulletins	N192210560	Engine Calibration Torque Model Not Accurate - Expires with Base Warranty	06/10/2019
Status:	Closed - Dealer Repaired		
Group:			
Sub-Group:	39802		
Expires:	10/30/2021		
Original Number:	N192210560		
Labour Ops:	9104396 N192210560 - Verified Module Programmed with Same Level Software or Calibration 9104397 N192210560 - Engine Control Module Reprogramming with SPS		

Government Agency #:

Field Action Description: Certain 2019 model year Chevrolet Silverado 1500 (New Model) and GMC Sierra 1500 (New Model) vehicles may have a condition where the vehicle does not accelerate or decelerate but maintains speed after releasing the accelerator pedal for up to approximately 65 seconds. If the customer applies the brake pedal, the vehicle will stop as designed.

Safety Risk Description:

Repair Description: Reprogram the engine control module.  
Note: Expires with Bumper to Bumper Limited Warranty/New Vehicle Limited Warranty

© 2004 General Motors. All Rights Reserved.

INFORMATION REDACTED  
PURSUANT TO THE FREEDOM OF  
INFORMATION ACT (FOIA), 5 U.S.C.  
552(B)(6)