



View Field Action Details



Field Action Details

Type	Number	Description	Release Date
Customer Satisfaction Program	N192275630	Brake Assist Feature - Frontview Camera Reprogramming and Configuration - Exp. 01/31/2022	12/11/2019
Status:	Closed - Dealer Repaired		
Group:			
Sub-Group:	1345		
Expires:	01/31/2022		
Original Number:	N192275630		
Labour Ops:	9104798 N192275630 - Verified Module Programmed with Current Level Software or Calibration 9104799 N192275630 - Frontview Camera Reprogramming with SPS		
Government Agency #:			
Field Action Description:	Certain 2019 model year Chevrolet Silverado and GMC Sierra vehicles, may have a condition in which the electronic brake control module is less likely to activate the optional integrated brake assist. Normal braking capability functions as intended.		
Safety Risk Description:			
Repair Description:	Dealers are to reprogram the front view camera by performing the SPS Programming/SPS Configuration/GDS2 Learn. Caution: To avoid module performance issues and setting DTCs, carefully read the programming instructions in SI. Programming the front view camera is a three-step process. Module programming, module configuration and module calibration are required to successfully program the front view camera. Use GDS2 to perform the calibration portion of the programming event.		