

**INITIAL ACKNOWLEDGMENT FAX SHEET OF RECEIPT OF NONCOMPLIANCE
INFORMATION REPORT SUBMITTED UNDER 49 CFR PART 573**

Assigned Recall No. 00V-375 by the
National Highway Traffic Safety Administration

NOV 15 2000

Part 573 Report Date: November 10, 2000

MANUFACTURER: General Motors Corporation (GM)

MANUFACTURER CONTACT: Mr. Frank C. Sonye, Jr.
Director, Product Investigations

FAX: (810) 947-2318

SUBJECT: 13,893 GM 1998-2001 GMC Envoys manufactured from November 1997 through May 2000; and 2000-2001 Diamond Editions manufactured from March 1999 through May 2000, fail to comply with the requirements of FMVSS No. 201, "Occupant Protection in Interior Impacts." These vehicles have a console cover/armrest cam latch that could release at less than the required load of the standard. *GM Recall No. 00100.*

This is an initial acknowledgment for this recall. A formal acknowledgment letter will be forthcoming shortly. After our review of your report and associated documents, we may have additional comments or concerns.

In accordance with Part 577, amended July 7, 1995, a draft owner notification letter must be submitted for review prior to mailing as well as an estimated owner notification schedule.

If you have any questions, please call:

Patricia Wallace, Recall Analyst on (202) 366-5232
or Jonathan White, Chief on (202) 366-5226
or by FAX (202) 366-7882
Recall Analysis Division

DEC 29 2000

Mr. Frank C. Sonye, Jr.
Director, Product Investigations
General Motors Corporation
Mail Code: 480-106-304
30500 Mound Road Mail
Warren, MI 48090-9055

NSA-11paw
00V-375

Dear Mr. Sonye:

We have reviewed General Motors Corporation's (GM) Noncompliance Information Report dated November 10, 2000, submitted in accordance with 49 CFR Part 573, "Defect and Noncompliance Reports." This recall involves 13,893 GM 1998-2001 GMC Envoy's manufactured from November 1997 through May 2000; and 2000-2001 Diamond Editions manufactured from March 1999 through May 2000, fail to comply with the requirements of FMVSS No. 201, "Occupant Protection in Interior Impacts." These vehicles have a console cover/armrest cam latch that could release at less than the required load of the standard. The assigned recall identification number for this recall is 00V-375 (GM Safety Recall No. 00100).

GM is responsible for the remedy of these vehicles from this date forward, regardless of vehicle age, mileage, or ownership.

In accordance with Part 577, amended July 7, 1995, a draft owner notification letter must be submitted for review prior to mailing as well as an estimated owner notification date.

If you have any questions, please contact Mrs. Pat Wallace at (202) 366-5232 or fax at (202) 366-7882.

Sincerely,

JS
Jonathan D. White, Chief
Recall Analysis Division
Office of Defects Investigation
Safety Assurance