



Service Parts Operations

CPB#01-118

DISTRIBUTION:

- | | |
|---|--|
| <input type="checkbox"/> DEALER-PRINCIPAL | <input type="checkbox"/> USED CAR SALES |
| <input type="checkbox"/> PARTS MANAGER | <input type="checkbox"/> BODY SHOP MANAGER |
| <input type="checkbox"/> SERVICE MANAGER | <input type="checkbox"/> BUSINESS/GENERAL |
| <input type="checkbox"/> NEW CAR SALES | <input type="checkbox"/> OTHER |

PLEASE INITIAL AND RETURN TO PARTS MANAGER FOR PERMANENT FILE

Campaign Parts Bulletin

TO: GMC DEALERS ONLY

DATE: MAY 4, 2001

FROM: J. M. STONE, RECALL CAMPAIGNS

00V-375

SUBJECT: CONSOLE/ARMREST CAM LATCH COMPLIANCE

ATTN: PARTS MANAGER

NONCOMPLIANCE CAMPAIGN BULLETIN #00100 - APRIL 30, 2001

DESCRIPTION:

- **Condition:** General Motors has decided that certain 1998-2001 GMC Envoy's and 2000-2001 GMC Jimmy Diamond Editions fail to conform to Federal/Canada Motor Vehicle Safety Standard 201, "Occupant Protection in Interior Impacts." These vehicles have a console cover/armrest cam latch that could release at less than the 10-g vertical load requirement of the standard. During a crash, the console cover could open and the cover or items stored under it could injure an occupant.
- **Correction:** Dealers are to replace the console-latch mechanism.
- Refer to the Product Campaign Bulletin for further information.

EFFECTIVE DATE:

Initial owner mailing is scheduled to begin **May 9, 2001**. No pre-shipment.

GENERAL INFORMATION:

[REDACTED]		
15070844	Panel Asm, F/Flr Cons Compl Dr Int	1

**Parts**

Service Parts Operations

Campaign Parts Bulletin

00V-375

CPB#

DISTRIBUTION:

- | | |
|---|--|
| <input type="checkbox"/> DEALER PRINCIPAL | <input type="checkbox"/> USED CAR SALES |
| <input type="checkbox"/> PARTS MANAGER | <input type="checkbox"/> BODY SHOP MANAGER |
| <input type="checkbox"/> SERVICE MANAGER | <input type="checkbox"/> BUSINESS/GENERAL |
| <input type="checkbox"/> NEW CAR SALES | <input type="checkbox"/> OTHER |
- PLEASE INITIAL AND RETURN TO PARTS MANAGER FOR PERMANENT FILE

TO: GMC DEALERS ONLY**DATE: MAY 4, 2001****FROM: J. M. STONE, MANAGER RECALL CAMPAIGNS****SUBJECT: 00100 – CONSOLE/ARMREST CAM LATCH COMPLIANCE****ATTN: PARTS MANAGER****NONCOMPLIANCE CAMPAIGN BULLETIN #00100 – APRIL 30, 2001****DESCRIPTION:**

- **Condition:** General Motors has decided that certain 1998-2001 GMC Envoy and 2000-2001 GMC Jimmy Diamond Editions fail to conform to Federal/Canada Motor Vehicle Safety Standard 201, "Occupant Protection in Interior Impacts". These vehicles have a console cover/armrest cam latch that could release at less than the 10 g vertical load requirement of the standard. During a crash, the console cover could open and the cover or items stored under it could injure an occupant.
- **Correction:** Dealers are to replace the console latch mechanism.
- Refer to the Product Campaign Bulletin for further information.

EFFECTIVE DATE:

- Initial owner mailing is scheduled to begin May 9, 2001. No preshipment.

GENERAL INFORMATION:

PART NUMBER	DESCRIPTION	QUANTITY/VEHICLE
15070844	Panel Asm, F/Flr Cnsl Compt Dr Int	1

**GM SERVICE OPERATIONS
DCS732
URGENT - DISTRIBUTE IMMEDIATELY**

DATE: April 30, 2001

SUBJECT: 00100 - CONSOLE/ARMREST CAM LATCH COMPLIANCE

MODELS: 1998-2001 GMC ENVOY
2000-2001 GMC JIMMY DIAMOND EDITION

TO: ALL GMC DEALERS

ATTN: SERVICE MANAGER, PARTS MANAGER, AND WARRANTY ADMINISTRATOR

00V-375

CONDITION

General Motors has decided that certain 1998-2001 GMC Envoys and 2000-2001 GMC Jimmy Diamond Editions fail to conform to Federal/Canada Motor Vehicle Safety Standard 201, "Occupant Protection in Interior Impacts". These vehicles have a console cover/armrest cam latch that could release at less than the 10 g vertical load requirement of the standard. During a crash, the console cover could open and the cover or items stored under it could injure an occupant.

CORRECTION

Dealers are to replace the console latch mechanism.

VEHICLES INVOLVED

Involved are certain 1998-2001 GMC Envoys and 2000-2001 GMC Jimmy Diamond Edition vehicles built within these VIN breakpoints:

YEAR	DIV.	MODEL	PLANT	FROM	THROUGH
1998	GMC	Envoy	Moraine	W2950001	W2955851
1999	GMC	Envoy	Moraine	X2950001	X2955126
2000	GMC	Envoy	Moraine	Y2100003	Y2402333
2001	GMC	Envoy	Moraine	12100018	12100022
2000	GMC	Jimmy Diamond Ed.	Moraine	Y2108085	Y2388366
2001	GMC	Jimmy Diamond Ed.	Moraine	12100017	12100140

IMPORTANT: Dealers should confirm vehicle through GMVIS (GM Vehicle Inquiry System) or GM Access Screen (Canada only) or DCS Screen 445 (IPC only) before beginning campaign repairs. [Not all vehicles within the above breakpoints may be involved.]