

**INITIAL ACKNOWLEDGMENT FAX SHEET OF RECEIPT OF DEFECT
INFORMATION REPORT SUBMITTED UNDER 49 CFR PART 573**

Assigned Recall No. **01V-295** by the
National Highway Traffic Safety Administration

OCT - 1 2001

Part 573 Report Date: **September 18, 2001**

MANUFACTURER: **Mitsubishi Motor Manufacturing of America, Inc.**

MANUFACTURER CONTACT: **Mr. Jerome Berwanger, Vice President
Quality Control Department**

FAX: **(309) 888-7202**

SUBJECT: 25,891 Mitsubishi MY 2000 Galant and Eclipse passenger vehicles built with V6 engines with Federal emissions and manufactured from January 30 through July 5, 2000. (These vehicles were sold in the US, Puerto Rico, and Guam.) The power steering oil feed tube can come in contact with an exhaust manifold mounted heat shield causing a hole to be worn through the power steering pipe allowing oil leakage.

This is an acknowledgment for this recall. A formal acknowledgment letter will be written if we have additional comments or concerns.

As stated in your report, Mitsubishi Motor Sales of America and Mitsubishi Caribbean will be conducting the owner notification and remedy for this campaign. Mitsubishi America's recall number will be 01V-295.001 and Mitsubishi Caribbean's recall number will be 01V-295.002.

If you have any questions, please call:

Patricia Wallace, Recall Analyst on (202) 366-5232
or Jonathan White, Chief on (202) 366-5226
or by FAX (202) 366-7882
Defects and Recall Information Analysis Division

cc: **Kent Reeves, Manager, Product Engineering and Technical Compliance
- (714) 892-4131
Rafael Arzuaga, Senior Manager, Service Dept. - (787) 251-8700**