

From: Patricia Wallace
To: "rbabcock@hstcl.com".gwhub.hubsmtg
Date: 2/5/03 2:37PM
Subject: Recall 03V-030/049 (expansion of 01V-388)

ACKNOWLEDGMENT FAX SHEET OF RECEIPT OF DEFECT INFORMATION REPORT SUBMITTED UNDER 49 CFR PART 573

Assigned Recall No. 03V-030 by the
National Highway Traffic Safety Administration

Part 573 Report Date: December 20, 2002

Date Approved & E-mailed: February 5, 2003

MANUFACTURER: Hyundai America Technical Center, Inc.

MANUFACTURER CONTACT: Robert Babcock, Manager, Corporate Affairs

FAX: (734) 747-8899

SUBJECT: 25,643 Hyundai 2001-2002 Santa Fe vehicles equipped with 2.7 liter V-6 engines and manufactured from March 31, 2000 through August 14, 2001. Improperly manufactured Crankshaft Position Sensors (CPS) were installed. The CPS cases were improperly manufactured and did not meet dimensional specifications. Internal gaps within the cases allowed epoxy to contact the printed circuit board, which resulted in cracking of the printed circuit board capacitor. A damaged CPS capacitor could result in engine stalling. (This is an expansion of a previous recall, 01V-388).

This is an acknowledgment for this recall. A formal acknowledgment letter will ONLY be written if we have additional comments or concerns.

Per our phone conversation of January 24, 2003, the owner notification letter meets the requirements of Part 577 after making the suggested changes.

As stated in Part 573.6, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter in which notification to purchasers occurs. As stated in your report, owner notification is expected to begin during February 2003. Therefore, the first quarterly report will be due by April 30, 2003.

If you have any questions, please call:

Patricia Wallace, Recall Analyst on (202) 366-5232
or George Person, Chief on (202) 366-6210
or by FAX (202) 366-7882
or e-mail at pwallace@nhtsa.dot.gov
Recall Management Division