

March 10, 2003

**TO: ALL HYUNDAI DEALER PRINCIPALS:
ALL HYUNDAI SERVICE MANAGERS:
ALL HYUNDAI PARTS MANAGERS:**

**REFERENCE: Campaign 049, Santa Fe V6 Crankshaft Position (CKP) Sensor
Inspection/Replacement - Expanded Vehicle Production Range**

Hyundai Motor America, in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act, has expanded the population of vehicles involved in Campaign 049. 2001 Santa Fe V6 vehicles manufactured beginning March 31, 2001 through August 14, 2001 are now included in the campaign. Consumers with vehicles manufactured from March 31, 2000 through February 28, 2001 were previously notified by mail in March 2002. Customers with vehicles manufactured from March 1, 2001 through August 14, 2001 are now also being asked by mail to take their vehicles to their servicing Hyundai dealer to have the campaign completed

Enclosed with the Service Manager's letter are materials developed for your use: (5) copies of the Technical Service Bulletin containing instructions on performing the repair and submitting the campaign claim, a copy of the Customer Notification Letter, and a VIN listing of your retail customers affected by this campaign.

Customer notification letters for vehicles manufactured from March 1, 2001 through August 14, 2001 will be sent on March 10, 2003.

Hyundai appreciates your cooperation in properly completing this campaign. Questions may be directed to your District Parts and Service Manager.

Sincerely,

Chuck Halper
Vice President of Service

Enclosures: