



ADMINISTRATIVE MESSAGE

Message Author: Marianne MacDonald
Template Type: Standard
Author's Division/Department: VS9M
Status: Forwarded
Message Date: 03/08/2004
Message Number: VSU20040026-01

Message Criteria/Information

Dealer Recipient Criteria:	Chevy Oldsmobile Pontiac
Exclude SAC(s):	
Originating Dept:	SPO - recalls, Joan Stone
Subject:	GMP04-014A - 03043A Turn Signals/Hazard Warning Flashers Inoperative
Actionable Item:	Information Only
Actionable Item Details:	
Contact Person: (for Wholesale)	Name: Joan M. Stone Phone: 810-806-4422 Email: Joan.M.Stone/US/GM/GMC @ GM Fax:
Contact Person: (for Wholesale)	Name: Phone: Email: Fax:
Contact Person: (for Dealership)	Name: Joan M. Stone Phone: 810-806-4422 Email: Joan.M.Stone/US/GM/GMC @ GM Fax:
Contact Person: (for Dealership)	Name: Phone: Email: Fax:
Functional Role(s): (Recommended Distribution):	Parts Manager, Service Manager

Message Categorization Information

Message Type:	GM Parts Bulletin & Information
Revision Reference:	

Message Retention

Release Date:	03/08/2004
Archive Date:	03/17/2004

Dealer Salutation: TO ALL CHEVROLET, OLDSMOBILE AND PONTIAC DEALERS

Product Safety Recall #03043A Dated: March 2004

NOTE: THIS BULLETIN IS BEING REVISED TO INCLUDE 2000 AND 2001 MODEL YEAR PONTIAC GRAND AM VEHICLES. DISCARD ALL COPIES OF BULLETIN 03043, ISSUED FEBRUARY 2004.

- General Motors has decided that a defect, which relates to motor vehicle safety, exists in certain 2000 and 2001 model year Chevrolet Malibu, Oldsmobile Alero and Pontiac Grand AM vehicles. Some of these vehicles have a condition in which solder joints in the hazard warning flasher switch may crack. If cracking occurs, it may cause the audible flasher indicator, visual flasher indicator in the instrument cluster, turn signals, and the hazard warning flashers to work intermittently or not at all. If the turn signals or hazard warning flashers are not working, others may react more slowly to a turning or stopped vehicle and a crash could occur.

- Dealers are to replace the hazard warning flasher switch.
- Refer to the Product Safety Recall Bulletin #03043A for further information.

EFFECTIVE DATE:

Pontiac owner mailing is scheduled to begin **MARCH 15, 2004**.

GENERAL INFORMATION:

Part Number	Description	Quantity/Vehicle
22594148	Switch, Hazard Wrng (w/flasher) (Malibu)	1
22642608	Switch, Hazard Wrng (w/flasher) (Alero)	1
22842605	Switch, Hazard Wrng (w/flasher) (2000 Grand Am)	1
22624799	Switch, Hazard Wrng (w/flasher) (2001 Grand Am)	1

Important: An initial supply of Hazard Warning Switches (22642605 and 22624799) for the Grand Am vehicles required to complete this program will be pre-shipped to involved dealers of record. This pre-shipment will take place the week of March 1, 2004, and equates to approximately 20% of each dealer's involved vehicles. Pre-shipped parts will be charged to dealer's open parts account.

VSSM Library Fields

Do Not Send Message to VSSM Library

Does This Document Require Action from a Field Rep? Information

Intended Audience(s): Area Parts Manager, Field Zone Manager, Region-NC, Region-NE, Region-SC, Region-SE, Region-W, Regional Field Operations Manager, Regional Parts Manager

Involved Brand(s): Chevrolet-Malibu, Oldsmobile-Alero

Document Type(s): Parts

Expiration Date: 04/15/2004

Topic: GM Parts - Product Safety Recall #03043A/Turn Signals/Hazard Warning Flashers Inoperative GMP04-014A