



Customer Services Head Office: 26 DeBasta Street, Winnipeg, Manitoba, Canada R2J 4G5, Phone: 204-982-5400, Fax: 204-224-0248

January 28, 2004

Kenneth Weinstein
Associate Administrator for Enforcement
National Highway Traffic Safety Administration
400 Seventh Street, S.W.
Washington, DC
20590

Dear Mr. Weinstein:

An issue relating to motor vehicle safety has been discovered in certain D60HF models of New Flyer buses sold within the 1996-2003 model year. Please find, enclosed, the 573 report attached as required in 49CFR Part 573. This 573 report relates to ODI Resume PE-04-003 opened on January 8, 2004. New Flyer and ArvinMeritor continue to work diligently to resolve the issue of centre axle lockup.

The attached 573 submission has already been faxed to the Office of Defects Investigation Division and forwarded to the Defects and Recall Information Analysis Division.

Sincerely,

Scott Halbesma
Safety and Compliance Manager
New Flyer

Enc.

RECEIVED
NHTS-215
2004 FEB -2 A 9 26
OFFICE OF
DEFECTS INVESTIGATION

Safety Defect and Noncompliance Report Guide for Vehicles
PART 573 Defect and Noncompliance Report¹

On January 26, 2004, New Flyer [MFR] decided that a defect which relates to motor vehicle safety exists in the motor vehicles listed below, and is furnishing notification to the National Highway Traffic Safety Administration in accordance with 49 CFR Part 573 Defect and Noncompliance Reports.

Date this report was prepared: January 28, 2004

Furnish the manufacturer's identification code for this recall (if applicable): Recall Number to be assigned by NHTSA

1. Identify the full corporate name of the fabricating manufacturer of the vehicle being recalled. If the recalled vehicle is imported, provide the name and mailing address of the designated agent as prescribed by 49 U.S.C. §30164.

New Flyer Industries Limited, 711 Kernaghan Avenue, Winnipeg, Manitoba, Canada, R2C 3T4

Identify the corporate official, by name and title, whom the agency should contact with respect to this recall.

Scott Halbesma, Safety and Compliance Manager, Fax No.: 204.224.0248, Ph: 204.934.4882

Name and Title of Person who prepared this report.

Same as above

Signed: , 28-JAN-04

¹Each manufacturer must furnish a report, to the Associate Administrator for Safety Assurance, for each defect or noncompliance condition which relates to motor vehicle safety.

This guide was developed from 49 CFR Part 573, "Defect and Noncompliance Reports" and also outlines information currently requested. Any questions, please consult the complete Part 573 or contact Mr. Jon White at (202) 366-5227 or by FAX at (202) 366-7882.

I. Identify the Vehicle Models Involved in the Recall

2. Identify the Vehicles Involved in the Recall, for each make and model or applicable vehicle line (provide illustrations or photographs as necessary to describe the vehicle), provide:

New Flyer and ArvinMeritor are diligently analyzing the defect. Based on this analysis, a more detailed list of affected vehicles will be immediately submitted. Model Year 1996-2003 New Flyer Articulated 60' high floor buses appear to be affected.

II. Identify the Recall Population

3. Furnish the total number of vehicles recalled potentially containing the defect or noncompliance.

Model	Year	Number of Vehicles Potentially Involved
<u>D60HF</u>	<u>1996-2003</u>	<u>1081</u>

Total Number Potentially Affected by the Recall: 1081

4. Furnish the approximate percentage of the total number of vehicles estimated to actually contain the defect or noncompliance: TBD

Identify and describe how the recall population was determined--in particular how the recalled models were selected and the basis for the beginning and final dates of manufacture of the recalled vehicles:

TBD

III. Describe the Defect or Noncompliance

5. Describe the defect or noncompliance. The description should address the nature and physical location of the defect or noncompliance. Illustrations should be provided as appropriate.

When the vehicle is parked for an extended period of time, such as overnight, the center axle wheel end brakes have a potential to not release. This 'stiction' has the possibility to lock a center axle wheel end while attempting to drive-away from a parked position.

Describe the cause(s) of the defect or noncompliance condition.

If the vehicle is parked for an extended period of time, the brake linings have a potential to adhere to the brake drums.

Describe the consequence(s) of the defect or noncompliance condition.

While driving away from a parked position, driver can lose control of the vehicle if condition is not detected.

Identify any warning which can (a) precede or (b) occur.

Rear (drive) axle can push the locked center axle into a 'jack-knife' situation. Driver may also perceive vehicle as having derated power while trying to pull away.

If the defect or noncompliance is in a component or assembly purchased from a supplier, identify the supplier by corporate name and address.

ArvinMeritor, 2135 W. Maple Road, Troy, MI 48064

Identify the name and title of the chief executive officer or knowledgeable representative of the supplier:

Niran Audimoolan, Project Manager Product Safety and Compliance

IV. Provide the Chronology in Determining the Defect/Noncompliance

If the recall is for a defect, complete item 6, otherwise item 7.

6. With respect to a defect, furnish a chronological summary (including dates) of all the principle events that were the basis for the determination of the defect. The summary should include, but not be limited to, the number of reports, accidents, injuries, fatalities, and warranty claims.

Customer reported multiple incidents of center axle lock-up to New Flyer. Three of the incidents have involved a crash resulting in property damage.

7. With respect to a noncompliance, identify and provide the test results or other data (in chronological order and including dates) on which the noncompliance was determined.

V. Identify the Remedy

8. Furnish a description of the manufacturer's remedy for the defect or noncompliance. Clearly describe the differences between the recall condition and the remedy.

Still being determined

Clearly describe the distinguishing characteristics of the remedy component/assembly versus the recalled component/assembly.

TBD

Identify and describe how and when the recall condition was corrected in production. If the production remedy was identical to the recall remedy in the field, so state. If the product was discontinued, so state.

TBD

VI. Identify the Recall Schedule

Furnish a schedule or agenda (with specific dates) for notification to other manufacturers, dealers/retailers, and purchasers. Please, identify any foreseeable problems with implementing the recall.

TBD

VII. Furnish Recall Communications

9. Furnish a final copy of all notices, bulletins, and other communications that relate directly to the defect or noncompliance and which are sent to more than one manufacturer, distributor, or purchaser. This includes all communications (including both original and follow-up) concerning this recall from the time your company determines the defect or noncompliance condition on, not just the initial notification. *A DRAFT copy of the notification documents should be submitted to this office by Fax (202-366-7882) for review prior to mailing.*

Note that these documents are to be submitted separately from those provided in accordance with Part 573.8 requirements.