

Safety Defect and Noncompliance Report Guide for Vehicles
PART 573 Defect and Noncompliance Responsibility and Reports¹

On 2-09, 2004, LANDOLL CORP. ~~(NHTSA)~~ decided that ~~(a defect which relates to motor vehicle safety) (a noncompliance with Federal Motor Vehicle Safety Standard~~ ~~No. _____)~~ exists in the motor vehicles listed below, and is furnishing notification to the National Highway Traffic Safety Administration in accordance with 49 CFR Part 573 Defect and Noncompliance Responsibility and Reports. *THAT THE COMPLAINT IDENTIFIED IN THE NEWS WIRE RECALL APPLIES TO FIVE (5) TRUCKS MANUFACTURED BY LANDOLL CORPORATION.*
 Date this report was prepared: 2-10-04

Furnish the manufacturer's identification code for this recall (if applicable): 04E-062

1. Identify the full corporate name of the fabricating manufacturer of the vehicle being recalled. If the recalled vehicle is imported, provide the name and mailing address of the designated agent as prescribed by 49 U.S.C. §30164.

LANDOLL CORPORATION

Identify the corporate official, by name and title, whom the agency should contact with respect to this recall.


HANK BRUCKER CUSTOMER SERVICE MGR

Telephone Number: 785-562-4721 Fax No.: 785-562-4997

Name and Title of Person who prepared this report.

HANK BRUCKER
CUSTOMER SERVICE MGR

Signed:



¹ Each manufacturer must furnish a report, to the Associate Administrator for Safety Assurance, for each defect or noncompliance condition which relates to motor vehicle safety.

This guide was developed from 49 CFR Part 573, "Defect and Noncompliance Responsibility and Reports" and also outlines information currently requested. Any questions, please consult the complete Part 573 or contact Mr. George Person at (202) 366-5210 or by FAX at (202) 366-7882.

I. Identify the Vehicle Models Involved in the Recall

2. Identify the Vehicles Involved in the Recall, for each make and model or applicable vehicle line (provide illustrations or photographs as necessary to describe the vehicle), provide:

Make(s): LANDOLL Model Years Involved: 2001 Model(s): 305

Production Dates: Beginning: 7-16-01 Ending: 8-21-01

VIN Range: Beginning: 1LH05DR5121A11821 Ending: 1LH05DR5121A11825

Vehicle Type: TRAILER Bodystyle: BOTTOM DUMP

Descriptive information which characterizes/distinguishes the recalled vehicles from those model vehicles not included in the recall:

THESE FIVE (5) TRAILERS ONLY USED 30 HUB AND DRUM ASSEMBLIES SPECIFICALLY ORDERED FOR USE ON THESE FIVE (5) TRAILERS.

Make(s): — Model Years Involved: — Model(s): —

Production Dates: Beginning: — Ending: —

VIN Range: Beginning: — Ending: —

Vehicle Type: — Bodystyle: —

Descriptive information which characterizes/distinguishes the recalled vehicles from those model vehicles not included in the recall:

Make(s): — Model Years Involved: — Model(s): —

Production Dates: Beginning: — Ending: —

VIN Range: Beginning: — Ending: —

Vehicle Type: — Bodystyle: —

Descriptive information which characterizes/distinguishes the recalled vehicles from those model vehicles not included in the recall:

Identify the approximate percentage of the production of all the recalled models manufactured by your company between the inclusive dates of manufacture provided above, that the recalled model population represents. For example, if the recall involved Widgets equipped with certain items of equipment from January 1, 1996 through April 1, 1997, then what was the percentage of the recalled Widgets of all Widgets manufactured during that time period.

RECALL APPLIES ONLY TO THE FIVE (5) TRAILERS IDENTIFIED ABOVE.

II. Identify the Recall Population

3. Furnish the total number of vehicles recalled potentially containing the defect or noncompliance.

Vehicles Model	Year	Number of Potentially Involved
305	2001	5

Total Number Potentially Affected by the Recall: 5

4. Furnish the approximate percentage of the total number of vehicles estimated to actually contain the defect or noncompliance:

Identify and describe how the recall population was determined--in particular how the recalled models were selected and the basis for the beginning and final dates of manufacture of the recalled vehicles:

HAUB AND DRUM ASSEMBLIES ORDERED FROM WERB WHEEL
CONTAINING THE COMPONENT BEING RECALLED WERE TRACED
BY LANDOLL CORPORATION MATERIAL USAGE HISTORY DATA TO
THE TRAILERS IDENTIFIED ABOVE.

III. Describe the Defect or Noncompliance

5. Describe the defect or noncompliance. The description should address the nature and physical location of the defect or noncompliance. Illustrations should be provided as appropriate.

SEE WOOD WHEEL REPORT

Describe the cause(s) of the defect or noncompliance condition.

SEE WOOD WHEEL REPORT

Describe the consequence(s) of the defect or noncompliance condition.

SEE WOOD WHEEL REPORT

Identify any warning which can (a) precede or (b) occur.

SEE WOOD WHEEL REPORT

If the defect or noncompliance is in a component or assembly purchased from a supplier, identify the supplier by corporate name and address.

WOOD WHEEL PRODUCTS, INC

2310 INDUSTRIAL DRIVE SW

CULLMAN, AL 35055

Identify the name and title of the chief executive officer or knowledgeable representative of the supplier:

JOHN C. HALL VP ENGINEERING

IV. Provide the Chronology in Determining the Defect/Noncompliance

If the recall is for a defect, complete item 6, otherwise item 7.

6. With respect to a defect, furnish a chronological summary (including dates) of all the principle events that were the basis for the determination of the defect. The summary should include, but not be limited to, the number of reports, accidents, injuries, fatalities, and warranty claims.

SEE WEBB WHEEL REPORT

7. With respect to a noncompliance, identify and provide the test results or other data (in chronological order and including dates) on which the noncompliance was determined.

SEE WEBB WHEEL REPORT

V. Identify the Remedy

8. A description of the manufacturer's program for remedying the defect or noncompliance. This program shall include a plan for reimbursing an owner or purchaser who incurred costs to obtain a remedy for the problem addressed by the recall within a reasonable time in advance of the manufacturer's notification of owners, purchasers and dealers, in accordance with §573.13 of this part. A manufacturer's plan may incorporate by reference a general reimbursement plan it previously submitted to NHTSA, together with information specific to the individual recall. Information required by §573.13 that is not in a general reimbursement plan shall be submitted in the manufacturer's report to NHTSA under this section. If a manufacturer submits one or more general reimbursement plans, the manufacturer shall update each plan every two years, in accordance with §573.13. The manufacturer's remedy program and reimbursement plans will be available for inspection by the public at NHTSA headquarters.

SEE WEBB WHEEL REPORT

9. Furnish a description of the manufacturer's remedy for the defect or noncompliance. Clearly describe the differences between the recall condition and the remedy.

SEE WEAR WHEEL REPORT

Clearly describe the distinguishing characteristics of the remedy component/assembly versus the recalled component/assembly.

SEE WEAR WHEEL REPORT

Identify and describe how and when the recall condition was corrected in production. If the production remedy was identical to the recall remedy in the field, so state. If the product was discontinued, so state.

SEE WEAR WHEEL REPORT

VI. Identify the Recall Schedule

10. Furnish a schedule or agenda (with specific dates) for notification to other manufacturers, dealers/retailers, and purchasers. Please, identify any foreseeable problems with implementing the recall.

LANDOLL CORPORATION ACCEPTS THE WEAR WHEEL OFFER, AND AUTHORIZES WEAR WHEEL, TO DIRECTLY CONTACT OUR CUSTOMERS TO COMPLETE ALL ACTIVITIES REQUIRED TO RESOLVE THE RECALL SITUATION.

Hank Brucker

From: "Hank Brucker" <hank_brucker@landoll.com>
To: <crusk@webbwheel.com>
Cc: "Betts Lammerding" <b_lammerding@landoll.com>
Sent: Tuesday, February 10, 2004 11:14 AM
Subject: Webb Wheel Recall Number 04E-002

Christy,

Landoll Corporation purchased 30 Hub and Drum Assemblies, on Landoll PO 96566-00, containing the brake drum component being recalled by Webb Wheel. Refer to Webb Wheel Sales Order number 205261 dated 06-29-2001. These assemblies were used to manufacture five Model 305 trailers, each a triple axle, all owned by one customer. The current owner is Farmers Supply Co., 110 South 3rd St., Cheyenne, OK 73628. The contact is Dwane Roak. The phone number is 580-497-2283. The VIN numbers are:

1LH05DRJ121A11821

1LH05DRJ121A11822

1LH05DRJ121A11823

1LH05DRJ121A11824

1LH05DRJ121A11825

Landoll Corporation requests that Webb Wheel contact our customer directly to complete the recall process.

Landoll Corporation has no other inventory affected by this recall.

Hank Brucker
Landoll Corporation
Customer Service Manager
Phone 785-562-4721
Fax 785-562-4997