

**INITIAL ACKNOWLEDGMENT FAX SHEET OF RECEIPT OF DEFECT INFORMATION REPORT
SUBMITTED UNDER 49 CFR PART 573**

Assigned Recall No. 04V-006 by the
National Highway Traffic Safety Administration

Part 573 Report Date: **December 22, 2003**

Date Faxed: **January 5, 2004**

Manufacturer: **Land Rover North America, Inc.**

Manufacturer Contact: **Mr. Dennis T. Johnston, Manager, Product Compliance**

FAX: **201-818-8234**

SUBJECT: 8,117 Land Rover 2000-2003 Discovery II sport utility vehicles manufactured from June 18, 2000 through June 17, 2003. The Active Cornering Enhancement (ACE) pump banjo bolt loses torque and allows fluid to leak past the joint. Land Rover Recall No. B149.

This is an initial acknowledgment for this recall. A formal acknowledgment letter will be forthcoming shortly. After our review of your report and associated documents, we may have additional comments or concerns.

Please provide us with a draft owner notification letter for our review before mailing to consumers as well as an estimated owner notification schedule.

If you have any questions, please call:



Patricia Wallace, Safety Defects Analyst on (202) 366-5232 or
George Person, Chief on (202) 366-5210
or Fax at (202) 366-7882
or e-mail at PatriciaWallace@nhtsa.dot.gov
Recall Management Division