



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

400 Seventh Street, SW
Washington, DC 20590

**ACKNOWLEDGMENT FAX SHEET OF RECEIPT OF DEFECT INFORMATION
REPORT SUBMITTED UNDER 49 CFR PART 573**

Assigned Recall No. **04V-262** by the
National Highway Traffic Safety Administration

Part 573 Report Date: **May 05, 2004**

Date Faxed: **June 03, 2004**

MANUFACTURER: **Triumph Motorcycles (America) Ltd**

MANUFACTURER CONTACT: **Dan Harmon, National Operations Manager**

FAX: **678-854-2025**

SUBJECT: **2,792 Triumph 2002-2003 Bonneville America And 2003-2004
Speedmaster motorcycles. Under certain assembly conditions, the electrical power
supply cable to the starter motor may come into direct contact with the oil cooler return
pipe. This could cause the insulation on the starter cable to degrade.**

This is an acknowledgment for this recall. A formal acknowledgment letter will be written
only if we have additional comments or concerns.

Please provide us with a draft owner notification letter for our review before mailing to
consumers

If you have any questions, please call:

Patricia Wallace, Safety Defects Analyst on (202) 366-5232 or
George Person, Chief on (202) 366-5210
or Fax at (202) 366-7882
or e-mail at Patricia.Wallace@nhtsa.dot.gov
Recall Management Division