



U.S. Department  
of Transportation

400 Seventh Street, SW  
Washington, DC 20590

**National Highway  
Traffic Safety  
Administration**

**ACKNOWLEDGMENT FAX SHEET OF RECEIPT OF DEFECT INFORMATION  
REPORT SUBMITTED UNDER 49 CFR PART 573**

Assigned Recall No. **04V-536** by the  
National Highway Traffic Safety Administration

Part 573 Report Date: **November 11, 2004**

Date Faxed/Emailed: **November 18, 2004**

MANUFACTURER: **American Honda Motor Co.**

MANUFACTURER CONTACT: **Mr. William R. Willen, Managing Counsel  
Product Regulatory Office**

FAX: **310-783-2999**

**SUBJECT: 2,247 Honda 2005 Odyssey minivans manufactured from July 28, 2004 through October 16, 2004. The anti-lock brake system (ABS) uses a sensor on each wheel to detect wheel speed. Some sensors on the rear wheels were installed incorrectly, which means the sensor may report the wrong wheel speed to the ABS control unit. *Honda Recall No. P52.***

This is an acknowledgment for this recall. A formal acknowledgment letter will be written only if we have additional comments or concerns.

As stated in Part 573.6, submission of the first of six consecutive quarterly status reports is required within one month after the close of the calendar quarter **in which notification to purchasers occurs**. As stated in your report, the recall is expected to November 2004. Therefore, the first quarterly report will be due by January 30, 2005.

If you have any questions, please call:

Patricia Wallace, Safety Defects Analyst on (202) 366-5232 or  
George Person, Chief on (202) 366-5210  
or Fax at (202) 366-7882  
or e-mail at [Patricia.Wallace@nhtsa.dot.gov](mailto:Patricia.Wallace@nhtsa.dot.gov)  
Recall Management Division