



U.S. Department
of Transportation

**National Highway
Traffic Safety
Administration**

400 Seventh Street, SW
Washington, DC 20590

**ACKNOWLEDGMENT FAX SHEET OF RECEIPT OF DEFECT
INFORMATION REPORT SUBMITTED UNDER 49 CFR PART 573**

Assigned Recall No. **04V-554** by the
National Highway Traffic Safety Administration

Part 573 Report Date: **November 8, 2004**

Date E-Mailed: **November 19, 2004**

Manufacturer: **Land Rover North America, Inc.**

Manufacturer Contact: **Mr. Dennis Johnston, Manager, Product Compliance**
Mr. Gabriel D. Kim, Coordinator, Product Compliance

SUBJECT: 17 Land Rover 2004 Range Rover sport utility vehicles equipped with dynamic stability control may have been fitted with a yaw rate sensor that has internally delaminated, which could actuate the system incorrectly. *Land Rover Recall No. B178.*

This is an acknowledgment for this recall. A formal acknowledgment letter will be written only if we have additional comments or concerns.

Please provide us with a draft owner notification letter for our review before mailing to consumers as well as an estimated owner notification date.

If you have any questions, please call:

Patricia Wallace, Safety Defects Analyst on (202) 366-5232 or
George Person, Chief on (202) 366-5210
or Fax at (202) 366-7882
or e-mail at PatriciaWallace@nhtsa.dot.gov
Recall Management Division