



04V-052

DEALER COMMUNICATIONS

Harley-Davidson Motor Company

Dealer Department Routing

☒ Dealer Principal	☐ General Merchandise	☒ Service
☒ General Manager	☐ Buell	☒ Parts
☐ Office Manager	☐ F&I Manager	
☒ Vehicle Sales Manager	☐ HOG Director	

January 23, 2004

ML - 389

Subject: Safety Recall Campaign 0112

Dear Harley-Davidson Dealer:

Harley-Davidson Motor Company, Inc. has learned that a condition affecting safety exists on certain 2004 Model Year Dyna Glide EFI Fuel Injected Motorcycles produced between September 2, 2003 and November 19, 2003. This condition involves the rubber fuel hose. The rubber hose has the potential to separate from the inner liner causing a fuel leak which could result in a fire.

We have voluntarily declared this a defect related to motor vehicle safety (Campaign 0112) to allow us to formally recall all affected motorcycles. The remedy of this issue is to replace the fuel line assembly on the above noted vehicles.

In the interest of the safety of our mutual customers and as required by law, you may sell but NOT DELIVER any affected motorcycles to your customers. A service bulletin outlining the repair and credit procedure, along with the list of affected VIN's will follow within two weeks. This bulletin will also contain the credit procedures required to handle fuel line assembly replacement.

In accordance with Federal regulations administrated by NHTSA, Harley-Davidson Motor Company, Inc. will provide notice to all owners of record of affected products with direction to bring the vehicle in for the recall service.

Sincerely,

Harley-Davidson Motor Company, Inc.