

TO: All Hyundai Dealership Service and Parts Managers
FROM: Service
SUBJECT: Recall Campaign 065 - 2003 and 2004 Santa Fe 3.5L ABS ECU
Reprogramming - TSB Precaution Update

The following precautions are re-emphasized to avoid accidental damage to the HECU (Hydraulic Electronic Control Unit) described in Recall Campaign 065, TSB# 04-01-002.

Ensure that the Santa Fe 3.5L vehicle being reprogrammed is affected by Campaign 065. Check the Vehicle Warranty Information screen for an open Campaign 065 before starting repairs.

* Note: DO NOT reprogram a 3.5L 2WD Santa Fe with ABS following the campaign procedure 065. Reprogramming of a 3.5L 2WD with ABS will result in DAMAGE to the HECU.

* DO NOT interrupt the reprogramming at any time during the reprogramming as it will result in DAMAGE to the HECU.

* DO NOT shut the power OFF at any time during the reprogramming.

* Follow all instructions in Recall Campaign 065 TSB # 04-01-002, as described.

If you have any questions, please contact your District Parts and Service Manager.

//END