

May 19, 2004
Campaign 04V-199
Bulletin SB04-02-S003

**TROOPER ACCELERATOR CABLE
SAFETY CAMPAIGN
04V-199**

To: Dealership Executive Management

Affected Vehicles:

Isuzu Trooper produced from November 11, 1991 -- January 27, 1995 equipped with 6VD1 engine. VIN Range N7900012 to S7906162.

Condition:

On some vehicles, the accelerator cable dust cover may deteriorate causing the cable dust cover to adhere to the inner throttle cable. This can cause the accelerator throttle cable to delay RPM and vehicle speed reduction for several seconds after the accelerator pedal is released, which in turn, can lead to a crash without warning.

Dealer Action:

Isuzu dealers will replace the accelerator cable dust cover as outlined in Campaign Service Bulletin SB04-02-S003. This repair will be done at no cost to the consumer.

<u>Campaign Timetable</u>	<u>DATE</u>
Dealer Notification	05/18/04
Begin Shipment of Parts to Dealerships	05/18/04
Campaign Bulletin and Campaign Reports to be Mailed to Dealers	05/20/04
Owner Notification Begins	05/24/04

Please ensure that all appropriate personnel within your dealership are aware of this campaign and that the necessary repairs are performed on all affected vehicles either in your inventory or brought into your dealership for repair.

To confirm that a vehicle has an applicable campaign you can validate the VIN through ICS on the VIN inquiry screen.

We apologize for any inconvenience this may cause.

Sincerely,
ISUZU MOTORS AMERICA, INC.