



# SERVICE ALERT

April 13, 2005

SA04RE-05

NAS:

US Only:

Cda Only:

**ATTENTION:** Centre Manager, Service Manager, Service Advisor, Technician, Warranty Admin

## Bulletin Labor Time Error for RECALL B156

Land Rover has discovered an editorial error in the published documents Service Bulletin SRE05-03 and Technical Bulletin RB156 relating to the gas tank replacement time allowance.

Retailers who claim the **B156** code with Options **B** or **C** will be paid 1.5 hours, plus drive-in drive-out if Option C is selected. **The 1.5 hour time is CORRECT according to the most recent documentation from Land Rover UK.** Also the SRO number has been adjusted in association with the time change to 19.55.01.

Land Rover regrets the error in the US and Canadian documentation. See below for the correct labor information table. This information is reflected in revised documents posted to InfoTrail (Service Bulletins) and GTR (Technical Information Bulletins).

Program Code	Option	Job Description	SRO	Time (Hours)	Part Number	Part Description	QTY	Misc Expense
B156	B	Replace fuel tank	19.55.01	1.5	WFE 500740K NTC 5859	Fuel Tank Grommet	1	
B156	C	Replace fuel tank Drive in/drive out	19.55.01 02.02.02	1.5 0.2	WFE 500740K NTC 5859	Fuel Tank Grommet	1	