



ADMINISTRATIVE MESSAGE

Message Author: Theresa Toccaceli/US/GM/GMC
Template Type: Standard
Author's VSSM
Division/Department:
Status: Forwarded
Message Date: 08/19/2004
Message Number: VSU20040253

Message Criteria/Information

Dealer Recipient Criteria:	GMC Dealers Oldsmobile
Exclude BAC(s):	
Originating Dept:	SPO - Recalls, Joan Stone
Subject:	GMP04-133 - 04048 - Electronically Controlled Air Suspension/Powertrain Control Module
Actionable Item:	Action Required
Actionable Item Details:	
Contact Person: (for Wholesale)	Name: Joan Stone Phone: 810-606-4422 Email: Joan M. Stone/US/GM/GMC @ GM Fax:
Contact Person: (for Wholesale)	Name: Phone: Email: Fax:
Contact Person: (for Dealership)	Name: Joan Stone Phone: 810-606-4422 Email: Joan M. Stone/US/GM/GMC @ GM Fax:
Contact Person: (for Dealership)	Name: Phone: Email: Fax:
Functional Role(s): (Recommended Distribution):	Parts Manager

Message Categorization Information

Message Type:	GM Parts Bulletins & Information
Revision Reference:	

Message Retention

Release Date:	08/20/2004
Archive Date:	09/03/2004

Dealer Salutation: TO ALL GMC AND OLDSMOBILE DEALERS

DESCRIPTION:

- General Motors has decided that a defect, which relates to motor vehicle safety, exists in **certain** 2002 model year GMC Envoy and Oldsmobile Bravada vehicles equipped with an electronically controlled air suspension (ECAS) (RPO G67). Some of these vehicles have a condition in which the ECAS may produce a brief electrical spike while the vehicle is operating. This electrical spike can disrupt the powertrain control module (PCM) causing the vehicle to stall. If the spike damages the PCM, the vehicle may not restart. If this happens while the vehicle is moving, a crash could occur without prior warning.
- Dealers are to install a wiring harness.
- Refer to Customer Satisfaction Program # 04048 for further information.

EFFECTIVE DATE:

Initial owner mailing will begin **AUGUST 27, 2004**.

GENERAL INFORMATION:

Parts Pre-Ship Information

Important: An initial supply of wiring harnesses required to complete this recall will be pre-shipped to involved Dealers of record. This pre-shipment is scheduled to begin the week of August 9, 2004 and will be approximately 15% of each Dealer's involved vehicles. Pre-shipped parts will be charged to Dealer's open parts account.

Additional parts, if required, are to be obtained from General Motors Service & Parts Operations (GMSPO). Please refer to your "involved vehicles listing" before ordering parts. Normal orders should be placed on a DRO = Daily Replenishment Order. In an emergency situation, parts should be ordered on a CSO = Customer Special Order.

Part Number	Description	Quantity/Vehicle
15166099	Harness, Chas RR Wrg	1
12337820	Strap, Adj Tie	1

VSSM Library Fields

Do Not Send Message to VSSM Library

Does This Document Require Action from a Field Rep? Information

Intended Audience(s): Area Parts Manager, Area Sales Manager, Field Zone Manager, Local Advt & Mktg Manager, Region-NC, Region-NE, Region-SC, Region-SE, Region-W, Regional Field Operations Manager, Regional Parts Manager

Involved Brand(s): GMC--Envoy, Oldsmobile--Bravada

Document Type(s): Parts

Expiration Date: 09/15/2004

Topic: GM Parts -- O, P-G 2002 Envoy, Bravada Electronically Controlled Air Suspension/Powertrain Control Module GMP04-133/Customer Satisfaction Recall #04048