

**VAN HOOL SERVICE BULLETIN #1126 - OWNER'S NOTIFICATION LETTER UPDATE**  
**IMPORTANT MESSAGE PLEASE READ IMMEDIATELY**

...  
(Name + address coach owner)

USA

CERTIFIED MAIL  
RETURN RECEIPT REQUESTED

..., 2005

**IMPORTANT:** This update supplements the information provided in Van Hool Service Bulletin N°. 1126 and its original accompanying Owner's Notification Letter.



Re.: NHTSA Safety Recall Program-Campaign number 04V - 422  
Van Hool Service Bulletin N°. 1126 "Main junction box – top cover", section Parts and products

Dear Coach Owner,


Left-hand junction box top cover N°. VH 10906063, which has been supplied to you as a repair part to use for the above-mentioned campaign has been determined unsuitable for this application.

Please find enclosed a replacement top cover, which has been tailored to your coach's junction box. The new part is 4 inches longer than the old part (see Figure 1) and can be attached to the junction box center section using adhesive, and to the junction box side wall with two sheet metal screws (see Figure 2).

**IMPORTANT:** Please do not use the shorter version of Van Hool cover VH 10906063. Scrap it instead.



**Figure 1:**  
VH 10906063 old  
and new – do not  
use the shorter  
version



**Figure 2: VH 10906063 – new part installation**

For additional information please contact ABC Companies our designated agent in the United States, address:

ABC Companies  
17469 West Colonial Drive  
Winter Garden, FL 34787  
toll free # : (800) 222-2871  
tel # : (407) 656 7977  
fax # : (407) 905 7020

Van Hool NV and ABC Companies apologize for any inconvenience this may cause, however this action is taken in the interest of your safety and continued satisfaction with our vehicles.

Yours sincerely,

VAN HOOL N.V.