



## ADMINISTRATIVE MESSAGE

Message Author: FCN Team/US/GM/GMC  
 Template Type: Standard  
 Author's: VSSM  
 Division/Department:  
 Status: Forwarded  
 Message Date: 01/10/2005  
 Message Number: VSU20050467

RECEIVED  
 2005 JAN 14 A 9:21  
 01/10/2005 09:21 AM

### Message Criteria/Information

Dealer Recipient Criteria:	Chevy Pontiac
Exclude BAC(s):	
Originating Dept:	SPO - Recalls, Joan Stone
Subject:	GMP05-006 - 04083 - Rear Stop/Turn Signal Lamps Inoperative on 2003 Chevrolet Cavalier and 2003 Pontiac Sunfire Vehicles
Actionable Item:	_Information Only
Actionable Item Details:	
Contact Person: (for Wholesale)	Name: Joan Stone      Phone: 810-606-4422 Email:                      Fax:
Contact Person: (for Wholesale)	Name:                      Phone: Email:                      Fax:
Contact Person: (for Dealership)	Name: Joan Stone      Phone: 810-606-4422 Email: joan.m.stone@gm.com      Fax:
Contact Person: (for Dealership)	Name:                      Phone: Email:                      Fax:
Functional Role(s): (Recommended Distribution):	Parts Manager

### Message Categorization Information

Message Type:	GM Parts Bulletins & Information
Revision Reference:	

### Message Retention

Release Date:	01/10/2005
Archive Date:	01/25/2005

Dealer Salutation: TO ALL CHEVROLET AND PONTIAC DEALERS

### DESCRIPTION:

**SAFETY PRODUCT RECALL #04083**  
**DATED: JANUARY 10, 2005**

### CONDITION

General Motors has decided that a defect, which relates to motor vehicle safety, exists in **certain** 2003 model year Chevrolet Cavalier and Pontiac Sunfire vehicles. Some of these vehicles have a condition where the rear lamps that provide stop and turn signals and tail lamp functions stop working because of inadequate contact between the bulb and socket. If the turn signal is inoperative, the driver should notice a higher rate of turn signal indicator flashes and rapid clicking of the turn signal flasher. In addition, if one bulb were to become inoperative while the vehicle was operating in cruise control, the cruise control would disengage when the remaining bulb was activated. If both lamps were to become inoperative, the cruise control would not engage. If these rear lamps are inoperative, a following

driver may take longer to react to the motion of the vehicle and a crash could occur.

Dealers are to inspect the rear lamp sockets and apply grease or replace them if necessary.

Refer to the Product Safety Recall Bulletin #04083 for further information.

**EFFECTIVE DATE:**

Owner mailing is scheduled to begin January 17, 2005

**GENERAL INFORMATION:**

The Parts list follows:

Part Number	Description	Quantity/Vehicle
89025035	Socket, Tail & RR Si Mkr Lp (All Cavaliers and Pontiac 4-Dr)	1-2 If Req'd
89025036	Socket, T/Lp (Pontiac 2-Dr)	1-2 If Req'd
09441839	Bulb, T/Lp	1-2 If Req'd
12377900*	Lubricant, Dielectric	1 If Req'd

\*One unit of Lubricant will service 100 vehicles.

**VSSM Library Fields**

Do Not Send Message to VSSM Library

Does This Document Require Action from a Field Rep? Information

**Intended Audience(s):** Area Parts Manager, Field Zone Manager, Region-NC, Region-NE, Region-SC, Region-SE, Region-W, Regional Field Operations Manager, Regional Parts Manager

**Involved Brand(s):** Chevrolet--Cavalier, Pontiac--Sunfire

**Document Type(s):** Service

**Expiration Date:** 02/15/2005

**Topic:** 04083 -- C, P-G 2003 Cavalier, Sunfire Rear Stop/Turn Signal Lamps Inoperative GMP05-006