

Next Unread Message

View Message

Sent On Expires On
 From
 Subject

DATE: November 18, 2004
TO: All Honda Sales, Service & Parts Managers
FROM: American Honda Service Division
RE: Campaign Announcement and Stop Sale Order

Honda Motor Co., Ltd., has announced to NHTSA (National Highway Traffic Safety Administration) its intention to recall selected 2005 Civic Si model vehicles manufactured in England in order to verify proper operation of the outboard front seat belt anchors.

Basic Problem: Some front seat belt anchors may have been installed with an incorrect washer that could restrict anchor movement. As a result, the seat belt may be improperly positioned on certain occupants. An improperly positioned belt could increase the risk of injury in a crash.

Stop-Sale Order: Only applies to the 145 Civic Si vehicles listed at the end of this message. Those 145 units are within a very large range of VINs that will be listed on the service bulletin.

NOTE 1: Vehicles listed below CANNOT be sold or leased with a known defect.

NOTE 2: It is illegal to sell or lease a vehicle with a known defect. If any affected vehicle with a known defect is sold/leased to a retail customer, the dealership will be entirely responsible for all legal consequences should an injury occur as a result of a failure of the defective part.

Support Materials: The recall repair service bulletin will be on ISIS on Friday morning (11/19/04).

Campaign Parts: AH Parts Division will FedEx every Honda Dealership a quantity of repair kits equal to 100% of their new car unsold vehicle inventory and vehicles sold to customers. Additional repair kits to fix customer vehicles will be available via the Controlled Parts System.

Repair Strategy: Check the movement of both front seat belt lower anchors. If the anchors move smoothly, the vehicle can be sold. If the anchors bind, or stick, the wave washer inside the anchor must be replaced.

Customer Notification: Approximately 416 vehicles are affected by this Recall Campaign. Notifications will be mailed to all known owners (on or about December 6, 2004). You will be notified of the exact customer mailing date by iN Message.

DEALER	VIN	DEALER	VIN
206534	SHHEP33585U500201	207486	SHHEP33594U505843
206545	SHHEP33545U500194	207499	SHHEP33575U500125
206546	SHHEP33555U500110	207502	SHHEP33564U505749
206549	SHHEP33585U500151	207508	SHHEP33515U500220
206549	SHHEP33585U500179	207519	SHHEP33564U505847
206572	SHHEP33525U500114	207525	SHHEP33595U500367
206583	SHHEP335X5U500149	207549	SHHEP33555U500348
206591	SHHEP33585U500182	207561	SHHEP33585U500361

INTERACTIVE NETWORK

206592	SHHEP33565U500360	207575	SHHEP33535U500123
206602	SHHEP33554U505841	207577	SHHEP33594U505860
206604	SHHEP33555U500141	207626	SHHEP33594U505793
206620	SHHEP33565U500150	207629	SHHEP33535U500168
206624	SHHEP33515U500167	207629	SHHEP33544U505734
206637	SHHEP33685U500336	207671	SHHEP33635U500325
206653	SHHEP33595U500143	207676	SHHEP33525U500128
206666	SHHEP33575U500190	207676	SHHEP335X5U500345
206681	SHHEP33674U505512	207683	SHHEP33525U500131
206687	SHHEP33535U500364	207788	SHHEP33505U500225
206689	SHHEP33575U500352	207805	SHHEP33505U500113
206707	SHHEP33554U505774	207806	SHHEP33575U500139
206717	SHHEP336X5U500337	207814	SHHEP33555U500365
206735	SHHEP33505U500371	207814	SHHEP33565U500178
206746	SHHEP33605U500329	207814	SHHEP335X5U500233
206747	SHHEP33625U500333	207825	SHHEP33514U505741
206760	SHHEP33625U500283	207834	SHHEP33535U500106
206772	SHHEP33585U500358	207834	SHHEP33575U500156
206795	SHHEP33525U500243	207846	SHHEP33515U500105
206795	SHHEP33575U500108	207855	SHHEP33535U500137
206805	SHHEP335X4U505799	207858	SHHEP33685U500319
206811	SHHEP33575U500187	207889	SHHEP33575U500111
206822	SHHEP33615U500310	207895	SHHEP33545U500101
206857	SHHEP33534U505885	207896	SHHEP33625U500316
206860	SHHEP33574U505873	207915	SHHEP33594U505874
206862	SHHEP33514U505853	207923	SHHEP33575U500268
206862	SHHEP33565U500228	207929	SHHEP33574U505792
206878	SHHEP33535U500154	207939	SHHEP33525U500355
206881	SHHEP33594U505664	207962	SHHEP33545U500227
206883	SHHEP33505U500161	207963	SHHEP335X5U500118
206888	SHHEP33595U500112	207983	SHHEP33545U500177
206890	SHHEP33595U500157	207994	SHHEP33574U505727
206894	SHHEP33595U500160	207996	SHHEP33525U500369
206898	SHHEP33514U505674	208011	SHHEP33595U500109
206902	SHHEP335X5U500121	208015	SHHEP33574U505856
206907	SHHEP33524U505764	208027	SHHEP33555U500205
206939	SHHEP33615U500324	208037	SHHEP33675U500327
206956	SHHEP33505U500192	208045	SHHEP33525U500209
207013	SHHEP33585U500134	208045	SHHEP33575U500173
207034	SHHEP33585U500277	208052	SHHEP33505U500368
207059	SHHEP33575U500240	208061	SHHEP33515U500122
207080	SHHEP33545U500115	208088	SHHEP33655U500312
207103	SHHEP335X5U500152	208091	SHHEP335X4U505754
207105	SHHEP33524U505733	208103	SHHEP33585U500120
207108	SHHEP33515U500119	208132	SHHEP33525U500162
207126	SHHEP33545U500180	208149	SHHEP33505U500130
207255	SHHEP33544U505717	208170	SHHEP33655U500326
207260	SHHEP33565U500262	208206	SHHEP335X5U500264
207262	SHHEP33615U500341	208210	SHHEP33545U500132
207270	SHHEP33524U505800	208215	SHHEP33505U500239
207277	SHHEP33525U500193	208216	SHHEP33625U500302
207282	SHHEP33585U500117	208269	SHHEP335X5U500216
207287	SHHEP33585U500246	208293	SHHEP33595U500174
207325	SHHEP33545U500129	208294	SHHEP33535U500199
207333	SHHEP33594U505731	208297	SHHEP33535U500350

INTERACTIVE NETWORK

207337	SHHEP335X5U500359	208316	SHHEP33524U505795
207357	SHHEP33505U500189	208317	SHHEP33595U500370
207392	SHHEP33515U500153	208329	SHHEP33555U500169
207392	SHHEP33685U500305	208329	SHHEP33575U500271
207397	SHHEP33594U505714	208332	SHHEP33534U505739
207415	SHHEP33555U500155	208332	SHHEP33554U505712
207440	SHHEP33524U505697	208336	SHHEP33564U505699
207445	SHHEP335X5U500362	208358	SHHEP33504U505861
		208358	SHHEP33584U505784
		208368	SHHEP33565U500231

End of message.

© 2000–2004, American Honda Motor Co., Inc. All Rights Reserved.