



October 15, 2004

CSAR 1053

Name
Address
Address

Dear:

This notice is sent to you in accordance with the requirements of the National Traffic and Vehicle Safety Act.

Western Recreational Vehicles has decided that a defect, which relates to motor vehicle safety, exists in certain 2005 ALPINE COACH LIMITEDS equipped with VANSKO VMM 2820 Modules. The module may experience an incorrect fault on its bi-directional outputs numbers 19 and 20. During this fault condition, the cruise control may not engage, and the alternator may not charge the house batteries. There may also be loss of operation of the ABS warning light. The driver may not be aware that the ABS is no longer working, which could result in a crash.

To eliminate the possibility of these conditions the VANSKO VMM 2820 Modules will be replaced with revised modules. This service action will be accomplished without cost to you. Please contact your dealer or Western RV Customer Service, toll-free, at (866) 567-4133 to arrange a service date and to assure that the necessary parts for this repair may be ordered. The labor time needed to perform this service action is approximately one (1) hour.

Federal regulations require that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten (10) days.

If after contacting your dealer or the Western RV Customer Service Department you are unable to have this safety defect remedied without charge and within a reasonable time, you may wish to call (888) DASH-2-DOT ((888) 327-4236) or write,

Safety Administrator
National Highway Traffic Safety Administration
400 Seventh Street SW
Washington, DC 20590

Sincerely,
WESTERN RECREATIONAL VEHICLES, INC.

Phil Mattoon
Customer Service Manager
PRM/tms

Western Recreational Vehicles, Inc.

3401 W. Washington Avenue • P.O. Box 9547 • Yakima, WA 98909
509.457.4133 • 509.457.8184 fax • www.wrv.com

Manufacturer of Alpine Coach, Peak Chassis and Alpenlite Recreational Vehicles • Member RVIA