

October 2004

2004 Mazda3 Crash Zone Sensor Recall 2304J

Dear Mazda Owner:

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act.

Mazda Motor Corporation has decided that a defect, which relates to motor vehicle safety, exists in certain 2004 Mazda3 vehicles produced from June 24, 2003 through March 22, 2004. If you are a recipient of this notice, your vehicle is included in this campaign.

What is the problem?

On certain 2004 Mazda3 vehicles, a crack in the airbag crash zone sensor housing can allow water to enter the sensor, causing a short circuit and illuminating the airbag warning light. If this problem exists, the airbag will not deploy as designed in certain types of frontal crashes, increasing the risk of death or serious injury to the driver and front seat passenger.

What will Mazda do?

Your Mazda dealer will inspect the crash zone sensor and replace it, if necessary, with a modified one **free of charge**. The repair should take approximately one hour to complete. However, it may take longer depending on the service workload at your Mazda dealership.

As a reminder, the Mazda Driver's Assurance Plan may provide alternate transportation when your vehicle is at an authorized Mazda dealership for a warranty repair. To be eligible for alternate transportation, your vehicle must be within the mileage and time limitations under the Mazda New Vehicle Limited Warranty and adhere to the Rental Car Reimbursement policy. Ask your dealer for details about the Mazda Rental Car Reimbursement Program.

What should you do?

Mazda is concerned about your safety, and we encourage you to make an appointment with any authorized Mazda dealer to have the crash zone sensor inspected and replaced, if necessary, as soon as possible. You do not need to bring this notice to the dealer, but it may assist in the check-in process.

What If you have already paid for a repair of the crash zone sensor?

If you have already paid for the Inspection/repair or replacement of the crash zone sensor due to a defect in the sensor, you may be eligible for reimbursement of reasonable repair expenses based on Mazda's repair standards. Please complete the enclosed "Reimbursement Application Form," including the necessary documentation, and mail it to us in the pre-eddressed envelope provided, allowing 6-8 weeks for processing.

Where is the closest Mazda dealer?

To locate your nearest Mazda dealer, visit our web site and try our "Locate a Dealer" feature at www.MazdaUSA.com or consult your local yellow pages.

Moved or no longer own this vehicle?

If you have moved or no longer own your Mazda3, please complete the enclosed prepaid Information Change Card as soon as possible. This enables us to update our records and notify the current owner.

Federal law requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

Still have questions?

If you have any questions regarding this campaign, please contact our Customer Assistance Center at (800) 222-5500, option #4.

If Mazda or its dealers do not repair the defect free of charge and within a reasonable amount of time, you may notify the Administrator of the National Highway Traffic Safety Administration, 400 Seventh Avenue, SW, Washington, D.C. 20590. You may also call their toll-free Auto Safety Hotline at (888) 327-4236.

Your safety is a priority for Mazda. We actively work to improve our products and search for solutions to improve your ownership experience. Please accept our apologies for any inconvenience this program may have caused you.

Sincerely,

Mazde North American Operations

REIMBURSEMENT PLAN

Requirements for Reimburgement

if you meet all of the following requirements, you are eligible to receive reimbursement under this plan:

- An authorized Mazda dealer has inspected your vehicle and completed the 2004 Mazda3 Crash Zone Sensor Recall 2304J.
- You own or have owned a subject 2004 Mazde3 within the VIN range:

JM1BK**** 41 100088 -169916

Note: The asterisk "" can be any number or letter.

- You have paid for the inspection/repair or replacement of the crash zone sensor due to a defect in the sensor.
- 4. You have an original or legible copy of the paid repair order or invoice receipt showing:
 - Description of the concern reported
 - Inspection/Repair or replacement of the crash zone sensor due to a defect in the sensor.
 - Itemized part(s) and labor charges
 - Vehicle model and year, and vehicle identification number
 - Repair date
 - Repair mileage
 - Name, address, and telephone number of the authorized Mazda Dealer or a licensed repair shop where such
 repairs were performed
 - Your name and address at the time of repair
- 5. Mall this reimburgement application form in the enclosed envelope to:

Mazda North American Operations PO Box 5049 Lake Forest, CA 92609-8549

Procedure for Reimbursement Request

Once your vehicle has been inspected, repaired or the crash zone sensor replaced by an authorized Mazda dealer due to a defect in the crash zone sensor, you may apply for reimbursement by doing the following:

- Complete the Reimburgement Application Form found on the reverse side of this page.
- Mail the Reimbursement Application Form with a <u>legible</u> copy of the paid repair order and/or invoice using the enclosed envelope.
- Retain copies of the paid repair order or invoice and this application form for your records.

If you wish to correspond with Mazda regarding this reimbursement plan, please write to the above address and refer to your vehicle Identification number (VIN).

Any reimbursement application form that is incomplete, illegible, or sent without the legible copy of the paid repair order or invoice will be returned for completion. If Mazda has any questions concerning your application for reimbursement, you may be contacted. Please allow 6-8 weeks for processing.

(SEE REVERSE SIDE FOR APPLICATION FORM)

REMBURSEMENT APPLICATION FORM

2004 Mazda3 Crash Zone Sensor Recall 2304.J

(Please type or print)	-		· -	
Name:	First	Middle	Lest	_
	7081			•
Address:				_
	Sirent Ad	drees		
	Capy	Sinin	Zip Code	
	Home:			
Phone Number:				_
	Work:		 	-
Vehicle Identification	on Number (VIN):			
	, , , , , , , , , , , , , , , , , , ,	(17 digita in k	mglh)	— <u> </u>
T-1-1 \$-1-100 ad (1)				ì
Total Amount of Ru	simbursement Requested	: Dat	iere Carrie	- (
<u> </u>				
INST	RUCTIONS FOR GEN	IERAL RELEASE	DESCRIBED BELOW:	
i		ad thoroughly		
		icie identification n General Release (b		
<u> </u>	Ger	neral Release	·	
am submitting to Mazda Moto eplacement performed to date VIN) is:				
VIN:				_
n exchange for Mazda's pay ill claims for such inspection forth American Operations, heir respective directors, of slease shall bind my heire, o	n/repair costs. This <i>t</i> e its regiona/distribute ficars, agents, emplo	elesse shall benef rs (foreign and do yeas, divisions, so	it Mazda and its authorized mestic), its authorized de	d agent Mazda alerships, and al
Dated:		Signed:		