



605 West Crystal Lake Rd
Forest City, Iowa 50436
PH: 641/585-3535 FAX: 641/585-6966

OCTOBER 1, 2004

RECALL 91

RE: BODY SERIAL
CHASSIS SERIAL

Dear Owner:

This notice is being sent to you in accordance with the requirements of the National Traffic and Motor Vehicle Safety Act. Our records indicate that you have purchased a vehicle with the serial number which appears above. If you have paid to have this defect corrected, you may be eligible for reimbursement. To be eligible, you must meet the requirements described in the enclosed Reimbursement Plan Notice.

REASON FOR THIS RECALL

The motor vehicles potentially containing the defect are on certain 2004 through 2005 model year Winnebago Vectra®/Itasca Horizon® (S36GD, S36RD, S40AD, and S40KD) motor homes built on a Freightliner® chassis with a 400-hp Cummins® engine. These motor homes were manufactured January 6, 2004 through July 30, 2004. It has been determined that a condition exists where a sheet metal "tab" on a wire cover behind the accelerator pedal has the potential to catch on the accelerator pedal. If the accelerator pedal would hang up on the tab of the wire cover, a hazardous situation could result in the pedal not going back to idle position. Personal injury and/or vehicle damage may result.

WHAT WE WILL DO

Winnebago Industries, Inc. has provided instructions for you to inspect and, if necessary have the wire cover repaired. If you do not feel comfortable performing this inspection, you have the option to have a dealer inspect and repair, if necessary at no charge to you.

WHAT YOU SHOULD DO

Please follow the inspection instructions and mail the enclosed owner reply card back. If you do not feel comfortable doing the inspection, please contact your Winnebago Industries, Inc. dealer immediately to arrange for and appointment. The labor time necessary to perform this correction will be approximately one-half hour. Please allow time for the dealer to process your vehicle.

Winnebago Industries, Inc. dealers are best equipped to obtain parts and provide service to ensure your vehicle is corrected as promptly as possible. HOWEVER, if you take your vehicle to the dealer on the agreed date and he does not service this condition on that date or within five days, we recommend you contact Winnebago Industries, Inc., Attention: Owner Relations Representative (641-585-6939). If you are still unable to obtain such installation without charge to you and within a reasonable time, you may contact the Administrator, N.H.T.S.A., Washington, DC 20590, or call toll free, Auto Safety Hot Line, 888-327-4236.

Page two

Presentation of this letter to the service center will assist in making the necessary correction to your vehicle in the shortest possible time. If you have sold or traded your vehicle, please let us know by completing the postage-paid owner reply card and returning it to us.

We are sorry to cause you this inconvenience; however, we have taken this action in the interest of your safety and continued satisfaction with our products. This letter does not constitute an acknowledgment of legal liability.

Winnebago Industries, Inc.
Forest City, Iowa 50436





Enclosure

INSTRUCTIONS TO PERFORM CAMPAIGN #91
Inspection of Driver Side Dash Wiring Shield
on Winnebago Vectra and Itasca Horizon motor homes
built on Freightliner chassis with Cummins 400 diesel engine

PROCEDURE

The basic procedure involves inspecting the dash wiring shield beneath the driver side of the dash. See the following photos which show improper and proper orientation of the access flap on the wiring shield. Please inspect the wire cover, then depending on condition, contact your dealer or complete the Owner Reply Card and send to Winnebago Industries as described in the photos below.

Wiring shield beneath driver side of dash on Winnebago Vectra or Itasca Horizon)



REIMBURSEMENT PLAN NOTICE

Dear Owner:

If you have already paid to have this defect or noncompliance corrected (Winnebago Recall No. 91), you may be eligible for reimbursement under this plan.

TO BE ELIGIBLE, YOU MUST MEET ALL OF THE FOLLOWING REQUIREMENTS:

1. You own, or have owned, a Winnebago Vectra[®], or Itasca Horizon[®] built on a Freightliner chassis with a 400-hp Cummins engine from January 6, 2004 through July 20, 2004.
2. You have paid for a wire cover adjustment
3. The repair was performed on or prior to September 20, 2004.
4. You have the original repair order or invoice showing:
 - ◆ Vehicle model and year or VIN.
 - ◆ Repair date.
 - ◆ Itemized labor charges including description of the adjustment to the wire cover.
 - ◆ Your name and address at the time of repair.
 - ◆ Name and address of repair shop.

TO REQUEST REIMBURSEMENT:

1. Complete the reimbursement application. (See reverse side for form.)
2. Mail this application along with the original copy of the repair order or invoice to:

Attention: Owner Relations
Winnebago Industries, Inc.
605 West Crystal Lake Road
P.O. Box 152
Forest City, IA 50436

3. Retain copies of repair order or invoice for your records.

SEE REVERSE SIDE FOR REIMBURSEMENT APPLICATION

**REIMBURSEMENT APPLICATION
WINNEBAGO INDUSTRIES, INC.**

RECALL CAMPAIGN NO. 91

Please Print All Information:

First Name: _____

Last Name: _____

Mailing Address: _____

Telephone Number: _____

(If we need additional information)