

# Technical Info

# EvoBus

TI No.: 47.10W007 c.c.: W Issued: 2004-07-27

Issued by: PQF-PR

Your contact for queries and information is your national Setra Service representative

TYPE: S 417 USA Model: 629 534  
 ASSY.: System:  
 TITLE: TC400 USA – Fuel tank replacement

**ISSUE:**

Under some conditions cracks and fissures can form on the lower sections of the tanks' side walls, leading to fuel leakage.

**REMEDIAL ACTION:**

Install new fuel tank with baffle plates.

**NOTICE:**

No return shipping: defective components are to be scrapped on location following release approval from ASK

**INFORMATION:**

This operation is to be carried out on affected vehicles as part of a recall campaign.

**REQUIRED COMPONENTS:**

Qty.	Description	Part Number	Remarks
1	Fuel tank	A6294702602	right
1	Fuel tank	A6294702201	left

**CONTACT PERSON / ORDERING ADDRESS:**

Your national EvoBus/Setra spare parts depot

**JOB TEXT AND PROVISIONAL FLAT RATES:**

Job No.	Job text	Flat rate
02-4846	Fuel tank replacement	

*The flat rates apply to operations based on hourly labor*

**DAMAGE CODE:**

47900 70	
----------	--

**CODE WORD:****EvoBus**

This information may be confidential. Access is to be strictly limited to the persons and internal parties indicated in the official factory distribution list; all other use and distribution is prohibited.

Page 1 of 2

intended exclusively as general information. We reserve the right to introduce technical modifications at any time. This document will not be subject to subsequent editorial revision.

## TANKAUSBAU

### Expense assignment:

100% of the associated costs will be assumed – prescribed Service procedure

### AFFECTED VEHICLES:

WKKA34AD843000038; WKKA34AD843000037; WKKA34ADX43000038;  
WKKA34AD143000039; WKKA34AD843000040; WKKA34ADX43000041;  
WKKA34AD143000042; WKKA34AD343000043; WKKA34AD543000044;  
WKKA34AD743000045; WKKA34AD943000046; WKKA34AD043000047;  
WKKA34AD243000048; WKKA34AD443000049; WKKA34AD043000050;  
WKKA34AD243000051; WKKA34AD443000052; WKKA34AD643000053;  
WKKA34AD843000054; WKKA34ADX43000055; WKKA34AD343000107;  
WKKA34AD543000108; WKKA34AD743000112; WKKA34AD943000113;  
WKKA34AD043000114; WKKA34AD243000115; WKKA34CD843000116;  
WKKA34AD843000117; WKKA34AD843000118; WKKA34ADX43000119;  
WKKA34AD843000120; WKKA34AD843000121; WKKA34ADX43000122;  
WKKA34AD143000123; WKKA34AD343000124; WKKA34AD543000125;  
WKKA34AD743000126; WKKA34AD943000127; WKKA34AD043000128;  
WKKA34AD243000129; WKKA34AD943000130; WKKA34AD043000131;  
WKKA34AD243000132; WKKA34AD443000133; WKKA34AD643000134;  
WKKA34AD443000083; WKKA34AD643000084; WKKA34AD843000085;  
WKKA34AD843000135; WKKA34ADX43000136; WKKA34AD143000137;  
WKKA34AD343000138; WKKA34AD543000139; WKKA34AD143000140;  
WKKA34AD343000141; WKKA34AD543000142; WKKA34AD743000143;  
WKKA34AD943000144; WKKA34AD043000145; WKKA34AD243000146;  
WKKA34AD443000147; WKKA34AD643000148; WKKA34AD843000149;  
WKKA34AD443000150; WKKA34AD643000151; WKKA34AD843000152;  
WKKA34ADX43000153; WKKA34AD143000154; WKKA34AD343000155;  
WKKA34AD543000156; WKKA34AD743000167;

PQF

ASK

Signed  
Duppui

Signed  
Lentz